



TOYOTA



report date: 2024-03-29

General information

Make	TOYOTA
Model	VERSO VALVEMATIC TR
Colour	Grey
Year of manufacture	2009
Top speed	115 mph
0 - 60 mph	11.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	132 BHP
Max. torque	160 Nm at 4.400 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.8 mpg
Consumption extra urban	50.4 mpg
Consumption combined	42.2 mpg
CO2 emission	158 g/km
CO2 label	G





Internet history

Entry 1	
Date	2021-06-18
Pictures	20
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2024-08-25
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	43
Total items failed	5

## MOT #16 2023-08-25 16:05

MOT test number 784830432814

Result ✓ Passed

Next expiry date 2024-08-25

- Advice** Rear Direction indicator slightly discoloured Both (4.4.3 (a))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Parking brake lever defective but can be satisfactorily operated (1.1.6 (d))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Minor** Horn control insecure (7.7 (b))

## MOT #15 2022-08-24 08:04

MOT test number 417822934196

Result ✓ Passed

- Advice** Rear Brake pipe corroded, covered in grease or other material Both sides. (1.1.11 (c))
- Minor** Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
- Advice** General surface corrosion under vehicle.
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Minor** Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**MOT #14**

2021-08-26 09:36

**MOT test number**

951641752936

**Result**

✓ Passed

**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Minor** Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #13**

2021-08-24 09:50

**MOT test number**

386911561860

**Result**

✗ Failed

**Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #12**

2021-04-01 17:11

**MOT test number**

903725544027

**Result**

✓ Passed

**MOT #11**

2021-04-01 15:39

**MOT test number**

470016007203

**Result**

✗ Failed

**Fail** Front Headlamp light source and lamp not compatible (4.1.4 (c))



<b>MOT #10</b>	2020-03-31 08:44
<b>MOT test number</b>	565685380105
<b>Result</b>	✓ Passed
<b>MOT #9</b>	2019-03-30 09:22
<b>MOT test number</b>	342180131214
<b>Result</b>	✓ Passed
<b>MOT #8</b>	2018-04-05 07:53
<b>MOT test number</b>	871466392790
<b>Result</b>	✓ Passed
<b>MOT #7</b>	2017-03-29 16:58
<b>MOT test number</b>	686300633344
<b>Result</b>	✓ Passed
<b>MOT #6</b>	2016-03-30 10:46
<b>MOT test number</b>	424355404063
<b>Result</b>	✓ Passed



MOT #5

2015-04-10 18:13

MOT test number

388990205125

Result

✓ Passed

- Notice

Child seat fitted not allowing full inspection of adult belt
- Advice

Brake pad(s) wearing thin (3.5.1g)
- Notice

Engine covers fitted obscuring some components in the engine bay
- Notice

Child seat fitted to center rear
- Advice

Brake pad(s) wearing thin (3.5.1g)
- Notice

Under-trays fitted obscuring some underside components
- Advice

Brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Notice

Both bumpers scuffed

**MOT #4**

2015-04-10 12:34

**MOT test number**

977650805122

**Result****✗ Failed**

- Notice** Child seat fitted not allowing full inspection of adult belt
- Fail** Nearside Headlamp aim too high (1.8)
- Advice** Brake pad(s) wearing thin (3.5.1g)
- Notice** Engine covers fitted obscuring some components in the engine bay
- Advice** Brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Notice** Child seat fitted to center rear
- Fail** Offside Front Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)
- Notice** Under-trays fitted obscuring some underside components
- Advice** Brake pad(s) wearing thin (3.5.1g)
- Notice** Both bumpers scuffed

**MOT #3**

2014-04-11 13:06

**MOT test number**

378901704104

**Result****✓ Passed**

- Notice** Under-trays fitted obscuring some underside components
- Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Rear Brake hose has slight corrosion to ferrules (3.6.B.4e)
- Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)



MOT #2	2013-04-26 15:05
MOT test number	709236813119
Result	✓ Passed
Advice	Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

MOT #1	2012-11-19 14:10
MOT test number	957844122316
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓  
**Taxed**  
  
Tax due:  
1 July 2024

✓  
**MOT**  
  
Expires:  
25 August 2024

Tax status	Valid until 1 July
Days left	62
MOT expiry date	25 August 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-




Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	YP59VVK
Plate since	2019-03-29
Current registration	YP59VVK
Plate since	2019-03-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.


Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-11-30
Last registration	2023-08-25
Complete history	<a href="#">See info</a>



Registration #1	2009-11-30	9 mi
Registration #2	2012-11-19	26.012 mi
Registration #3	2013-04-26	29.439 mi
Registration #4	2014-04-11	44.199 mi
Registration #5	2015-04-10	55.262 mi
Registration #6	2015-04-10	55.262 mi
Registration #7	2016-03-30	61.797 mi
Registration #8	2017-03-29	65.836 mi
Registration #9	2018-04-05	71.676 mi
Registration #10	2019-04-05	75.277 mi
Registration #11	2020-04-05	75.277 mi
Registration #12	2021-04-05	75.277 mi
Registration #13	2022-04-05	75.277 mi
Registration #14	2023-04-05	75.277 mi
Registration #15	2024-04-05	75.277 mi
Registration #16	2025-04-05	75.277 mi
Registration #17	2026-04-05	75.277 mi
Registration #18	2027-04-05	75.277 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	86%
Pedestrian	53%
Safety systems	86%
Overall rating	81%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1790 mm
Height	1620 mm
Length	4440 mm
Wheel base	2780 mm
Kerb weight	1505 kg
Max. allowed weight	2125 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Engine number 1ZSU191958