



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	FOX URBAN FOX
Colour	Grey
Year of manufacture	-
Top speed	92 mph
0 - 60 mph	17.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	55 BHP
Max. torque	108 Nm at 3.000 rpm
Cylinders	3
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	46.3 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-09-19
Pictures	5
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

MOT #12	2021-08-06 15:56
MOT test number	668170675956
Result	✓ Passed
Next expiry date	2022-08-05

MOT #11	2018-05-04 09:31
MOT test number	923272338043
Result	✓ Passed

Advice Rear Exhaust has a minor leak of exhaust gases (7.1.2)

MOT #10	2018-04-26 08:50
MOT test number	656513282493

Result	✗ Failed
---------------	----------

Advice Rear Exhaust has a minor leak of exhaust gases (7.1.2)

Fail Supplementary Restraint System warning lamp indicates a fault (5.4.2)

Fail Offside Rear coil spring broken (2.4.C.1a)

Fail Nearside Front Front constant velocity joint is insecure (2.5.C.1b)

MOT #9	2017-05-08 13:46
MOT test number	142468826078

Result	✓ Passed
---------------	----------

Advice Nearside Front Tyre worn close to the legal limit inner edge (4.1.E.1)

Advice Offside Front Tyre worn close to the legal limit inner edge (4.1.E.1)

MOT #8	2016-05-16 09:07
MOT test number	590927204534

Result	✓ Passed
---------------	----------

Advice Front Front constant velocity joint gaiter damaged, but preventing the ingress of dirt both sides (2.5.C.1a)

**MOT #7** 2015-05-08 13:40**MOT test number** 617008825120**Result** ✓ Passed**MOT #6** 2015-05-08 10:29**MOT test number** 759328825199**Result** ✗ Failed**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)**Fail** Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)**MOT #5** 2014-05-08 09:55**MOT test number** 148038224147**Result** ✓ Passed**Notice** Rear tyres starting to crack**MOT #4** 2013-05-13 11:10**MOT test number** 219393733163**Result** ✓ Passed**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Notice** Both rear tyres cracking on sidewalls**MOT #3** 2012-05-04 09:50**MOT test number** 229405822132**Result** ✓ Passed**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)



MOT #2	2011-05-13 10:21
MOT test number	367413331140
Result	✓ Passed
<div><div>Advice</div>Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)</div>	

MOT #1	2010-05-14 09:43
MOT test number	770184130108
Result	✓ Passed



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	NG07LPK
Plate since	2024-03-29
Current registration	NG07LPK
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2007-05-12
Last registration	2021-08-06
Complete history	See info



Registration #1	2007-05-12	10 mi
Registration #2	2010-05-14	30.183 mi
Registration #3	2011-05-13	16.847 mi
Registration #4	2012-05-04	47.110 mi
Registration #5	2013-05-13	54.306 mi
Registration #6	2014-05-08	61.424 mi
Registration #7	2015-05-08	69.595 mi
Registration #8	2016-05-08	75.277 mi
Registration #9	2017-05-08	81.277 mi
Registration #10	2018-05-08	87.277 mi
Registration #11	2019-05-08	93.277 mi
Registration #12	2020-05-08	99.277 mi
Registration #13	2021-05-08	105.277 mi
Registration #14	2022-05-08	111.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1660 mm
Height	1544 mm
Length	3828 mm
Wheel base	2465 mm
Kerb weight	1069 kg
Max. allowed weight	1480 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	4
Number of axles	2
Engine number	BMD 313622