



TOYOTA



report date: 2024-03-28

General information

Make	TOYOTA
Model	CELICA T SPORT VVTI
Colour	Silver
Year of manufacture	2004
Top speed	140 mph
0 - 60 mph	7.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	189 BHP
Max. torque	179 Nm at 6.800 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	24.6 mpg
Consumption extra urban	42.8 mpg
Consumption combined	33.6 mpg
CO2 emission	200 g/km
CO2 label	J





Internet history

Entry 1

Date	2022-06-15
Pictures	0
Listing price	View report

source: cargurus.co.uk



MOT history

MOT expiry date	2024-05-19
MOT pass rate	69 %
MOT passed	18
Failed MOT tests	8
Total advice items	39
Total items failed	24

MOT #26	2023-05-04 16:05
MOT test number	957009257017
Result	✓ Passed
Next expiry date	2024-05-19
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Exhaust noisy (8.1.1 (a))

MOT #25	2023-04-24 13:33
MOT test number	602748568888
Result	✗ Failed
Fail	Offside Front Brake pipe excessively corroded (1.1.11 (c))
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Fail	Offside Headlamp insecure (4.1.1 (c))
Advice	Exhaust noisy (8.1.1 (a))
Fail	Anti-roll bar linkage ball joint excessively worn offside + nearside front (5.3.4 (a) (i))
Fail	Offside Rear Brake pipe excessively corroded (1.1.11 (c))
Fail	Nearside Front Brake hose excessively chafed rubbing on suspension /anti roll bar link (1.1.12 (b) (ii))
Fail	Offside Headlamp aim too high (4.1.2 (a))

**MOT #24** 2022-05-20 14:03**MOT test number** 877349369338**Result** ✓ Passed**MOT #23** 2021-10-21 08:15**MOT test number** 629802655153**Result** ✓ Passed**MOT #22** 2020-10-23 08:05**MOT test number** 339729133556**Result** ✓ Passed**Advice** Rear Service brake binding but not excessively both sides (1.2.1 (f))**Advice** Noise from brakes rear both sides**MOT #21** 2019-10-28 09:15**MOT test number** 389578529400**Result** ✓ Passed**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Nearside Rear Inner Nail in tyre edge**Advice** Battery went flat during test**MOT #20** 2019-10-28 09:15**MOT test number** 726415691881**Result** ✗ Failed**Advice** Nearside Rear Inner Nail in tyre edge**Advice** Battery went flat during test**Pass with rectification** Nearside Front Position lamp light intensity significantly reduced (4.2.3 (a) (ii))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #19**

2018-10-05 10:48

MOT test number

600634293568

Result

✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Nail in tyre
- Advice** Parking brake 42% imbalance
- Advice** Front Registration plate deteriorated but not likely to be misread cracked (0.1 (b))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #18

2018-10-04 12:04

MOT test number

476346429108

Result

✗ Failed

- Advice** Parking brake 42% imbalance
- Fail** Offside Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Rear Exhaust has a major leak of exhaust gases (6.1.2 (a))
- Fail** Offside Front Position lamp not working (4.2.1 (a))
- Fail** Offside Headlamp aim not tested (4.1.2 (b))
- Advice** Front Registration plate deteriorated but not likely to be misread cracked (0.1 (b))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Nail in tyre
- Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))

**MOT #17**

2017-10-25 13:06

MOT test number

812660404421

Result

✓ Passed

Advice

Exhaust has a minor leak of exhaust gases rear section (7.1.2)

MOT #16

2017-10-25 08:10

MOT test number

107809169052

Result

✗ Failed

Advice

Exhaust has a minor leak of exhaust gases rear section (7.1.2)

Advice

Nearside Front Anti-roll bar linkage ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

Fail

Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

Fail

Nearside Stop lamp not working (1.2.1b)

Fail

Parking brake lever has no reserve travel (3.1.6b)

Fail

Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)

Fail

Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #15

2016-11-03 15:36

MOT test number

498582119722

Result

✓ Passed

Advice

Exhaust has a minor leak of exhaust gases centre silencer (7.1.2)

Advice

Offside Rear Nail in tyre

Advice

Front Inner brake disc worn, pitted or scored, but not seriously weakened faces (3.5.1i)

Advice

Oil leak

**MOT #14**

2016-11-03 10:08

MOT test number

583626166849

Result**✗ Failed****Advice** Oil leak**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)**Advice** Offside Rear Nail in tyre**Fail** Parking brake lever has no reserve travel (3.1.6b)**Advice** Exhaust has a minor leak of exhaust gases centre silencer (7.1.2)**Advice** Front Inner brake disc worn, pitted or scored, but not seriously weakened faces (3.5.1i)**MOT #13**

2015-11-04 15:01

MOT test number

482080010199

Result**✓ Passed****Advice** Nearside Front Upper Anti-roll bar linkage ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)**MOT #12**

2014-08-29 13:39

MOT test number

899811744227

Result**✓ Passed****Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear coil spring corroded (2.4.C.1b)**MOT #11**

2014-02-04 10:41

MOT test number

737485034034

Result**✓ Passed**

**MOT #10** 2014-02-03 09:38**MOT test number** 935814734099**Result** ✗ Failed**Fail** Nearside Front Shock absorber has a serious fluid leak (2.7.3)**Fail** Front brake application uneven (3.7.B.2)**Fail** Offside front brake binding (3.7.B.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #9** 2013-08-16 09:20**MOT test number** 328018523482**Result** ✓ Passed**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**MOT #8** 2012-08-31 11:36**MOT test number** 258754542266**Result** ✓ Passed**MOT #7** 2011-10-05 11:49**MOT test number** 369418171242**Result** ✓ Passed**MOT #6** 2011-10-05 11:49**MOT test number** 328678371274**Result** ✗ Failed**Pass with rectification** Rear Brake lining(s) less than 1.5 mm thick (3.5.1g)**MOT #5** 2010-09-29 12:30**MOT test number** 563762470208**Result** ✓ Passed



MOT #4	2010-09-29 12:30
MOT test number	731052670258
Result	✗ Failed
<div>Pass with rectification</div> Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)	

MOT #3	2009-10-07 12:53
MOT test number	274060289295
Result	✓ Passed

MOT #2	2008-10-07 11:13
MOT test number	582071688272
Result	✓ Passed

MOT #1	2007-10-10 10:36
MOT test number	380173787446
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 May 2025

✓
MOT
Expires:
19 May 2024

Tax status	Valid until 1 May
Days left	367
MOT expiry date	19 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2004-10-15
Last registration	2023-05-04
Complete history	See info



Registration #1	2004-10-15	24 mi
Registration #2	2007-10-10	19.696 mi
Registration #3	2008-10-07	24.814 mi
Registration #4	2009-10-07	29.976 mi
Registration #5	2010-09-29	34.438 mi
Registration #6	2011-10-05	38.666 mi
Registration #7	2012-08-31	43.570 mi
Registration #8	2013-08-16	47.242 mi
Registration #9	2014-02-03	48.100 mi
Registration #10	2014-02-04	48.100 mi
Registration #11	2014-08-29	49.492 mi
Registration #12	2015-11-04	53.210 mi
Registration #13	2016-11-03	55.701 mi
Registration #14	2016-11-03	55.701 mi
Registration #15	2016-11-03	55.701 mi
Registration #16	2016-11-03	55.701 mi
Registration #17	2016-11-03	55.701 mi
Registration #18	2016-11-03	55.701 mi
Registration #19	2016-11-03	55.701 mi
Registration #20	2016-11-03	55.701 mi
Registration #21	2016-11-03	55.701 mi
Registration #22	2016-11-03	55.701 mi
Registration #23	2016-11-03	55.701 mi
Registration #24	2016-11-03	55.701 mi
Registration #25	2016-11-03	55.701 mi
Registration #26	2016-11-03	55.701 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1735 mm
Height	1315 mm
Length	4355 mm
Wheel base	2600 mm
Kerb weight	1145 kg
Max. allowed weight	1595 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	2ZZ0143405