



report date: 2024-03-28

General information

Make	FORD
Model	S-MAX GHIA TDCI
Colour	Grey
Year of manufacture	-
Top speed	120 mph
0 - 60 mph	10.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	143 BHP
Max. torque	340 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	34.5 mpg
Consumption extra urban	51.4 mpg
Consumption combined	43.5 mpg







Internet history

Entry 1

Date	2021-06-26
Pictures	5
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT #12

2022-02-03 19:24

MOT test number

122894620965

Result

✗ Failed

- Minor** Rear Windscreen wiper blade defective (3.4 (b) (i))
- Fail** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Fail** Nearside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Front Windscreen washer not working (3.5 (a))
- Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Fail** Rear fog lamp not working (4.5.1 (a) (ii))
- Fail** Offside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Rear Axle Corroded
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Horn not working (7.7 (a))



MOT #11

2020-11-12 14:37

MOT test number

585328559109

Result

✓ Passed

- Advice

Rear Lower Gearbox mounting defective
- Advice

Engine cover fitted
- Advice

Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice

Nearside Front Tyre worn close to legal limit/worn on edge 2.0 mm (5.2.3 (e))
- Advice

Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice

Under tray fitted
- Advice

Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice

Offside Side repeater slightly discoloured (4.4.3 (a))

**MOT #10**

2020-11-09 17:31

MOT test number

526729853902

Result**✗ Failed**

- Fail** Nearside Rear Suspension arm pin or bush excessively worn tailing arm as marked (5.3.4 (a) (i))
- Fail** Offside Side repeater incorrect colour (4.4.3 (a))
- Fail** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Rear Lower Gearbox mounting defective
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Under tray fitted
- Fail** Offside Rear Suspension arm pin or bush excessively worn tailing arm as marked (5.3.4 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2.0 mm (5.2.3 (e))
- Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Engine cover fitted

MOT #9

2019-05-04 10:29

MOT test number

777817149432

Result**✓ Passed****MOT #8**

2018-06-04 13:57

MOT test number

992896038691

Result**✓ Passed**

**MOT #7**

2018-06-04 10:04

MOT test number

647426394515

Result**✗ Failed**

- Advice** Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge wearing inner edge (5.2.3 (e))
- Advice** Rear sub frame light corrosion
- Fail** Offside Front Position lamp not working (4.2.1 (a))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge wearing inner edge (5.2.3 (e))
- Advice** Offside Rear Tyre slightly damaged/valve stem damaged (5.2.3 (d) (i))

MOT #6

2018-02-27 08:37

MOT test number

508670142166

Result**✓ Passed**

- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear coil spring corroded (2.4.C.1b)
- Advice** Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Rear Valve stem slightly damaged perished (4.1.D.1e)
- Advice** Undertrays and engine cover fitted
- Advice** Offside Rear coil spring corroded (2.4.C.1b)
- Advice** Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #5** 2017-02-10 09:49**MOT test number** 768156100635**Result** ✓ Passed**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened inner surface (3.5.1i)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened inner surface (3.5.1i)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #4** 2016-02-12 09:53**MOT test number** 825024556078**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Front Seat belt damaged but webbing not significantly weakened (5.2.2a)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #3** 2014-12-03 13:22**MOT test number** 157997734354**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #2** 2013-12-09 13:23**MOT test number** 746663243355**Result** ✓ Passed**Advice** Offside Outer Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Child seat fitted not allowing full inspection of adult belt**Advice** Rear Brake pad(s) wearing thin (3.5.1g)



MOT #1	2012-12-05 14:11
MOT test number	496840442373
Result	✓ Passed



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	MT59YKF
Plate since	2019-03-28
Current registration	MT59YKF
Plate since	2019-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2009-12-24
Last registration	2022-02-03
Complete history	See info



Registration #1	2009-12-24	26 mi
Registration #2	2012-12-05	22.943 mi
Registration #3	2013-12-09	29.904 mi
Registration #4	2014-12-03	37.170 mi
Registration #5	2016-02-12	56.487 mi
Registration #6	2017-02-10	74.149 mi
Registration #7	2018-02-27	90.400 mi
Registration #8	2019-05-29	111.277 mi
Registration #9	2020-05-29	131.277 mi
Registration #10	2021-05-29	151.277 mi
Registration #11	2022-05-29	171.277 mi
Registration #12	2023-05-29	191.277 mi
Registration #13	2024-05-29	211.277 mi
Registration #14	2025-05-29	231.277 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1884 mm
Height	1736 mm
Length	4820 mm
Wheel base	2850 mm
Kerb weight	1933 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	9K79192