



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	I30 CRDI COMFORT
Colour	Blue
Year of manufacture	-
Top speed	112 mph
0 - 60 mph	12.8 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	113 BHP
Max. torque	253 Nm at 2.500 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.9 mpg



LABEL UNKNOWN

**MOT history**

MOT #9	2020-06-12 13:09
MOT test number	512722112621
Result	✓ Passed
Next expiry date	2021-07-08
Advice	Front Tyre worn close to legal limit/worn on edge both side (5.2.3 (e))
Advice	Rear Brake pad(s) wearing thin both side (1.1.13 (a) (ii))

MOT #8	2019-07-09 08:13
MOT test number	867585801019
Result	✓ Passed
Advice	Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #7	2018-08-20 15:41
MOT test number	525106804786
Result	✓ Passed
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #6	2018-08-20 08:41
MOT test number	621709467169
Result	✗ Failed
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Fail	Front Tyre tread depth below requirements of 1.6mm x2 (5.2.3 (e))
Fail	Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #5** 2017-08-24 09:45**MOT test number** 284575948615**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2016-08-12 09:36**MOT test number** 366240881624**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #3** 2015-08-12 14:40**MOT test number** 877454125203**Result** ✓ Passed**MOT #2** 2014-10-31 10:18**MOT test number** 587044204327**Result** ✓ Passed**MOT #1** 2013-10-25 10:50**MOT test number** 946558393220**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2010-11-03
Last registration	2020-06-12
Complete history	See info



Registration #1	2010-11-03	13 mi
Registration #2	2013-10-25	20.180 mi
Registration #3	2014-10-31	28.171 mi
Registration #4	2015-08-12	29.457 mi
Registration #5	2016-08-12	40.591 mi
Registration #6	2017-08-20	51.727 mi
Registration #7	2018-08-20	62.863 mi
Registration #8	2019-08-20	73.999 mi
Registration #9	2020-06-12	85.135 mi
Registration #10	2020-06-12	96.271 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1760 mm
Height	1490 mm
Length	4245 mm
Wheel base	2650 mm
Kerb weight	1403 kg
Max. allowed weight	1840 kg

Additional information

Fuel tank capacity	53 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D4FBAZ231401