



report date: 2024-03-28

General information

Make	VOLVO
Model	V70 D SE
Colour	Green
Year of manufacture	2008
Top speed	130 mph
0 - 60 mph	9.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	161 BHP
Max. torque	340 Nm at 1.750 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	31.4 mpg
Consumption extra urban	51.4 mpg
Consumption combined	41.5 mpg
CO2 emission	172 g/km
CO2 label	H






Internet history

Entry 1

Date	2022-07-23
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-04-05
MOT pass rate	74 %
MOT passed	14
Failed MOT tests	5
Total advice items	33
Total items failed	8

MOT #19	2024-03-26 10:14
MOT test number	824848064590
Result	✓ Passed
Next expiry date	2025-04-05
Minor	Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Brake disc worn, pitted or scored, but not seriously weakened both fronts (1.1.14 (a) (ii))
Advice	Coil spring corroded both rears (5.3.1 (b) (i))

MOT #18	2024-03-21 10:03
MOT test number	679589046374
Result	✗ Failed
Fail	Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
Fail	Offside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt split (5.3.4 (b) (ii))
Minor	Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Fail	Direction indicator incorrect colour both rears (4.4.3 (a))
Advice	Brake disc worn, pitted or scored, but not seriously weakened both fronts (1.1.14 (a) (ii))
Fail	Nearside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt split (5.3.4 (b) (ii))
Advice	Coil spring corroded both rears (5.3.1 (b) (i))

**MOT #17** 2023-03-09 14:51**MOT test number** 770125297097**Result** ✓ Passed**Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))**MOT #16** 2023-03-09 11:20**MOT test number** 317239267747**Result** ✗ Failed**Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #15** 2022-04-06 11:15**MOT test number** 292367357831**Result** ✓ Passed**MOT #14** 2021-03-15 14:42**MOT test number** 733254078256**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Nearside Front Obligatory mirror slightly loose taped (3.3 (b) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #13** 2020-03-11 14:38**MOT test number** 260584923988**Result** ✓ Passed**Advice** Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Rear anti roll bar has corrosion

**MOT #12** 2020-03-11 13:53**MOT test number** 111097473690**Result** ✗ Failed**Fail** Front Tyre(s) of different sizes are fitted on the same axle. (5.2.3 (b))**Advice** Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Rear anti roll bar has corrosion**MOT #11** 2019-03-14 08:52**MOT test number** 106821940021**Result** ✓ Passed**Advice** Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**MOT #10** 2018-03-02 09:05**MOT test number** 809732655674**Result** ✓ Passed**Advice** Front Tyre worn close to the legal limit both inner edge (4.1.E.1)**MOT #9** 2018-03-02 09:05**MOT test number** 281053617090**Result** ✗ Failed**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Front Tyre worn close to the legal limit both inner edge (4.1.E.1)

**MOT #8** 2017-03-04 12:10**MOT test number** 740182838153**Result** ✓ Passed**Advice** Offside Rear Anti-roll bar has slight play in a ball joint (2.4.G.2)**Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)**Advice** Tyre worn close to the legal limit Both front inner and outer edges (4.1.E.1)**MOT #7** 2016-02-11 15:54**MOT test number** 601142968379**Result** ✓ Passed**Advice** Both front inner edge**MOT #6** 2015-01-27 15:51**MOT test number** 186247425494**Result** ✓ Passed**Advice** Rear coil spring corroded (2.4.C.1b)**Notice** Under-trays fitted obscuring some underside components**MOT #5** 2014-02-07 10:36**MOT test number** 578218534094**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**Advice** Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Under-trays fitted obscuring some underside components**MOT #4** 2013-01-28 10:23**MOT test number** 406258523092**Result** ✓ Passed



MOT #3 2012-02-08 15:26

MOT test number 149099232494

Result ✓ Passed

MOT #2 2011-03-23 16:56

MOT test number 456622481002

Result ✓ Passed

Notice Oi level on the minimum

Notice Both front and the n/s/r wheels are slightly distorted

MOT #1 2011-03-23 16:56

MOT test number 266852381036

Result ✗ Failed

Notice Oi level on the minimum

Pass with rectification Offside Registration plate lamp not working (1.1.C.1d)

Notice Both front and the n/s/r wheels are slightly distorted



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
5 April 2025

Tax status	Valid until 1 August
Days left	95
MOT expiry date	5 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2008-04-07
Last registration	2024-03-26
Complete history	See info



Registration #1	2008-04-07	13 mi
Registration #2	2011-03-23	70.460 mi
Registration #3	2012-02-08	75.458 mi
Registration #4	2013-01-28	82.105 mi
Registration #5	2014-02-07	88.639 mi
Registration #6	2015-01-27	96.687 mi
Registration #7	2016-02-11	105.335 mi
Registration #8	2017-03-04	112.417 mi
Registration #9	2018-03-02	120.018 mi
Registration #10	2018-03-02	120.018 mi
Registration #11	2019-03-02	120.018 mi
Registration #12	2019-03-02	120.018 mi
Registration #13	2019-03-02	120.018 mi
Registration #14	2019-03-02	120.018 mi
Registration #15	2019-03-02	120.018 mi
Registration #16	2019-03-02	120.018 mi
Registration #17	2019-03-02	120.018 mi
Registration #18	2019-03-02	120.018 mi
Registration #19	2019-03-02	120.018 mi
Registration #20	2019-03-02	120.018 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1804 mm
Height	1465 mm
Length	4710 mm
Wheel base	2816 mm
Kerb weight	1761 kg
Max. allowed weight	2300 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	528834