



AV60KAU

report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	TRANSPORTER T32 TDI P/V
Colour	White
Year of manufacture	2010
Top speed	98 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	102 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	29.1 mpg
Consumption extra urban	44.8 mpg
Consumption combined	37.7 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-09-11
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-11-10
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	11
Total items failed	5

MOT #14	2023-11-01 11:51
MOT test number	813620717634
Result	✓ Passed
Next expiry date	2024-11-10
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #13	2023-10-12 14:35
MOT test number	879127178653
Result	✗ Failed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Nearside Rear Shock absorbers has an excessively worn bush (5.3.2 (c))
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #12	2022-11-11 16:19
MOT test number	763824583497
Result	✓ Passed
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Offside Rear Upper Shock absorbers has a slightly worn bush (5.3.2 (c))
Minor	Nearside Obligatory mirror slightly loose Mirror cap loose. (3.3 (b) (i))
Advice	Nearside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))

**MOT #11** 2022-11-11 10:25**MOT test number** 376572459358**Result** ✗ Failed**Fail** Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Offside Rear Upper Shock absorbers has a slightly worn bush (5.3.2 (c))**Pass with rectification** Nearside Headlamp aim too low (4.1.2 (a))**Minor** Nearside Obligatory mirror slightly loose Mirror cap loose. (3.3 (b) (i))**Advice** Nearside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #10** 2021-09-16 08:34**MOT test number** 154435387172**Result** ✓ Passed**MOT #9** 2020-10-05 14:51**MOT test number** 809237266861**Result** ✓ Passed**MOT #8** 2019-10-07 13:25**MOT test number** 338310803568**Result** ✓ Passed**MOT #7** 2018-10-05 10:30**MOT test number** 168157446798**Result** ✓ Passed



MOT #6	2017-10-09 13:34
---------------	------------------

MOT test number	856143506172
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #5	2016-10-04 09:08
---------------	------------------

MOT test number	957316819832
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #4	2015-10-05 15:36
---------------	------------------

MOT test number	396142117035
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #3	2015-10-05 15:36
---------------	------------------

MOT test number	344684870859
------------------------	--------------

Result	✗ Failed
---------------	----------

Pass with rectification	Nearside Registration plate lamp not working (1.1.C.1d)
--------------------------------	---

MOT #2	2014-10-07 10:15
---------------	------------------

MOT test number	445700384281
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #1	2013-10-29 12:08
---------------	------------------

MOT test number	876402303324
------------------------	--------------

Result	✓ Passed
---------------	----------



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
10 November 2024

Tax status		Valid until 1 March
Days left		305
MOT expiry date		10 November 2024
Full MOT history		See MOT history



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	AV60KAU
Plate since	2024-03-29
Current registration	AV60KAU
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-11-08
Last registration	2023-11-01
Complete history	See info



Registration #1	2010-11-08	12 mi
Registration #2	2013-10-29	23.618 mi
Registration #3	2014-10-07	33.942 mi
Registration #4	2015-10-05	43.536 mi
Registration #5	2015-10-05	43.536 mi
Registration #6	2016-10-04	52.369 mi
Registration #7	2017-10-09	67.843 mi
Registration #8	2018-10-05	87.388 mi
Registration #9	2019-10-05	107.933 mi
Registration #10	2020-10-05	128.478 mi
Registration #11	2021-10-05	149.023 mi
Registration #12	2022-10-05	169.568 mi
Registration #13	2023-10-05	190.113 mi
Registration #14	2024-03-29	210.658 mi
Registration #15	2024-03-29	210.658 mi
Registration #16	2024-03-29	210.658 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1904 mm
Height	1990 mm
Length	5292 mm
Wheel base	3400 mm
Kerb weight	1928 kg
Max. allowed weight	3200 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of seats	3

Number of axles	2
Engine number	CAA 203179