



report date: 2024-03-29

General information

Make	MAZDA
Model	6 TS
Colour	Black
Year of manufacture	2012
Top speed	123 mph
0 - 60 mph	11.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	120 BHP
Max. torque	165 Nm at 4.300 rpm
Engine capacity	1.798 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.4 mpg
Consumption extra urban	53.3 mpg
Consumption combined	40.9 mpg
CO2 emission	155 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-02-01
Pictures	1
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2025-04-15
MOT pass rate	67 %
MOT passed	10
Failed MOT tests	5
Total advice items	32
Total items failed	14

MOT #15	2024-04-16 15:12
MOT test number	849335852407
Result	✓ Passed
Next expiry date	2025-04-15
Advice	Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))
Advice	Steering slightly tight lock to lock
Advice	Nearside Front Service brake binding but not excessively (1.2.1 (f))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #14**

2024-04-10 15:28

MOT test number

125629229396

Result**✗ Failed**

Fail Offside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Fail Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Fail Nearside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Fail Offside Rear Anti-roll bar linkage insecurely attached (5.3.3 (a) (i))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))

Fail Parking brake efficiency below requirements (1.4.2 (a) (i))

Advice Steering slightly tight lock to lock

Fail Offside Front Position lamp not working (4.2.1 (a) (ii))

Advice Nearside Front Service brake binding but not excessively (1.2.1 (f))

MOT #13

2023-03-27 15:40

MOT test number

203116019290

Result**✓ Passed**

Minor Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

Advice Offside Rear Lower Anti-roll bar ball joint has slight play (5.3.4 (a) (i))

Minor Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**MOT #12**

2023-03-13 19:20

MOT test number

153980443863

Result**✗ Failed****Advice**

Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

Minor

Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Fail

Power steering inoperative and steering adversely affected (2.1.5 (c) (ii))

Advice

Offside Rear Lower Anti-roll bar ball joint has slight play (5.3.4 (a) (i))

Minor

Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #11

2023-02-08 09:32

MOT test number

489232479749

Result**✗ Failed****Fail**

Power steering inoperative and steering adversely affected (2.1.5 (c) (ii))

Fail

Offside Rear Anti-roll bar linkage fractured (5.3.3 (b) (ii))

MOT #10

2022-02-10 15:08

MOT test number

384046280575

Result**✓ Passed****Advice**

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #9

2022-02-10 09:22

MOT test number

638595780171

Result**✗ Failed****Fail**

Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Fail

Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail

Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #8** 2021-02-10 14:26**MOT test number** 342720792840**Result** ✓ Passed

- Advice** Service brake binding but not excessively Both rear (1.2.1 (f))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge Edges (5.2.3 (e))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge Edges (5.2.3 (e))

MOT #7 2021-02-10 09:58**MOT test number** 276513270467**Result** ✗ Failed

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge Edges (5.2.3 (e))
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Service brake binding but not excessively Both rear (1.2.1 (f))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge Edges (5.2.3 (e))
- Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #6 2020-02-10 09:21**MOT test number** 624770766614**Result** ✓ Passed**MOT #5** 2019-02-11 11:43**MOT test number** 289523810415**Result** ✓ Passed**MOT #4** 2018-02-06 10:45**MOT test number** 974523020879**Result** ✓ Passed

**MOT #3** 2017-06-01 08:20**MOT test number** 349141626314**Result** ✓ Passed**Advice** Under trays fitted**MOT #2** 2016-05-11 09:16**MOT test number** 635858799680**Result** ✓ Passed**Advice** Brake disc worn, pitted or scored, but not seriously weakened wear on both front discs (3.5.1i)**Advice** Brake disc worn, pitted or scored, but not seriously weakened corrosion rear discs (3.5.1i)**Advice** Under trays fitted**MOT #1** 2015-05-05 10:04**MOT test number** 925885425176**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
15 April 2025

Tax status	Valid until 1 September
Days left	124
MOT expiry date	15 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	 KP12GWF
Plate since	2019-03-29
Current registration	 KP12GWF
Plate since	2019-03-29

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2012-05-31
Last registration	2024-04-16
Complete history	See info



Registration #1	2012-05-31	10 mi
Registration #2	2015-05-05	55.573 mi
Registration #3	2016-05-11	72.190 mi
Registration #4	2017-06-01	89.647 mi
Registration #5	2018-02-06	94.180 mi
Registration #6	2019-02-11	105.157 mi
Registration #7	2020-02-10	114.001 mi
Registration #8	2020-05-20	115.277 mi
Registration #9	2021-02-10	120.670 mi
Registration #10	2021-05-20	121.277 mi
Registration #11	2021-05-20	121.277 mi
Registration #12	2021-05-20	121.277 mi
Registration #13	2021-05-20	121.277 mi
Registration #14	2021-05-20	121.277 mi
Registration #15	2021-05-20	121.277 mi
Registration #16	2021-05-20	121.277 mi
Registration #17	2021-05-20	121.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	77%
Children	81%
Pedestrian	49%
Safety systems	71%
Overall rating	72%
Video	see crash video



Dimensions & weight

Width	1795 mm
Height	1440 mm
Length	4755 mm
Wheel base	2725 mm
Kerb weight	1410 kg
Max. allowed weight	1925 kg

Additional information

Fuel tank capacity	64 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	L8 10227363