



Mercedes-Benz



report date: 2024-03-29

General information

Make	MERCEDES
Model	CLK CLK200 KOMPRESSOR AVANTGARDE
Colour	Silver
Year of manufacture	2005
Top speed	139 mph
0 - 60 mph	10.5 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	161 BHP
Max. torque	240 Nm at 4.000 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	22.1 mpg
Consumption extra urban	41.5 mpg
Consumption combined	31.4 mpg
CO2 emission	214 g/km
CO2 label	K






Internet history

Entry 1

Date	2021-10-09
Pictures	28
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-01-26
MOT pass rate	67 %
MOT passed	16
Failed MOT tests	8
Total advice items	23
Total items failed	13

MOT #24 2024-01-24 12:46

MOT test number 543123489124

Result ✓ Passed

Next expiry date 2025-01-26

Advice Front Brake disc worn, but not excessively Both (1.1.14 (a) (i))

Advice Rear Tyre slightly damaged/cracking or perishing Both (5.2.3 (d) (ii))

Advice Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Both (5.3.4 (a) (i))

MOT #23 2023-01-24 14:57

MOT test number 991082303416

Result ✓ Passed

Advice Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Both (5.3.4 (a) (i))

MOT #22 2022-01-27 10:59

MOT test number 927258647956

Result ✓ Passed

**MOT #21** 2021-09-17 14:33**MOT test number** 398340229293**Result** ✓ Passed**Advice** Nearside Front 10 years old**Advice** Under trays fitted**Advice** Exhaust mounting defective exhaust rear section mounting missing (6.1.2 (a))**MOT #20** 2019-12-03 11:00**MOT test number** 365375835801**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Central Exhaust mounting defective (6.1.2 (a))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #19** 2018-08-02 13:13**MOT test number** 478014629788**Result** ✓ Passed**Advice** Outer sill covers fitted**Advice** Vehicle under body covers fitted**MOT #18** 2018-08-02 13:13**MOT test number** 719867425364**Result** ✗ Failed**Advice** Outer sill covers fitted**Advice** Vehicle under body covers fitted**Pass with rectification** Offside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (i))

**MOT #17** 2017-08-01 10:32**MOT test number** 796543551900**Result** ✓ Passed**MOT #16** 2017-08-01 10:32**MOT test number** 679383216162**Result** ✗ Failed**Pass with rectification** Nearside Front coil spring broken (2.4.C.1a)**MOT #15** 2016-05-17 12:29**MOT test number** 163515900671**Result** ✓ Passed**Advice** Engine bay cover fitted**Advice** Outer sill covers fitted**Advice** Exhaust centre support missing, system still adequately supported**Advice** Vehicle under body panels fitted**MOT #14** 2016-05-16 09:06**MOT test number** 177368545464**Result** ✗ Failed**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Outer sill covers fitted**Advice** Exhaust centre support missing, system still adequately supported**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Vehicle under body panels fitted**Advice** Engine bay cover fitted**Fail** Windscreen has damage to an area in excess of a 10mm circle within zone 'A' (8.3.1a)

**MOT #13** 2015-04-22 19:16**MOT test number** 227462215146**Result** ✓ Passed**MOT #12** 2014-05-20 10:31**MOT test number** 116990644130**Result** ✓ Passed**MOT #11** 2013-05-20 11:24**MOT test number** 759220143173**Result** ✓ Passed**MOT #10** 2013-05-20 11:24**MOT test number** 468370543158**Result** ✗ Failed**Pass with rectification** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #9** 2012-08-07 15:34**MOT test number** 406000922209**Result** ✗ Failed**Pass with rectification** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Pass with rectification** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #8** 2012-08-07 15:34**MOT test number** 555840922240**Result** ✓ Passed**MOT #7** 2011-08-26 11:30**MOT test number** 918568131251**Result** ✓ Passed

**MOT #6** 2010-09-14 10:38**MOT test number** 881027750286**Result** ✓ Passed**MOT #5** 2010-09-09 15:31**MOT test number** 641872250249**Result** ✗ Failed**Fail** Nearside Front Track rod end ball joint has excessive play (2.2.B.1f)**Fail** Offside Front Track rod end ball joint has excessive play (2.2.B.1f)**MOT #4** 2009-10-21 16:10**MOT test number** 322964699264**Result** ✓ Passed**MOT #3** 2009-10-16 09:41**MOT test number** 401079989209**Result** ✗ Failed**Fail** Nearside Rear Seat belt stitching badly frayed (5.2.2b)**Advice** Front wheel bearing has slight play (2.5.A.3c)**Fail** Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)**MOT #2** 2008-10-13 11:29**MOT test number** 644557288289**Result** ✓ Passed**MOT #1** 2008-10-13 09:41**MOT test number** 350097288255**Result** ✗ Failed**Fail** Nearside Rear coil spring incomplete (2.4.C.1a)



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
26 January 2025

Tax status	Valid until 1 February
Days left	278
MOT expiry date	26 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	 KD55NHY
Plate since	2019-03-29
Current registration	 KD55NHY
Plate since	2019-03-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2005-09-30
Last registration	2024-01-24
Complete history	See info



Registration #1	2005-09-30	20 mi
Registration #2	2008-10-13	29.341 mi
Registration #3	2008-10-13	29.341 mi
Registration #4	2009-10-16	35.694 mi
Registration #5	2009-10-21	35.798 mi
Registration #6	2010-09-09	45.092 mi
Registration #7	2010-09-14	45.293 mi
Registration #8	2011-08-26	56.799 mi
Registration #9	2012-08-07	62.401 mi
Registration #10	2013-05-20	65.549 mi
Registration #11	2014-05-20	72.352 mi
Registration #12	2015-04-22	74.071 mi
Registration #13	2016-04-22	75.000 mi
Registration #14	2017-04-22	75.000 mi
Registration #15	2018-04-22	75.000 mi
Registration #16	2019-04-22	75.000 mi
Registration #17	2020-04-22	75.000 mi
Registration #18	2021-04-22	75.000 mi
Registration #19	2022-04-22	75.000 mi
Registration #20	2023-04-22	75.000 mi
Registration #21	2024-01-24	75.000 mi
Registration #22		
Registration #23		
Registration #24		

More info >



Dimensions & weight

Width	1991 mm
Height	1415 mm
Length	4652 mm
Wheel base	2690 mm
Kerb weight	1665 kg
Max. allowed weight	2135 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	27194030699402