



report date: 2024-03-29

General information

Make	VOLVO
Model	S40 D SPORT V50
Colour	Blue
Year of manufacture	-
Top speed	130 mph
0 - 60 mph	9.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	136 BHP
Max. torque	320 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	61.4 mpg
Consumption combined	49.6 mpg





MOT history

MOT #18 2020-03-27 14:15**MOT test number** 629319943895**Result** ✓ Passed**Next expiry date** 2021-03-29

Advice Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn both rear axle bushes starting to split (5.1.2 (b) (i))

MOT #17 2020-03-27 14:15**MOT test number** 485741723218**Result** ✗ Failed

Pass with rectification Offside Front Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

Advice Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn both rear axle bushes starting to split (5.1.2 (b) (i))

Pass with rectification Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #16 2019-03-13 12:28**MOT test number** 772274351879**Result** ✓ Passed**MOT #15** 2019-03-06 13:19**MOT test number** 227232105451**Result** ✗ Failed

Fail Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

MOT #14 2018-03-13 15:43**MOT test number** 717491738348**Result** ✓ Passed

Advice Nearside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

Advice Offside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

**MOT #13**

2018-03-13 12:10

MOT test number

903109205021

Result**✗ Failed****Advice** Offside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**MOT #12**

2017-03-25 11:12

MOT test number

171366211530

Result**✓ Passed****MOT #11**

2017-03-16 13:59

MOT test number

575868918933

Result**✗ Failed****Fail** Offside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Fail** Nearside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)**Fail** Nearside rear brake binding (3.7.B.1)

**MOT #10**

2016-03-30 11:34

MOT test number

628758603599

Result

✓ Passed

Advice Offside Front Suspension arm rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Offside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

Advice Offside Front front brake fluctuating, but not excessively (3.7.B.3)

Advice Nearside Front Suspension arm rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Nearside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

Advice Nearside Front front brake fluctuating, but not excessively (3.7.B.3)

MOT #9

2016-03-30 07:27

MOT test number

911973876548

Result

✗ Failed

Fail Offside Rear Direction indicators incorrect colour (1.4.A.2f)

Fail Nearside Rear Registration plate lamp not working (1.1.C.1d)

Advice Nearside Front Suspension arm rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Nearside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

Fail Offside Front Direction indicators not working (1.4.A.2c)

Fail Nearside Rear Direction indicators incorrect colour (1.4.A.2f)

Advice Offside Front Suspension arm rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Offside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

MOT #8

2015-03-18 16:43

MOT test number

229097975015

Result

✓ Passed

**MOT #7** 2014-03-21 13:27**MOT test number** 838510284032**Result** ✓ Passed**MOT #6** 2013-02-19 15:12**MOT test number** 365780453016**Result** ✓ Passed**MOT #5** 2013-02-15 13:06**MOT test number** 508106943091**Result** ✗ Failed**Fail** Offside rear parking brake recording little or no effort (3.7.B.6a)**MOT #4** 2012-02-17 11:47**MOT test number** 829198042052**Result** ✓ Passed**MOT #3** 2012-02-17 09:31**MOT test number** 677648542014**Result** ✗ Failed**Fail** Offside rear parking brake recording little or no effort (3.7.B.6a)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Fail** Offside Rear Registration plate lamp not working (1.1.C.1d)**MOT #2** 2011-02-15 11:46**MOT test number** 567256841046**Result** ✓ Passed



MOT #1	2010-02-10 10:49
MOT test number	531921240072
Result	✓ Passed



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-03-01
Last registration	2020-03-27
Complete history	See info



Registration #1	2007-03-01	6 mi
Registration #2	2010-02-10	29.807 mi
Registration #3	2011-02-15	37.599 mi
Registration #4	2012-02-17	52.681 mi
Registration #5	2012-02-17	52.681 mi
Registration #6	2013-02-15	71.481 mi
Registration #7	2013-02-19	71.491 mi
Registration #8	2014-03-21	94.070 mi
Registration #9	2015-03-18	110.752 mi
Registration #10	2016-03-30	116.268 mi
Registration #11	2016-03-30	116.268 mi
Registration #12	2016-03-30	116.268 mi
Registration #13	2016-03-30	116.268 mi
Registration #14	2016-03-30	116.268 mi
Registration #15	2016-03-30	116.268 mi
Registration #16	2016-03-30	116.268 mi
Registration #17	2016-03-30	116.268 mi
Registration #18	2016-03-30	116.268 mi
Registration #19	2016-03-30	116.268 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1452 mm
Length	4514 mm
Wheel base	2640 mm
Kerb weight	1489 kg
Max. allowed weight	1960 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Engine number	7926
---------------	------