



report date: 2024-03-29

General information

Make	VOLVO
Model	C30 D SE SPORT
Colour	Blue
Year of manufacture	2007
Top speed	130 mph
0 - 60 mph	8.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	61.4 mpg
Consumption combined	49.6 mpg
CO2 emission	151 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-07-15
Pictures	4
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2022-08-18
MOT pass rate	67 %
MOT passed	12
Failed MOT tests	6
Total advice items	46
Total items failed	10

MOT #182021-08-19 15:48

MOT test number533721897175

Result✓ Passed

Next expiry date2022-08-18

- Advice

Central Front Lower Oil leak, but not excessive (8.4.1 (a) (i))
- Advice

Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice

Offside Front wheel binding slightly
- Advice

Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice

Central Front Lower Engine mounting damaged but not to excess (6.1.8 (a) (i))
- Advice

Central Front Lower Steering rack has slight free play detected at steering wheel (2.3 (a) (i))
- Advice

Nearside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))
- Advice

Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #17** 2021-08-19 15:48**MOT test number** 425368652339**Result** ✗ Failed

- Advice** Central Front Lower Engine mounting damaged but not to excess (6.1.8 (a) (i))
- Advice** Central Front Lower Steering rack has slight free play detected at steering wheel (2.3 (a) (i))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))
- Advice** Offside Front wheel binding slightly
- Advice** Central Front Lower Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- Pass with rectification** Supplementary restraint system warning lamp indicates a fault reset airbag lamp (7.1.6 (a))

MOT #16 2020-07-28 12:33**MOT test number** 547695183860**Result** ✓ Passed

- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #15 2020-07-20 09:51**MOT test number** 867006860979**Result** ✗ Failed

- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Offside Front Road wheel fixing missing (5.2.1 (a) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #14**

2019-07-08 14:04

MOT test number

336452219632

Result

✓ Passed

Advice Nearside Front Lower Suspension rod pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Offside Front Lower Suspension rod pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #13

2018-07-23 15:54

MOT test number

102417723452

Result

✓ Passed

Advice Oil leak, but not excessive (8.4.1 (a) (i))

MOT #12

2018-07-16 16:09

MOT test number

182701924592

Result

✗ Failed

Fail Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

Fail Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Fail Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #11

2017-07-17 14:32

MOT test number

284025628508

Result

✓ Passed

Advice Nearside Front Tyre wearing on inner edge

**MOT #10** 2017-07-17 08:59**MOT test number** 834190906640**Result** ✗ Failed**Advice** Nearside Front Tyre wearing on inner edge**Fail** Nearside Front coil spring broken (2.4.C.1a)**MOT #9** 2016-07-12 15:36**MOT test number** 965882031154**Result** ✓ Passed**MOT #8** 2015-06-19 09:36**MOT test number** 315630475101**Result** ✓ Passed**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)**Notice** O/s rear tyre cracking with age**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)

**MOT #7** 2015-06-19 09:36**MOT test number** 915750075137**Result** ✗ Failed**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**Notice** O/s rear tyre cracking with age**Pass with rectification** Nearside Headlamp not working on dipped beam (1.7.5a)**MOT #6** 2014-06-18 16:05**MOT test number** 388889364131**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Notice** Offside front side marker light not working**Notice** Rear exhaust box slightly deteriorated**MOT #5** 2014-06-18 10:21**MOT test number** 786059964163**Result** ✗ Failed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Notice** Offside front side marker light not working**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Notice** Rear exhaust box slightly deteriorated

**MOT #4** 2013-06-26 09:19**MOT test number** 139327973129**Result** ✓ Passed**Notice** Centre exhaust in poor condition**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #3** 2012-06-26 11:22**MOT test number** 246458872455**Result** ✓ Passed**MOT #2** 2011-06-03 17:12**MOT test number** 217604951449**Result** ✓ Passed**Advice** Centre Exhaust has part of the system slightly deteriorated (7.1.1a)**MOT #1** 2010-06-19 10:42**MOT test number** 631700270190**Result** ✓ Passed**Notice** Small cut in n/s/r tyre sidewall**Notice** Nail in offside front tyre



Tax & MOT check

✕
Untaxed

Tax expired:
1 February 2022

✕
MOT

Expired:
18 August 2022

Tax status	Expired at 1 February 2022
Days left	819 days too late
MOT expiry date	18 August 2022
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	AR07RKV
Plate since	2019-03-29
Current registration	AR07RKV
Plate since	2019-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-06-28
Last registration	2021-08-19
Complete history	See info



Registration #1	2007-06-28	20 mi
Registration #2	2010-06-19	18.309 mi
Registration #3	2011-06-03	26.701 mi
Registration #4	2012-06-26	36.610 mi
Registration #5	2013-06-26	55.297 mi
Registration #6	2014-06-18	73.737 mi
Registration #7	2014-06-18	73.737 mi
Registration #8	2015-06-19	90.805 mi
Registration #9	2016-07-12	108.268 mi
Registration #10	2017-07-17	115.486 mi
Registration #11	2018-06-20	121.277 mi
Registration #12	2019-06-20	121.277 mi
Registration #13	2020-06-20	121.277 mi
Registration #14	2021-06-20	121.277 mi
Registration #15	2022-06-20	121.277 mi
Registration #16	2023-06-20	121.277 mi
Registration #17	2024-06-20	121.277 mi
Registration #18	2025-06-20	121.277 mi
Registration #19	2026-06-20	121.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4252 mm
Wheel base	2640 mm
Kerb weight	1414 kg
Max. allowed weight	1840 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	58970