



report date: 2024-03-29

General information

Make	CITROEN
Model	DS3 E-HDI DSTYLE PLUS
Colour	Purple
Year of manufacture	2015
Top speed	113 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	230 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	64.2 mpg
Consumption extra urban	85.6 mpg
Consumption combined	76.4 mpg
CO2 emission	95 g/km
CO2 label	A





Internet history

Entry 1

Date	2022-03-04
Pictures	21
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-02-23
MOT pass rate	64 %
MOT passed	7
Failed MOT tests	4
Total advice items	40
Total items failed	5

MOT #11	2024-02-16 15:44
MOT test number	243899669693
Result	✓ Passed
Next expiry date	2025-02-23
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened Corroded (1.1.14 (a) (ii))
Advice	Front Exhaust mounting defective (6.1.2 (a))
Minor	Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Corrosion to rear axle

MOT #10	2024-02-16 12:52
MOT test number	218571206527
Result	✗ Failed
Fail	Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt Insecure (6.1.7 (g) (ii))
Advice	TPMS light on
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened Corroded (1.1.14 (a) (ii))
Advice	Front Exhaust mounting defective (6.1.2 (a))
Advice	Corrosion to rear axle
Minor	Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**MOT #9** 2023-02-01 14:10**MOT test number** 452224296518**Result** ✓ Passed

Minor Nearside Front Outer Anti-roll bar linkage ball joint dust cover severely deteriorated Upper (5.3.4 (b) (i))

Advice Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

Advice Nearside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

MOT #8 2023-02-01 11:50**MOT test number** 639276667390**Result** ✗ Failed

Advice Nearside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

Fail Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Fail Offside Front Direction indicator incorrect colour (4.4.3 (a))

Minor Nearside Front Outer Anti-roll bar linkage ball joint dust cover severely deteriorated Upper (5.3.4 (b) (i))

Advice Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

MOT #7 2022-02-24 12:10**MOT test number** 871276182873**Result** ✓ Passed**MOT #6** 2021-03-24 11:10**MOT test number** 619258609213**Result** ✓ Passed

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #5**

2020-03-26 16:55

MOT test number

347844124171

Result

✓ Passed

- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Rear exhaust hanger broken
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 3.00mm (5.2.3 (e))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #4

2020-03-26 14:40

MOT test number

552949958789

Result

✗ Failed

- Advice** Rear exhaust hanger broken
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 3.00mm (5.2.3 (e))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #3**

2019-03-28 13:11

MOT test number

689529425105

Result

✓ Passed

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge 3.00mm (5.2.3 (e))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 3.00mm (5.2.3 (e))
- Advice** Rear Inner exhaust hanger broken
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #2

2019-03-28 11:45

MOT test number

140328924616

Result

✗ Failed

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 3.00mm (5.2.3 (e))
- Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge 3.00mm (5.2.3 (e))
- Advice** Rear Inner exhaust hanger broken

MOT #1

2018-03-09 12:35

MOT test number

319544324177

Result

✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit and worn on inside edge (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
23 February 2025

Tax status	Valid until 1 March
Days left	305
MOT expiry date	23 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,000
Auction value	£ 15,000
Average private trade value	£ 15,000

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	SV15YUT
Plate since	2015-05-29
Current registration	SV15YUT
Plate since	2015-05-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2015-03-31
Last registration	2024-02-16
Complete history	See info



Registration #1	2015-03-31	24 mi
Registration #2	2018-03-09	21.661 mi
Registration #3	2019-03-28	31.815 mi
Registration #4	2019-03-28	31.815 mi
Registration #5	2020-03-26	41.719 mi
Registration #6	2020-03-26	41.719 mi
Registration #7	2021-03-24	46.835 mi
Registration #8	2022-03-22	51.951 mi
Registration #9	2022-03-22	51.951 mi
Registration #10	2023-03-20	57.067 mi
Registration #11	2023-03-20	57.067 mi
Registration #12	2024-02-16	62.183 mi
Registration #13	2024-02-16	62.183 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	71%
Pedestrian	35%
Safety systems	83%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1728 mm
Height	1524 mm
Length	3941 mm
Wheel base	2464 mm
Kerb weight	1085 kg
Max. allowed weight	1602 kg

Additional information

Fuel tank capacity	48 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number	JBFM0184699