



report date: 2024-03-29

General information

|                     |                         |
|---------------------|-------------------------|
| Make                | KIA                     |
| Model               | CEED CRDI 2 ECODYNAMICS |
| Colour              | Blue                    |
| Year of manufacture | 2014                    |
| Top speed           | 122 mph                 |
| 0 - 60 mph          | 11.5 seconds            |
| Gearbox             | 6 speed Manual          |

Engine & fuel consumption

|                         |                     |
|-------------------------|---------------------|
| Power                   | 126 BHP             |
| Max. torque             | 260 Nm at 2.750 rpm |
| Engine capacity         | 1.582 cc            |
| Cylinders               | 4                   |
| Fuel type               | Diesel              |
| Consumption city        | 67.3 mpg            |
| Consumption extra urban | 78.5 mpg            |
| Consumption combined    | 74.3 mpg            |
| CO2 emission            | 100 g/km            |
| CO2 label               | A                   |





MOT history

|                    |            |
|--------------------|------------|
| MOT expiry date    | 2024-11-28 |
| MOT pass rate      | 64 %       |
| MOT passed         | 7          |
| Failed MOT tests   | 4          |
| Total advice items | 13         |
| Total items failed | 11         |

|                  |   |
|------------------|---|
| MOT #11          | 2023-11-28 16:51  |
| MOT test number  | 444646726122  |
| Result           | ✓ Passed  |
| Next expiry date | 2024-11-28  |
| Advice           | Offside Rear Suspension rod pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))  |
| Minor            | Offside Rear Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))        |
| Advice           | Nearside Rear Suspension rod pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) |
| Minor            | Nearside Rear Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))       |

|                 |  |
|-----------------|--|
| MOT #10         | 2022-11-28 15:18   |
| MOT test number | 992797324916   |
| Result          | ✓ Passed   |
| Advice          | Offside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))  |
| Advice          | Nearside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) |

**MOT #9** 2022-11-25 14:30**MOT test number** 316038262500**Result** ✗ Failed

- Fail** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))
- Fail** Offside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))
- Advice** Offside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Fail** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Fail** Nearside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))
- Advice** Nearside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #8** 2021-11-25 12:09**MOT test number** 406391721126**Result** ✓ Passed

- Advice** Brake disc worn, pitted or scored, but not seriously weakened BOTH FRONT. (1.1.14 (a) (ii))
- Advice** Offside Rear Suspension rod pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Brake disc worn, pitted or scored, but not seriously weakened BOTH REAR. (1.1.14 (a) (ii))

**MOT #7** 2020-11-06 12:52**MOT test number** 898108740195**Result** ✓ Passed

**MOT #6** 2020-11-06 10:02**MOT test number** 772423305300**Result** ✗ Failed**Fail** Rear Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**MOT #5** 2019-11-19 13:39**MOT test number** 471505616678**Result** ✓ Passed**MOT #4** 2019-11-18 10:08**MOT test number** 688311127032**Result** ✗ Failed**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Fail** Offside Front Position lamp adversely affected by the operation of another lamp (4.2.3 (c))**MOT #3** 2018-11-22 10:57**MOT test number** 259158538376**Result** ✓ Passed**Advice** Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))**MOT #2** 2017-11-29 15:08**MOT test number** 253816999738**Result** ✓ Passed



|                 |   |
|-----------------|---|
| MOT #1          | 2017-11-22 15:13  |
| MOT test number | 326600254620  |
| Result          | ✗ Failed  |
| Advice          | Rear parking (secondary) brake grabbing slightly (3.7.B.6b) |
| Fail            | Front brake binding (3.7.B.1)                               |



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 April 2025

✓  
**MOT**  
**Expires:**  
28 November 2024

|                         |                                 |
|-------------------------|---------------------------------|
| <b>Tax status</b>       | Valid until 1 April             |
| <b>Days left</b>        | 336                             |
| <b>MOT expiry date</b>  | 28 November 2024                |
| <b>Full MOT history</b> | <a href="#">See MOT history</a> |

Tax calculation

|  |                |
|--|----------------|
| <b>Vehicle class</b>                           | 49             |
| <b>Band</b>                                    | A              |
| <b>Single payment (12 months)</b>              | £ 0,00,-       |
| <b>Single six month payment</b>                | Not applicable |
| <b>Total payable by 12 monthly instalments</b> | Not applicable |



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |

Damage 2

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

|                             |          |
|-----------------------------|----------|
| Trade retail value          | £ 19,999 |
| Auction value               | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >





Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

|       |       |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this KIA had different number plates.

|                      |                |
|----------------------|----------------|
| Number of plates     | 1              |
| Current registration | <b>ST64FYK</b> |
| Plate since          | 2024-03-29     |
| Current registration | <b>ST64FYK</b> |
| Plate since          | 2024-03-29     |

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

|                   |            |      |
|-------------------|------------|------|
| Finance company   | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type    | XXXXXXXXXX | XXXX |
| Agreement term    | XXXXXXXXXX | XXXX |
| Agreement number  | XXXXXXXXXX | XXXX |
| Contact info      | XXXXXXXXXX | XXXX |

More info >



Mileage check

|                            |                          |
|----------------------------|--------------------------|
| Odometer                   | In miles                 |
| Mileage registrations      | 12                       |
| First mileage registration | 2014-10-22               |
| Last registration          | 2023-11-28               |
| Complete history           | <a href="#">See info</a> |



|                  |            |           |
|------------------|------------|-----------|
| Registration #1  | 2014-10-22 | 27 mi     |
| Registration #2  | 2017-11-22 | 24.890 mi |
| Registration #3  | 2017-11-29 | 24.896 mi |
| Registration #4  | 2018-11-22 | 30.909 mi |
| Registration #5  | 2019-11-18 | 35.654 mi |
| Registration #6  | 2019-11-19 | 35.678 mi |
| Registration #7  | 2019-11-20 | 35.677 mi |
| Registration #8  | 2019-11-21 | 35.677 mi |
| Registration #9  | 2019-11-22 | 35.677 mi |
| Registration #10 | 2019-11-23 | 35.677 mi |
| Registration #11 | 2019-11-24 | 35.677 mi |
| Registration #12 | 2019-11-25 | 35.677 mi |

More info >



Car features

The KIA factory car options list is only available in the premium report.


|       |                  |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 |                  |
| S0482 |                  |
| S0501 |                  |
| S0566 |                  |
| S0567 |                  |
| S0569 |                  |

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

|                |                                 |
|----------------|---------------------------------|
| NCAP rating    | ★★★★★                           |
| Adult          | 89%                             |
| Children       | 88%                             |
| Pedestrian     | 61%                             |
| Safety systems | 86%                             |
| Overall rating | 83%                             |
| Video          | <a href="#">see crash video</a> |



Dimensions & weight

|                     |         |
|---------------------|---------|
| Width               | 1780 mm |
| Height              | 1470 mm |
| Length              | 4310 mm |
| Wheel base          | 2650 mm |
| Kerb weight         | 1499 kg |
| Max. allowed weight | 1810 kg |

Additional information

|                    |                  |
|--------------------|------------------|
| Fuel tank capacity | 53 l             |
| Fuel delivery      | Direct Injection |
| Number of doors    | 5                |
| Number of seats    | 5                |

|                        |              |
|------------------------|--------------|
| <b>Number of axles</b> | 2            |
| <b>Engine number</b>   | D4FBDZ562059 |