





report date: 2024-03-28

General information

Make	CITROEN
Model	DISPATCH 1200 L2H1 ENTERPRISE HDI
Colour	White
Year of manufacture	2014
Top speed	106 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	126 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.997 сс
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	48.7 mpg
Consumption combined	44.1 mpg
CO2 emission	168 g/km
CO2 label	Н



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 1

Date 2021-12-23

Pictures 8

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

MOT history

MOT expiry date	2024-11-07	
MOT pass rate	64 %	
MOT passed	7	
Failed MOT tests	4	
Total advice items	11	
Total items failed	11	

MOT #11		2023-10-30 15:16
MOT test	number	990071659824
Result		✓ Passed
Next exp	iry date	2024-11-07
Minor (b) (i))	Nearside Registration plate lamp inoperative in the case of multiple lamps or	r light sources (4.7.1
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14	(a) (ii))
Advice	Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))	

MOT #10		2022-10-27 15:27
MOT test	number	702123855955
Result		✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge inner and outer	r edges (5.2.3 (e))
Advice	Central Exhaust mounting defective hanger corroded from pipe (6.1.2 (a))
Advice	Steering column universal joint has slight wear or play (2.2.2 (c))	

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #9 2022-10-27 12:11

MOT test number 818887487421

Result X Failed

Advice Steering column universal joint has slight wear or play (2.2.2 (c))

Fail Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))

Fail Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

Advice Offside Front Tyre worn close to legal limit/worn on edge inner and outer edges (5.2.3 (e))

Advice Central Exhaust mounting defective hanger corroded from pipe (6.1.2 (a))

MOT #8 2021-11-01 12:32

MOT test number 847472433288

Result

Passed

MOT #7 2021-11-01 10:21

MOT test number 190623169948

Result X Failed

Fail Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

Fail Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Fail Offside Front Position lamp not working (4.2.1 (a) (ii))

Fail Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

Fail Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MOT #6 2020-11-03 15:43

MOT test number 220963198602

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #5 2019-11-06 12:20

MOT test number 516123896249

Result ✓ Passed

Advice Offside Rear Tyre worn close to legal limit/worn on edge close to legal limit (5.2.3 (e))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened both rear brake disc slightly corroded and scored but not excessive (1.1.14 (a) (ii))

MOT #4 2018-11-08 12:18

MOT test number 392429570265

Result \(\sqrt{Passed} \)

MOT #3 2018-11-08 12:18

MOT test number 775056109899

Result X Failed

Pass with rectification Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #2 2017-10-12 15:52

MOT test number 580256994947

Result ✓ Passed

MOT #1 2017-10-10 16:11

MOT test number 419041959156

Result X Failed

Fail Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Pass with rectification Upper Stop lamp not working (1.2.1b)

CarCheck.co.uk page 5/12



report date: 2024-03-28





Tax status	Valid until 1 January
Days left	248
MOT expiry date	7 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this CITROEN had different number plates. More info >		
See in this check if this CITROEN had different number plates.		
See in this check if this CITROEN had different number plates.		
See in this check if this CITROEN had different number plates.		
See in this check if this CITROEN had different number plates.		
See in this check if this CITROEN had different number plates.		
See in this check if this CITROEN had different number plates.	*********	
See in this check if this CITROEN had different number plates.		
See in this check if this CITROEN had different number plates.	***************************************	
See in this check if this CITROEN had different number plates.		More info >
器 UK UK	Plate changes	
THE REPORT OF THE PROPERTY OF	See in this check if this CITROEN had different number plates.	
THE REPORT OF THE PROPERTY OF	Number of plates	,
Plate since	Current registration	OK SIE
Plate since	Plate since	
More info >	Current registration	NK SIN
More info >	Plate since	
		More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2014-11-03
Last registration	2023-10-30
Complete history	See info



Registration #1	2014-11-03	8 mi
Registration #2	2017-10-10	26.299 mi
Registration #3	2017-10-12	26.294 mi
Registration #4	2018-11-08	35.786 mi
Registration #5	2018-11-08	35.786 mi
Registration #6	2019-11-06	41.918 mi
Registration #7	2020-11-03	49.215 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		10.777 es

More info >

CarCheck.co.uk page 11/12



PE64ZPT report date: 2024-03-28

		_	
- Duma	anciar	וכ ג.	Woldht
	-113101	אט כו	weight

Width	1895 mm
Height	1942 mm
Length	5135 mm
Wheel base	3120 mm
Kerb weight	1732 kg
Max. allowed weight	2932 kg

Additional information

Fuel tank capacity	80
Fuel delivery	Direct Injection
Number of seats	3
Number of axles	2
Engine number	DYZG4110977

CarCheck.co.uk page 12/12