





report date: 2024-03-28

### General information

Make	VOLKSWAGEN
Model	SCIROCCO GTD
Colour	Black
Year of manufacture	2010
Top speed	138 mph
0 - 60 mph	8.0 seconds
Gearbox	6 speed Manual

# Engine & fuel consumption

Power	170 BHP
Max. torque	350 Nm at 1.750 rpm
Engine capacity	1.968 сс
Cylinders	4
Fuel type	Diesel
Consumption city	40.4 mpg
Consumption extra urban	65.7 mpg
Consumption combined	53.3 mpg
CO2 emission	134 g/km
CO2 label	E



CarCheck.co.uk page 1/13



### Internet history

### Entry 2

Date 2021-06-17

Pictures 14

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 1

Date	2021-05-26	

Pictures 14

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2025-04-18
MOT pass rate	86 %
MOT passed	12
Failed MOT tests	2
Total advice items	23
Total items failed	3

MOT #14	2024-04-19 11:26
MOT test number	507602905891
Result	<b>✓</b> Passed
Next expiry date	2025-04-18
Advice Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))	

MOT #13		2024-04-19 11:26
MOT test number		681250087072
Result		<b>X</b> Failed
Pass with rectification	Nearside Front Road wheel fixing missing 1 (5.2.1 (a) (i))	
Pass with rectification	Offside Rear Road wheel fixing missing (5.2.1 (a) (i))	
Advice Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))		
Pass with rectification	Nearside Rear Road wheel fixing missing (5.2.1 (a) (i))	

MOT #12	2023-04-15 09:47
MOT test number	141773855087
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/13



MOT #11 2022-03-25 16:56

MOT test number 456586546603

**Result** ✓ Passed

**Advice** Front Tyre slightly damaged Both (5.2.3 (d) (ii))

**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #10** 2021-04-12 14:41

**MOT test number** 866302775743

**Result** 
✓ Passed

MOT #9 2021-04-06 11:53

**MOT test number** 690171956831

**Result** X Failed

**MAJOR** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MAJOR** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

MOT #8 2020-04-17 11:13

MOT test number 828224920272

**Result** ✓ Passed

**Advice** Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Minor Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

CarCheck.co.uk page 4/13



**LL10GBX** 

report date: 2024-03-28

MOT #7	2019-05-07 11:03	
MOT test number	156609557107	
Result	✓ Passed	
Advice Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))		
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Minor Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))		
Advice Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))		
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))		

MOT #6	2018-05-16 11:21
MOT test number	305295390729
Result	<b>✓</b> Passed
MOT #5	2017-05-18 15:24
MOT test number	957549998812
Result	<b>✓</b> Passed
MOT #4	2016-05-12 10:39
MOT test number	551000182338
Result	<b>✓</b> Passed

CarCheck.co.uk page 5/13



MOT #3 2015-05-07 15:06

**MOT test number** 218917225472

Result Passed

**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Notice** Under-trays fitted obscuring some underside components

**Notice** Emissions to clean for readings

**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Notice** Engine covers fitted obscuring some components in the engine bay

MOT #2 2014-06-28 12:44

**MOT test number** 526969674130

**Result** ✓ Passed

**MOT #1** 2013-06-22 11:46

**MOT test number** 375493073135

Result \rightarrow Passed

CarCheck.co.uk page 6/13



### Tax & MOT check



Tax status	Valid until 1 March
Days left	306
MOT expiry date	18 April 2025
Full MOT history	See MOT history

### Tax calculation

Vehicle class	49
Band	Е
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 7/13



### Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <a href="here">here</a> for the results.

#### Damage 1

Date	
Category	
Туре	

#### Damage 2

Date	
Category	

**Type** 



#### Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



### Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

Owner history	
For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dow here.	
*********	
***************************************	
***************************************	
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
***************************************	
	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	UK NEW YORK
Plate since	
	More info >

CarCheck.co.uk page 10/13



### Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

**Contact info** 

More info >

CarCheck.co.uk page 11/13



# Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-06-16
Last registration	2024-04-19
Complete history	See info



Registration #1	2010-06-16	16 mi
Registration #2	2013-06-22	39.929 mi
Registration #3	2014-06-28	52.448 mi
Registration #4	2015-05-07	64.111 mi
Registration #5	2016-05-12	82.434 mi
Registration #6	2017-05-18	101.881 mi
Registration #7	2018-05-16	123.698 mi
Registration #8	2019-05-07	139.701 mi
Registration #9	2020-04-17	152.167 mi
Registration #10		71.777 es
Registration #11		9.700 es
Registration #12		11.777 es
Registration #13		9.70 es
Registration #14		11.777 es
Registration #15		9.70 es
Registration #16		11.777 es
Registration #17		11.117 es

More info >

CarCheck.co.uk page 12/13



### Car features

50225	Air conditionir
50295	
50482	
60501	
60566	
0567	
60569	

# Safety ratings

NCAP rating	****
Adult	97%
Children	84%
Pedestrian	61%
Safety systems	71%
Overall rating	85%
Video	see crash video



# Dimensions & weight

Width	1786 mm
Height	1479 mm
Length	4199 mm
Wheel base	2578 mm
Kerb weight	1299 kg
Max. allowed weight	1890 kg

# Additional information

Fuel tank capacity	55 I
Fuel delivery	Direct Injection
Number of doors	5
CarChock co.uk	pago 13/13

CarCheck.co.uk page 13/13

Number of seats	5
Number of axles	2
Engine number	CFG 121854