



report date: 2024-03-28

General information

Make	VOLVO
Model	S40 S S40
Colour	Grey
Year of manufacture	2007
Top speed	115 mph
0 - 60 mph	11.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	150 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.7 mpg
Consumption extra urban	48.7 mpg
Consumption combined	39.8 mpg
CO2 emission	171 g/km
CO2 label	H





Internet history

Entry 1

Date	2022-06-27
Pictures	31
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-06-30
MOT pass rate	67 %
MOT passed	14
Failed MOT tests	7
Total advice items	25
Total items failed	13

MOT #21	2023-06-28 08:57
MOT test number	415836132737
Result	✓ Passed
Next expiry date	2024-06-30

MOT #20	2022-07-01 15:57
MOT test number	370146058046
Result	✓ Passed

MOT #19	2021-10-21 08:00
MOT test number	833178216360
Result	✓ Passed

- Advice** Brake fluid close to minimum mark (1.1.10 (d) (ii))
- Advice** Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Rear reverse lights not working

**MOT #18**

2020-10-30 07:52

MOT test number

554290682052

Result

✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #17**

2020-10-29 15:43

MOT test number

280019528731

Result

✗ Failed

Advice Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Offside Front Bumper damaged and likely to cause injury when grazed or contacted (6.1.4 (a) (i))**Fail** Offside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Rear Bumper damaged and likely to cause injury when grazed or contacted (6.1.4 (a) (i))**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Nearside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))**MOT #16**

2019-11-04 12:58

MOT test number

724476315573

Result

✓ Passed

Advice Rear Exhaust mounting defective (6.1.2 (a))**Advice** Nearside Rear tyre has a screw in tread.

**MOT #15** 2018-10-29 12:43**MOT test number** 508021212456**Result** ✓ Passed**Advice** Front bumper has damage**Advice** Offside Front Tyre worn close to legal limit/worn on edge Valve is perished (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge Valve is perished (5.2.3 (e))**Advice** Rear bumper has damage**MOT #14** 2017-11-04 12:16**MOT test number** 282717718430**Result** ✓ Passed**MOT #13** 2017-10-24 13:58**MOT test number** 639011548003**Result** ✗ Failed**Fail** Offside Front Front suspension has excessive movement at a suspension ball joint bottom ball joint (2.5.A.1c)**Fail** Offside Rear Direction indicator incorrect colour (1.4.A.2f)**Fail** Nearside Front Front suspension ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt bottom arm ball joint (2.4.G.2)**Fail** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)**MOT #12** 2016-11-05 12:10**MOT test number** 249239458015**Result** ✓ Passed**MOT #11** 2016-11-05 12:10**MOT test number** 214218833325**Result** ✗ Failed**Pass with rectification** Nearside Headlamp not working on dipped beam (1.7.5a)

**MOT #10** 2015-11-07 14:45**MOT test number** 244749647487**Result** ✓ Passed

- Advice** Rear Direction indicator slightly discoloured (1.4.A.2f)
- Advice** Offside Front Lower Suspension arm has slight play in a pin/bush (2.4.G.2)
- Advice** Nearside Front Lower Suspension arm has slight play in a pin/bush (2.4.G.2)

MOT #9 2015-11-07 14:45**MOT test number** 774147297015**Result** ✗ Failed

- Advice** Rear Direction indicator slightly discoloured (1.4.A.2f)
- Advice** Offside Front Lower Suspension arm has slight play in a pin/bush (2.4.G.2)
- Pass with rectification** Offside Headlamp not working on dipped beam (1.7.5a)
- Advice** Nearside Front Lower Suspension arm has slight play in a pin/bush (2.4.G.2)

MOT #8 2014-12-02 17:43**MOT test number** 648096534304**Result** ✓ Passed**MOT #7** 2014-12-02 17:43**MOT test number** 405636334460**Result** ✗ Failed

- Pass with rectification** Offside Front Headlamp not working on main beam (1.7.5a)

MOT #6 2013-12-09 13:58**MOT test number** 216793743365**Result** ✓ Passed

**MOT #5** 2013-12-09 13:58**MOT test number** 217883743373**Result** ✗ Failed**Pass with rectification** Nearside Front Front constant velocity joint is insecure (2.5.C.1b)**MOT #4** 2012-11-30 11:25**MOT test number** 725305532316**Result** ✓ Passed**MOT #3** 2011-10-24 10:38**MOT test number** 256797491266**Result** ✓ Passed**MOT #2** 2010-10-12 14:17**MOT test number** 253555080247**Result** ✓ Passed**Notice** X2 child seats fitted to rear or vehicle.**MOT #1** 2010-10-12 13:31**MOT test number** 101245680270**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** X2 child seats fitted to rear or vehicle.**Fail** Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
30 June 2024

Tax status	Valid until 1 August
Days left	94
MOT expiry date	30 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2007-10-17
Last registration	2023-06-28
Complete history	See info



Registration #1	2007-10-17	17 mi
Registration #2	2010-10-12	17.244 mi
Registration #3	2010-10-12	17.244 mi
Registration #4	2011-10-24	22.788 mi
Registration #5	2012-11-30	27.645 mi
Registration #6	2013-12-09	32.485 mi
Registration #7	2014-12-02	36.042 mi
Registration #8	2015-11-07	39.847 mi
Registration #9	2015-11-07	39.847 mi
Registration #10	2016-11-05	43.925 mi
Registration #11	2016-11-05	43.925 mi
Registration #12	2016-11-05	43.925 mi
Registration #13	2016-11-05	43.925 mi
Registration #14	2016-11-05	43.925 mi
Registration #15	2016-11-05	43.925 mi
Registration #16	2016-11-05	43.925 mi
Registration #17	2016-11-05	43.925 mi
Registration #18	2016-11-05	43.925 mi
Registration #19	2016-11-05	43.925 mi
Registration #20	2016-11-05	43.925 mi
Registration #21	2016-11-05	43.925 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1454 mm
Length	4476 mm
Wheel base	2640 mm
Kerb weight	1322 kg
Max. allowed weight	1800 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5

Engine number	63117
---------------	-------