





General information

Make	LAND ROVER
Model	RANGE ROVER SPORT SDV6 HSE
Colour	White
Year of manufacture	2016
Top speed	130 mph
0 - 100 km/h	7.2 seconds
Gearbox	8 speed automatic

Engine & fuel consumption

Power	225 kW / 306 HP / 306 BHP
Max. torque	700 Nm at 1.500 rpm
Engine capacity	2.993 cc
Cylinders	6
Fuel type	Diesel
Consumption city	35.8 mpg
Consumption extra urban	44.1 mpg
Consumption combined	40.4 mpg
CO2 emission	185 g/km
CO2 label	





Internet history

Entry 1

Date Pictures 2021-12-16

28

Listing price

View report









source: autotrader.co.uk



MOT history

MOT expiry date	2024-12-12
MOT pass rate	56 %
MOT passed	5
Failed MOT tests	4
Total advice items	12
Total items failed	12

MOT #9		2023-12-07 12:29
MOT test	number	381437976745
Result		🗸 Passed
Next expiry date 2024-12		2024-12-12
Advice Nearside Rear Outer Drive shaft joint boot leaking grease slightly		
Advice Offside Rear Tyre has a cut but not deep enough to reach the ply or cords + nail (5.2.3 (d) (i))		+ nail (5.2.3 (d) (i))

MOT #8	2023-12-06 11:02	
MOT test number	171394378461	
Result	🗙 Failed	
Fail Offside Front Tyre has a cut in excess of the requirements deep enough to reach the 1.6mm (5.2.3 (d) (i))	ply or cords +	
Fail Offside Front Lower Suspension arm ball joint dust cover no longer prevents the ingreating arm (5.3.4 (b) (ii))	ess of dirt front	
Fail Nearside Front Lower Suspension arm ball joint dust cover no longer prevents the ing arm (5.3.4 (b) (ii))	ress of dirt rear	
FailNearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords(5.2.3 (d) (i))		
Fail Offside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt rear arm (5.3.4 (b) (ii))		
Advice Nearside Rear Outer Drive shaft joint boot leaking grease slightly		
Advice Offside Rear Tyre has a cut but not deep enough to reach the ply or cords + nail (5.2.3 (d) (i))	



PB	11	G	Η	B
repo	ort dat	e: 20	24-0	3-29

MOT #7	2022-12-06 10:00	
MOT test number	273122828159	
Result	✓ Passed	
MOT #6	2022-12-05 14:59	
MOT test number	819562530823	
Result	🗙 Failed	
FailNearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords(5.2.3 (d) (i))		
Fail Offside Front Suspension arm ball joint dust cover no longer prevents the in	ngress of dirt (5.3.4 (b) (ii))	
MOT #5	2021-12-13 15:25	

MOT test number	112355251450
Result	✓ Passed

МОТ #4	2021-06-15 09:53
MOT test number	871665563647
Result	✓ Passed

MOT #3	2021-06-14 10:50
MOT test number	166384481641
Result	🗙 Failed
Fail Nearside Rear Brake pipe excessively corroded flexi (1.1.11 (c))	
Fail Offside Rear Brake pipe excessively corroded flexi (1.1.11 (c))	





MOT #2		2021-01-13 11:48
MOT test	number	124682166178
Result		✓ Passed
Advice	Offside Rear Brake pipe corroded, covered in grease or other material flex	ki (1.1.11 (c))
Advice (d) (i))	Nearside Rear Tyre has a cut but not deep enough to reach the ply or cor	ds outer sidewall (5.2.3
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material fl	exi (1.1.11 (c))
Advice (d) (i))	Nearside Front Tyre has a cut but not deep enough to reach the ply or con	rds outer sidewall (5.2.3

MOT #1	2021-01-13 09:39	
MOT test number	506646290792	
Result	🗙 Failed	
Advice Offside Rear Brake pipe corroded, covered in grease or other	material flexi (1.1.11 (c))	
Advice Nearside Rear Tyre has a cut but not deep enough to reach t (d) (i))	he ply or cords outer sidewall (5.2.3	
Fail Nearside Windscreen wiper does not clear the windscreen effect	cively (3.4 (b) (ii))	
Advice Nearside Rear Brake pipe corroded, covered in grease or other material flexi (1.1.11 (c))		
Advice Nearside Front Tyre has a cut but not deep enough to reach the ply or cords outer sidewall (5.2.3 (d) (i))		
Pass with rectification Windscreen washer provides insufficient washer	asher liquid (3.5 (a))	
Fail Offside Windscreen wiper does not clear the windscreen effective	rely (3.4 (b) (ii))	



Tax & MOT check

✓ Taxed Tax due: 1 December 2024	✓ MOT Expires: 12 December 2024
Tax status	Valid until 1 December
Days left	215
MOT expiry date	12 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-





Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPLE
Date	
Category	AMPL
Туре	

Extra LAND ROVER salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200





Owner history

For how long did the current and previous owner(s) have this LAND ROVER? How many owners did this LAND ROVER have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this LAND ROVER had different numb	er plates.

Number of plates	
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this LAND ROVER is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	



PB11GHB report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2016-09-02
Last registration	2023-12-07
Complete history	See info



Registration #1	2016-09-02	19 mi
Registration #2	2021-01-13	38.096 mi
Registration #3	2021-01-13	38.096 mi
Registration #4	2021-06-14	40.525 mi
Registration #5	2021-06-15	40.525 mi
Registration #6	2021-12-13	46.889 mi
Registration #7		11.717 est
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi





Safety ratings

NCAP rating	****
Adult	91%
Children	84%
Pedestrian	63%
Safety systems	86%
Overall rating	84%
Video	see crash video



Dimensions & weight	
Width	2220 mm
Height	1801 mm
Length	4856 mm
Wheel base	2923 mm
Kerb weight	2115 kg
Max. allowed weight	3050 kg
Additional information	
Additional information Fuel tank capacity	89 I
	89 l Direct Injection
Fuel tank capacity	
Fuel tank capacity Fuel delivery	Direct Injection
Fuel tank capacity Fuel delivery Number of doors	Direct Injection 5