

Ford



General information

Make	FORD
Model	TOURNEO CONNECT GRAND ZETEC TDCI
Colour	Silver
Year of manufacture	2015
Top speed	103 mph
0 - 60 mph	14.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	50.4 mpg
Consumption extra urban	61.4 mpg
Consumption combined	58.9 mpg
CO2 emission	130 g/km
CO2 label	D





Internet history

Entry 1	
Date	2021-01-30
Pictures	10
Listing price	View report



source: autoonline.co.uk



MOT history

MOT expiry date	2024-11-28
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	20
Total items failed	0

MOT #9		2023-11-22 15:09
MOT test nu	umber	997220523115
Result		✓ Passed
Next expiry	v date	2024-11-28
Advice	Offside Rear Service brake fluctuating, but not excessively (1.2.1 (e))	
Advice	Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e))	

МОТ #8	2022-11-17 16:16
MOT test number	314883210895
Result	✓ Passed
Advice Front Oil leak, but not excessive (8.4.1 (a) (i))	

MOT #7		2022-11-15 15:56
MOT test	number	647274216803
Result		× Failed
MAJOR	Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))	
MAJOR	Nearside Rear Position lamp not working (4.2.1 (a) (ii))	
Advice	Front Oil leak, but not excessive (8.4.1 (a) (i))	



MOT #6		2021-11-29 15:27
MOT test	number	950112971232
Result		✓ Passed
Advice	Nearside Front Inner wheel repaired	
Advice	Nearside Rear Inner wheel repaired	
Advice	Offside Rear Outer Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))	
Advice	Offside Front Inner wheel repaired	
Advice	Offside Rear Inner wheel repaired	

MOT #5		2021-11-29 14:24
MOT test	number	948025535845
Result		🗙 Failed
MAJOR ingress of	Nearside Outer Drive shaft joint constant velocity boot split or insecure, no long dirt (6.1.7 (g) (ii))	er prevents the
Advice	Offside Rear Outer Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))	
Advice	Offside Front Inner wheel repaired	
Advice	Offside Rear Inner wheel repaired	
MAJOR	Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	
Advice	Nearside Front Inner wheel repaired	
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1	.1.14 (a) (ii))
Advice	Nearside Rear Inner wheel repaired	

МОТ #4	2020-08-26 14:12
MOT test number	112114560715
Result	✓ Passed

LM15ABZ

report date: 2024-03-28





MOT #3	2019-08-29 13:42
MOT test number	376047450732
Result	Passed
MOT #2	2018-11-29 14:37
MOT test number	990129849058
Result	Passed
MOT #1	2018-11-29 14:36
MOT test number	867274799999
Result	🗙 Failed
MAJOR Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)))



Tax & MOT check

√ Taxed	✓ MOT
Tax due: 1 March 2025	Expires: 28 November 2024
Tax status	Valid until 1 March
Days left	306
MOT expiry date	28 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-





Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FER I
Category	 A PLANE
Туре	
Damage 2	AMPLE
Damage 2	E Stand
Date	*
Category	 ante.
Туре	

Extra FORD salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200





Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	





Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-04-28
Last registration	2023-11-22
Complete history	See info



Registration #1	2015-04-28	18 mi
Registration #2	2018-11-29	58.488 mi
Registration #3	2018-11-29	58.488 mi
Registration #4	2019-08-29	64.353 mi
Registration #5	2020-08-26	68.943 mi
Registration #6		11.117 esi
Registration #7		11.777 mi
Registration #8		11.777 mi
Registration #9		11.777 mi
Registration #10		11.777 mi
Registration #11		11.777 mi





Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	94%
Children	85%
Pedestrian	62%
Safety systems	70%
Overall rating	83%
Video	<u>see crash video</u>



Dimensions & weight	
Width	1835 mm
Height	1861 mm
Length	4818 mm
Kerb weight	1517 kg
Max. allowed weight	2315 kg

Additional information

Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats	7	
Number of axles	2	
Engine number Carcheck.co.uk	FL06737	page 12/12