






report date: 2024-03-29

## General information

Make	PEUGEOT
Model	107 URBAN
Colour	Silver
Year of manufacture	2007
Top speed	100 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	67 BHP
Max. torque	93 Nm at 3.600 rpm
Engine capacity	998 сс
Cylinders	3
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	68.9 mpg
Consumption combined	61.4 mpg
CO2 emission	109 g/km
CO2 label	В



CarCheck.co.uk page 1/13



report date: 2024-03-29

Internet history

Entry 1

Date 2021-05-24

Pictures 1

Listing price <u>View report</u>



source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

	_				
11/1/	TC	n		$\overline{}$	r\/
IVIL	, ,		51	LU.	ıv
					. ,

MOT expiry date	2025-02-22
MOT pass rate	79 %
MOT passed	15
Failed MOT tests	4
Total advice items	17
Total items failed	5

MOT #19	2024-02-23 15:48
MOT test number	217077569147
Result	✓ Passed
Next expiry date	2025-02-22

MOT #	18	2024-02-23 10:39
MOT to	est number	761834258985
Result		<b>×</b> Failed
Fail	Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.	1 (b) (ii))
Fail	Front Brake disc significantly and obviously worn (1.1.14 (a) (i))	

MOT #17		2023-07-04 10:04
MOT test	number	308072767275
Result		✓ Passed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a)	(ii))

MOT #16	2022-06-21 13:13
MOT test number	522136991521
Result	✓ Passed
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

CarCheck.co.uk page 3/13



report date: 2024-03-29

**MOT #15** 2022-06-21 08:37

**MOT test number** 901280583105

**Result** X Failed

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Fail Rear Service brake imbalanced across an axle (1.2.1 (b) (i))

**MOT #14** 2021-07-06 08:55

**MOT test number** 905394385716

**Result** ✓ Passed

MOT #13 2021-07-06 08:55

**MOT test number** 173203235712

**Result** X Failed

**Pass with rectification** Nearside Headlamp aim too high (4.1.2 (a))

**MOT #12** 2020-10-12 08:14

MOT test number 839600364197

Result \( \sqrt{Passed} \)

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor Windscreen wiper blade defective (3.4 (b) (i))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #11** 2019-10-14 08:26

MOT test number 332693980597

**Result** 
✓ Passed

**Advice** Offside Front Brake drum worn, pitted or scored, but not seriously weakened Inner face corroded and in poor condition (1.1.14 (a) (ii))

**Advice** Nearside Front Brake drum worn, pitted or scored, but not seriously weakened Inner face corroded and in poor condition (1.1.14 (a) (ii))

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT #10 2018-10-11 09:32

**MOT test number** 130828237424

MOT #9 2017-10-20 09:42

**MOT test number** 338954462264

Result 

Passed

**Advice** N/s/r tyre worn on outer edge

Advice Front Inner brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #8 2016-10-21 09:39

**MOT test number** 443184296986

Result \rightarrow Passed

**MOT #7** 2015-10-16 08:41

**MOT test number** 782393161491

Result \( \sqrt{Passed} \)

**Advice** Nearside Front Tyre worn close to the legal limit 2mm (4.1.E.1)

Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened Pitted inner edge

(3.5.1i)

**Advice** Both rear tyres slight perished and cracking

**Advice** Offside Front Tyre worn close to the legal limit 2mm (4.1.E.1)

**MOT #6** 2014-10-15 09:56

**MOT test number** 355608484227

**Result** ✓ Passed

**MOT #5** 2013-10-16 11:47

MOT test number 735129683237

CarCheck.co.uk page 5/13



report date: 2024-03-29

MOT #4 2012-10-23 10:24

**MOT test number** 515407192211

Result \( \sqrt{Passed} \)

MOT #3 2012-10-22 16:18

**MOT test number** 725576592239

**Result** X Failed

Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Fail** Indicator switch faulty (1.4.A.1)

**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #2 2011-11-07 11:50

**MOT test number** 887481311335

**Result** ✓ Passed

MOT #1 2010-11-25 12:01

MOT test number 214439720316

Result \( \sqrt{Passed} \)

CarCheck.co.uk page 6/13



report date: 2024-03-29

#### Tax & MOT check



Tax status	Valid until 1 March
Days left	307
MOT expiry date	22 February 2025
Full MOT history	See MOT history

## Tax calculation

Vehicle class	48
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 7/13



report date: 2024-03-29

#### Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

Owner	history
OWITCE	iliotoi y

For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	
***************************************	
*********	
************	
	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	,
Current registration	NK SIN
Flate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 10/13



KP57VMO report date: 2024-03-29

#### Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

## Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2007-11-29
Last registration	2024-02-23
Complete history	See info



Registration #1	2007-11-29	6 mi
Registration #2	2010-11-25	7.324 mi
Registration #3	2011-11-07	7.391 mi
Registration #4	2012-10-22	7.405 mi
Registration #5	2012-10-23	7.405 mi
Registration #6	2013-10-16	11.859 mi
Registration #7	2014-10-15	15.821 mi
Registration #8	2015-10-16	19.467 mi
Registration #9	2016-10-21	25.055 mi
Registration #10	2017-10-20	30.729 mi
Registration #11	2018-10-11	34.516 mi
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.777 es
Registration #21		11.777 esi

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-29

Car features

S0225	Air conditionin
S0295	
50482	
50501	
50566	
50567	
50569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1630 mm
Height	1465 mm
Length	3430 mm
Wheel base	2340 mm
Kerb weight	825 kg
Max. allowed weight	1190 kg

## Additional information

Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	4 page 13/1