




General information

Make	MINI
Model	COUNTRYMAN COOPER D ALL4 COOPER D ALL4
Colour	Blue
Year of manufacture	2012
Top speed	112 mph
0 - 60 mph	10.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	112 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption combined	64.2 mpg
CO2 emission	129 g/km
CO2 label	D








Internet history

Entry 1

Date	2021-06-06
Pictures	12
Listing price	View report



source: yesauto.com



MOT history

MOT expiry date	2025-04-29
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	24
Total items failed	7

MOT #14	2024-04-22 12:51
MOT test number	986930082209
Result	✓ Passed
Next expiry date	2025-04-29

MOT #13	2023-04-27 15:05
MOT test number	164761512535
Result	✓ Passed

MOT #12	2023-04-24 10:48
MOT test number	195845577465
Result	✗ Failed
Fail	Offside Headlamp aim too high (4.1.2 (a))
Fail	Nearside Front Position lamp not working (4.2.1 (a) (ii))
Fail	Bonnet primary retaining device ineffective (3.1 (c))

MOT #11	2022-04-30 10:24
MOT test number	839806954895
Result	✓ Passed

**MOT #10** 2021-04-29 11:51**MOT test number** 487591064273**Result** ✓ Passed**MOT #9** 2020-06-29 13:33**MOT test number** 927020457145**Result** ✓ Passed**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Engine covers & under trays fitted**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #8** 2020-06-29 10:52**MOT test number** 590659492960**Result** ✗ Failed**Fail** Front Registration plate does not conform to the specified requirements incorrect spacing (0.1 (d))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Engine covers & under trays fitted**Fail** Rear Registration plate does not conform to the specified requirements incorrect spacing (0.1 (d))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #7**

2019-06-25 13:25

MOT test number

863913015561

Result

✓ Passed

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))

Advice Offside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))

Advice Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Under guard trims fitted,poor visuelle

MOT #6

2019-06-25 09:19

MOT test number

698306312981

Result

✗ Failed

Advice Offside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))

Advice Under guard trims fitted,poor visuelle

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))

Advice Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))

**MOT #5** 2018-07-04 13:49**MOT test number** 605842941492**Result** ✓ Passed**Advice** Nearside Rear Nail in tyre**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Rear Nail in tyre**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #4** 2017-06-26 13:48**MOT test number** 512118063113**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2016-06-27 10:48**MOT test number** 587607113400**Result** ✓ Passed**MOT #2** 2015-04-16 18:28**MOT test number** 985396705123**Result** ✓ Passed**MOT #1** 2015-04-16 18:28**MOT test number** 665056405122**Result** ✗ Failed**Pass with rectification** Offside Rear Anti-roll bar rubber mounting deteriorated resulting in excessive movement (2.4.G.2)



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
29 April 2025

Tax status	Valid until 1 March
Days left	307
MOT expiry date	29 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXX	XXXXXX
XXXXXXXXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX
XXXXXX	XXXXXX
XXXXXXXXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	 XXXXX
Plate since	2019-09-29
Current registration	 XXXXX
Plate since	2019-09-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-04-16
Last registration	2024-04-22
Complete history	See info



Registration #1	2012-04-16	20 mi
Registration #2	2015-04-16	108.708 mi
Registration #3	2016-06-27	115.025 mi
Registration #4	2017-06-26	123.874 mi
Registration #5	2018-07-04	131.377 mi
Registration #6	2019-06-25	138.247 mi
Registration #7	2019-06-25	138.247 mi
Registration #8	2020-06-29	144.548 mi
Registration #9	2021-06-29	150.850 mi
Registration #10	2022-06-29	157.152 mi
Registration #11	2023-06-29	163.454 mi
Registration #12	2024-06-29	169.756 mi
Registration #13	2025-06-29	176.058 mi
Registration #14	2026-06-29	182.360 mi
Registration #15	2027-06-29	188.662 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1789 mm
Height	1577 mm
Length	4097 mm
Kerb weight	1380 kg
Max. allowed weight	1890 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	70338185