




report date: 2024-03-29

General information

| | |
|---------------------|---|
| Make | VAUXHALL |
| Model | VIVARO 2900 SPORTIVE S/S L2H1 2900 SPORTIVE S/S |
| Colour | White |
| Year of manufacture | 2020 |
| Top speed | 90 mph |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|----------------------|---------------------|
| Power | 101 BHP |
| Max. torque | 270 Nm at 1.600 rpm |
| Engine capacity | 1.499 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption combined | 38.2 mpg |
| CO2 emission | 181 g/km |
| CO2 label | I |





Internet history

Entry 2

| | |
|---------------|-----------------------------|
| Date | 2021-12-23 |
| Pictures | 0 |
| Listing price | View report |

source: cargurus.co.uk

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-12-23 |
| Pictures | 0 |
| Listing price | View report |

source: heycar.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-12-30 |
| MOT pass rate | 50 % |
| MOT passed | 1 |
| Failed MOT tests | 1 |
| Total advice items | 6 |
| Total items failed | 0 |

| | |
|------------------|--|
| MOT #2 | 2023-12-15 14:36 |
| MOT test number | 212536636945 |
| Result | ✓ Passed |
| Next expiry date | 2024-12-30 |
| Minor | Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) |
| Advice | Offside Rear Nail in tyre |
| Minor | Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i)) |

| | |
|-----------------|---|
| MOT #1 | 2023-12-15 14:24 |
| MOT test number | 951261794174 |
| Result | ✗ Failed |
| Minor | Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) |
| Minor | Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i)) |
| MAJOR | Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i)) |



Tax & MOT check

✓
Taxed

Tax due:
1 February 2025

✓
MOT

Expires:
30 December 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 February |
| Days left | 278 |
| MOT expiry date | 30 December 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|----------------------------------|------------|
| Vehicle class | 39 |
| Standard rate (12 months) | £ 320,00,- |
| Standard rate (6 months) | £ 176,00,- |



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

| | |
|----------------------|--|
| Number of plates | 1 |
| Current registration |  DP70ANX |
| Plate since | 2024-03-29 |
| Current registration |  DP70ANX |
| Plate since | 2024-03-29 |

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

| | | |
|-------------------|----------|------|
| Finance company | XXXXXXXX | XXXX |
| Date of agreement | XXXXXXXX | XXXX |
| Agreement type | XXXXXXXX | XXXX |
| Agreement term | XXXXXXXX | XXXX |
| Agreement number | XXXXXXXX | XXXX |
| Contact info | XXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 5 |
| First mileage registration | 2020-12-31 |
| Last registration | 2023-12-15 |
| Complete history | See info |



| | | |
|-----------------|------------|-----------|
| Registration #1 | 2020-12-31 | 29 mi |
| Registration #2 | 2020-12-31 | 29,277 mi |
| Registration #3 | 2020-12-31 | 29,277 mi |
| Registration #4 | 2020-12-31 | 29,277 mi |
| Registration #5 | 2020-12-31 | 29,277 mi |

More info >



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1920 mm |
| Height | 1935 mm |
| Length | 5309 mm |
| Kerb weight | 1770 kg |
| Max. allowed weight | 2830 kg |

Additional information

| | |
|-----------------|-------------------|
| Number of seats | 3 |
| Number of axles | 2 |
| Engine number | 10Q4DK0062195 O4B |