



report date: 2024-03-29

General information

Make	CITROEN
Model	XSARA VTX 16V PICASSO
Colour	Red
Year of manufacture	2007
Top speed	109 mph
0 - 60 mph	13.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	92 BHP
Max. torque	215 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	43.5 mpg
Consumption extra urban	65.7 mpg
Consumption combined	55.4 mpg
CO2 emission	135 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-01-29
Pictures	1
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2022-07-19
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	26
Total items failed	2

MOT #15	2021-07-20 10:57
MOT test number	104107691630
Result	✓ Passed
Next expiry date	2022-07-19

MOT #14	2020-06-24 15:28
MOT test number	459168534764
Result	✓ Passed
Advice	Nearside Front Direction indicator slightly discoloured (4.4.3 (a))
Advice	Fluid leak from injector
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Nearside Rear Outer Tyre worn close to legal limit/worn on edge worn (5.2.3 (e))

**MOT #13** 2020-06-23 09:55**MOT test number** 402105677970**Result** ✗ Failed**MAJOR** Nearside Front Anti-roll bar linkage ball joint excessively worn gaiter also split (5.3.4 (a) (i))**MAJOR** Windscreen damaged and affecting the driver's view of the road (3.2 (a) (ii))**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm 185.65.15 (5.2.3 (e))**MAJOR** Offside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Nearside Rear Outer Tyre worn close to legal limit/worn on edge worn (5.2.3 (e))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Fluid leak from injector**MAJOR** Front Registration plate does not conform to the specified requirements (0.1 (d))**MAJOR** Nearside Side repeater incorrect colour (4.4.3 (a))**DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Nearside Front Direction indicator slightly discoloured (4.4.3 (a))**MOT #12** 2019-07-06 13:30**MOT test number** 159658366225**Result** ✓ Passed**Advice** Nearside Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #11** 2018-07-10 13:30**MOT test number** 813938776691**Result** ✓ Passed**Advice** N/s/f tyre wearing (border line).. n/s/r tyre wearing close to legal limit (border line)

**MOT #10** 2017-06-26 11:10**MOT test number** 562654875675**Result** ✓ Passed**MOT #9** 2016-07-04 13:05**MOT test number** 148772465525**Result** ✓ Passed**Advice** Nail in offside rear tyre & slight side wall damage**MOT #8** 2016-07-04 09:23**MOT test number** 124777710152**Result** ✗ Failed**Fail** Nearside Headlamp not working on dipped beam (1.7.5a)**Advice** Nail in offside rear tyre & slight side wall damage**Advice** Nearside Side repeater slightly discoloured (1.4.A.2f)**MOT #7** 2015-06-16 12:30**MOT test number** 836087965147**Result** ✓ Passed**MOT #6** 2014-07-03 09:54**MOT test number** 246924884465**Result** ✓ Passed**MOT #5** 2014-07-03 09:54**MOT test number** 616254684156**Result** ✗ Failed**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)



MOT #4	2013-07-09 10:56
---------------	------------------

MOT test number	917830993108
------------------------	--------------

Result	✓ Passed
---------------	----------

Notice	Under-trays fitted obscuring some underside components
---------------	--

Notice	Offside rear tyre subject to some age cracking on tyre walls
---------------	--

Notice	Child seat fitted not allowing full inspection of adult belt
---------------	--

Notice	Engine covers fitted obscuring some components in the engine bay
---------------	--

MOT #3	2012-07-04 09:29
---------------	------------------

MOT test number	597516282139
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #2	2011-07-06 09:36
---------------	------------------

MOT test number	678347381104
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #1	2010-06-23 11:30
---------------	------------------

MOT test number	904694070108
------------------------	--------------

Result	✓ Passed
---------------	----------



Tax & MOT check

X

Untaxed

Tax expired:
31 January 2022

X

MOT

Expired:
19 July 2022

Tax status	Expired at 31 January 2022
Days left	818 days too late
MOT expiry date	19 July 2022
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2007-07-10
Last registration	2021-07-20
Complete history	See info



Registration #1	2007-07-10	28 mi
Registration #2	2010-06-23	13.880 mi
Registration #3	2011-07-06	18.842 mi
Registration #4	2012-07-04	24.343 mi
Registration #5	2013-07-09	31.384 mi
Registration #6	2014-07-03	40.511 mi
Registration #7	2015-06-16	48.053 mi
Registration #8	2016-07-04	56.657 mi
Registration #9	2016-06-20	55.377 mi
Registration #10	2016-06-20	55.377 mi
Registration #11	2016-06-20	55.377 mi
Registration #12	2016-06-20	55.377 mi
Registration #13	2016-06-20	55.377 mi
Registration #14	2016-06-20	55.377 mi
Registration #15	2016-06-20	55.377 mi
Registration #16	2016-06-20	55.377 mi

More info >



Safety ratings

NCAP rating

★ ★ ★ ★ ★

Video [see crash video](#)

Dimensions & weight

Width	1751 mm
Height	1637 mm
Length	4276 mm
Wheel base	2760 mm
Kerb weight	1300 kg
Max. allowed weight	1850 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	JB660199901