



report date: 2024-03-29

General information

Make	CITROEN
Model	DS3 DSTYLE PLUS
Colour	White
Year of manufacture	2012
Top speed	118 mph
0 - 60 mph	9.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	120 BHP
Max. torque	160 Nm at 4.200 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.1 mpg
Consumption extra urban	52.3 mpg
Consumption combined	40.4 mpg
CO2 emission	136 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-01-29
Pictures	1
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2025-04-14
MOT pass rate	61 %
MOT passed	11
Failed MOT tests	7
Total advice items	27
Total items failed	22

MOT #18	2024-03-30 15:28
MOT test number	784379881333
Result	✓ Passed
Next expiry date	2025-04-14

MOT #17	2024-03-26 13:12
MOT test number	515737866196

Result	✗ Failed
--------	----------

- Fail** Horn not working (7.7 (a))
- Fail** Rear Service brake excessively fluctuating both discs (1.2.1 (e))
- Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Fail** Offside Front Tyre not fitted in accordance with side wall instructions (5.2.3 (i))
- Fail** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Fail** Rear Brake disc significantly and obviously worn both (1.1.14 (a) (i))
- Fail** Nearside Front Wheel bearing rough when rotated (5.1.3 (b) (i))
- Fail** Front Tyre(s) of different sizes are fitted on the same axle. (5.2.3 (b))

MOT #16	2023-04-05 11:00
MOT test number	915093141458

Result	✓ Passed
--------	----------

**MOT #15** 2022-04-14 10:46**MOT test number** 874138788521**Result** ✓ Passed**Advice** Exhaust system deteriorated several repairs**Advice** Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))**MOT #14** 2021-04-15 10:57**MOT test number** 248626634641**Result** ✓ Passed**Advice** Front Tyre worn close to legal limit/worn on edge front tyres (20545x17 (5.2.3 (e)))**MOT #13** 2020-09-29 17:09**MOT test number** 175992154209**Result** ✓ Passed**Advice** Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))**MOT #12** 2019-09-03 15:13**MOT test number** 683083089016**Result** ✓ Passed**MOT #11** 2019-09-03 07:30**MOT test number** 125077451907**Result** ✗ Failed**Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Fail** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Fail** Nearside Rear Brake pad(s) incorrectly mounted (1.1.13 (c))

**MOT #10**

2019-03-12 15:49

MOT test number

871793274042

Result

✓ Passed

- Advice** Items removed from driver's view prior to test
- Advice** Nearside body work damaged
- Advice** Exhaust has a minor leak of exhaust gases slight exhaust blow from front flex pipe (6.1.2 (a))
- Advice** Offside Front body work damaged
- Minor** Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Nearside Front door catch loose but not insecure

MOT #9

2019-03-11 17:09

MOT test number

931466341786

Result

✗ Failed

- Advice** Exhaust has a minor leak of exhaust gases slight exhaust blow from front flex pipe (6.1.2 (a))
- Advice** Offside Front body work damaged
- Advice** Nearside Front door catch loose but not insecure
- Minor** Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Items removed from driver's view prior to test
- Advice** Nearside body work damaged

MOT #8

2018-03-29 15:01

MOT test number

322447974105

Result

✓ Passed

**MOT #7**

2018-03-21 11:21

MOT test number

851422836511

Result**✗ Failed****Fail** Nearside Front Headlamp aim too low (1.8)**Fail** Nearside Rear coil spring broken (2.4.C.1a)**Fail** Offside Front Headlamp aim too low (1.8)**MOT #6**

2017-04-05 11:38

MOT test number

279675212076

Result**✓ Passed****Advice** Crash damage visible on rear**Advice** Brake disc worn, pitted or scored, but not seriously weakened rear brake discs pitted slightly recommend brake check (3.5.1i)**Advice** Both head lamp beam pattern distorted slightly**Advice** Nearside Rear Rear wheel bearing has slight play (2.6.2)**MOT #5**

2017-04-05 10:49

MOT test number

585597318371

Result**✗ Failed****Advice** Nearside Rear Rear wheel bearing has slight play (2.6.2)**Fail** Windscreen wiper does not clear the windscreen effectively both front wiper blades (8.2.2)**Advice** Both head lamp beam pattern distorted slightly**Advice** Brake disc worn, pitted or scored, but not seriously weakened rear brake discs pitted slightly recommend brake check (3.5.1i)**Advice** Crash damage visible on rear

**MOT #4** 2017-03-09 08:50**MOT test number** 755353443403**Result** ✗ Failed**Fail** Offside Registration plate lamp not working (1.1.C.1d)**Advice** N/s and o/s/front running lights inop**Fail** Rear fog lamp not working (1.3.2b)**Fail** Exhaust system not adequately supported at front and rear (7.1.1)**Advice** Offside Front brake binding**Advice** Clutch slave cylinder is leaking**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #3** 2016-03-25 11:53**MOT test number** 176123970561**Result** ✓ Passed**MOT #2** 2016-03-12 09:52**MOT test number** 395547649813**Result** ✗ Failed**Fail** Nearside Front Tyre has a lump, caused by separation or partial failure of its structure side wall (4.1.D.1b)**Fail** Nearside Headlamp aim too low and too far to the right. (1.8)**MOT #1** 2015-03-25 14:43**MOT test number** 916484785048**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
14 April 2025

Tax status	Valid until 1 March
Days left	305
MOT expiry date	14 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2012-03-30
Last registration	2024-03-30
Complete history	See info



Registration #1	2012-03-30	20 mi
Registration #2	2015-03-25	39.290 mi
Registration #3	2016-03-12	50.933 mi
Registration #4	2016-03-25	51.118 mi
Registration #5	2017-03-09	59.828 mi
Registration #6	2017-04-05	60.367 mi
Registration #7	2017-04-05	60.367 mi
Registration #8	2018-03-21	69.175 mi
Registration #9	2018-03-29	69.407 mi
Registration #10	2019-03-11	80.703 mi
Registration #11	2019-03-29	91.999 mi
Registration #12	2019-03-29	91.999 mi
Registration #13	2019-03-29	91.999 mi
Registration #14	2019-03-29	91.999 mi
Registration #15	2019-03-29	91.999 mi
Registration #16	2019-03-29	91.999 mi
Registration #17	2019-03-29	91.999 mi
Registration #18	2019-03-29	91.999 mi
Registration #19	2019-03-29	91.999 mi
Registration #20	2019-03-29	91.999 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	71%
Pedestrian	35%
Safety systems	83%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1715 mm
Height	1483 mm
Length	3948 mm
Wheel base	2464 mm
Kerb weight	1147 kg
Max. allowed weight	1554 kg

Additional information

Fuel tank capacity	48 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number	FHCA1665093