





report date: 2024-03-29

General information

Make	FORD
Model	TRANSIT 340 LR P/V
Colour	Yellow
Year of manufacture	2017
Gearbox	6 speed Manual

Engine & fuel consumption

Power	168 BHP
Max. torque	405 Nm
Engine capacity	1.995 сс
Cylinders	4
Fuel type	Diesel
Consumption city	36.7 mpg
Consumption extra urban	47.1 mpg
Consumption combined	42.8 mpg
CO2 emission	162 g/km
CO2 label	G



CarCheck.co.uk page 1/10



report date: 2024-03-29

Internet history

Entry 1

Date 2021-07-23

Pictures 11

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/10



report date: 2024-03-29

MOT history

MOT expiry date	2024-01-25
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	8
Total items failed	3

MOT #7		2023-01-26 16:02
MOT test	number	301061480337
Result		✓ Passed
Next expi	ry date	2024-01-25
Advice	OSR Tyre perished	
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (i	i))
Advice	Service light on dash	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	

MOT #6	2022-01-25 13:20
MOT test number	395196394737
Result	✓ Passed
Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.)	14 (a) (ii))

CarCheck.co.uk page 3/10



Result

LB66CMF

report date: 2024-03-29

× Failed

MOT #5 2022-01-13 12:51 808534863391 **MOT** test number Result × Failed **Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Fail Offside Rear Towbar attachment insecure (6.1.6 (c) (i)) **Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Fail Nearside Rear Towbar attachment insecure (6.1.6 (c) (i)) **Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #4 2021-04-23 13:08
MOT test number 589972609973
Result ✓ Passed

MOT #3 2021-01-20 15:25

MOT test number 499073606893

Result ✓ Passed

MOT #2 2020-01-10 14:21

MOT test number 472527446313

Result ✓ Passed

MOT #1 2020-01-10 12:10

MOT test number 467880326262

Fail Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

CarCheck.co.uk page 4/10




report date: 2024-03-29

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 6/10



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report is	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	NK NE
Plate since	
Current registration	NK SILVE
Plate since	
	More info >

CarCheck.co.uk page 7/10



report date: 2024-03-29

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 8/10



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2017-01-23
Last registration	2023-01-26
Complete history	See info



Registration #1	2017-01-23	15 mi
Registration #2	2020-01-10	59.521 mi
Registration #3	2020-01-10	59.521 mi
Registration #4	2021-01-20	84.153 mi
Registration #5	2021-04-23	84.930 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		D.777 es

More info >

CarCheck.co.uk page 9/10



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	84%
Children	90%
Pedestrian	48%
Safety systems	71%
Overall rating	76%
Video	see crash video



Dimensions & weight

Width	2272 mm
Height	1923 mm
Length	5339 mm
Kerb weight	1891 kg
Max. allowed weight	3365 kg

Additional information

Fuel tank capacity	80
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Engine number CarCheck.co.uk	GY77723 page 10/10