





report date: 2024-03-28

General information

Make	HONDA
Model	CR-Z I-VTEC IMA SPORT
Colour	Silver
Year of manufacture	2012
Top speed	124 mph
0 - 60 mph	10.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	145 Nm at 4.800 rpm
Engine capacity	1.497 cc
Cylinders	4
Fuel type	Hybrid / Electric
Consumption city	46.3 mpg
Consumption extra urban	64.2 mpg
Consumption combined	56.5 mpg
CO2 emission	117 g/km
CO2 label	С



CarCheck.co.uk page 1/12



Internet history

Entry 1


Date 2022-02-27

Pictures 15

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2025-03-05
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	6
Total items failed	3

MOT #12	2024-02-23 11:00
MOT test number	631680398875
Result	✓ Passed
Next expiry date	2025-03-05

1101 #11	2024-02-22 11.20
MOT test number	772213876643
Result	X Failed
Fail Rear Service brake excessively binding (1.2.1 (f))	
Advice Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #10	2023-03-06 12:20
MOT test number	413732114947
Result	✓ Passed

MOT #9	2023-03-02 12:59
MOT test number	339773252133
Result	× Failed

Fail Nearside Track rod end ball joint dust cover insecure so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))

Fail Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

CarCheck.co.uk page 3/12



MOT #8 2022-02-14 10:34

MOT test number 267123251478

MOT #7 2021-02-23 17:09

MOT test number 651822821805

Result

Passed

MOT #6 2020-02-19 11:54

MOT test number 874662458859

Result \(\sqrt{Passed} \)

MOT #5 2019-02-21 11:39

MOT test number 748196362266

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #4 2018-02-21 11:37

MOT test number 191463294663

Result ✓ Passed

MOT #3 2017-02-23 16:37

MOT test number 367765226862

Result / Passed

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #2 2016-02-17 10:24

MOT test number 360415876918

Result

Passed

CarCheck.co.uk page 4/12



MOT #1

MOT test number

508276555096

Result

Notice Under-trays fitted obscuring some underside components

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 February
Days left	278
MOT expiry date	5 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	59
Band	С
Single payment (12 months)	£ 25,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 26,25,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner	history
OWITEL	HISLULY

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this HONDA had different number plates.		
See in this check if this HONDA had different number plates.		
See in this check if this HONDA had different number plates.		
See in this check if this HONDA had different number plates.		
See in this check if this HONDA had different number plates.		
See in this check if this HONDA had different number plates.		
See in this check if this HONDA had different number plates.	********	
See in this check if this HONDA had different number plates.	***************************************	
See in this check if this HONDA had different number plates.	***************************************	
See in this check if this HONDA had different number plates.		More info >
	Plate changes	
	See in this check if this HONDA had different number plates.	
	Number of plates	,
Plate since	Current registration	UK ZIS
Plate since	Plate since	
More info >	Current registration	UK NE
More info >	Plate since	
		More info >

CarCheck.co.uk page 9/12



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HONDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-03-31
Last registration	2024-02-23
Complete history	See info



Registration #1	2012-03-31	11 mi
Registration #2	2015-02-25	17.024 mi
Registration #3	2016-02-17	20.655 mi
Registration #4	2017-02-23	24.853 mi
Registration #5	2018-02-21	28.080 mi
Registration #6	2019-02-21	31.528 mi
Registration #7	2020-02-19	34.637 mi
Registration #8		11.777 es
Registration #9		9.777 es
Registration #10		11.777 es
Registration #11		91.777 esi
Registration #12		11.777 es
Registration #13		11.777 es

mn.n.n

More info >

77.777 86

CarCheck.co.uk page 11/12



Safety ratings

NCAP rating	****
Adult	93%
Children	80%
Pedestrian	71%
Safety systems	86%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	2014 mm
Height	1395 mm
Length	4080 mm
Wheel base	2425 mm
Kerb weight	1198 kg

Additional information

Fuel tank capacity	40 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	LEA1 1017966

CarCheck.co.uk page 12/12