





report date: 2024-03-29

General information

Make	FORD
Model	GALAXY ZETEC TDCI
Colour	Black
Year of manufacture	2008
Top speed	120 mph
0 - 60 mph	10.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	143 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	1.997 сс
Cylinders	4
Fuel type	Diesel
Consumption city	35.3 mpg
Consumption extra urban	54.3 mpg
Consumption combined	45.6 mpg
CO2 emission	165 g/km
CO2 label	G



CarCheck.co.uk page 1/15



CF08EKE

report date: 2024-03-29


Internet history


Entry 1

Date 2021-10-23

Pictures 22

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/15



MOT history

MOT expiry date	2024-10-19
MOT pass rate	60 %
MOT passed	12
Failed MOT tests	8
Total advice items	47
Total items failed	6

MOT #20		2023-10-20 10:04
MOT test	number	883152275629
Result		✓ Passed
Next expiry date 2024-10-19		
Advice (a) (i)) Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4		
Advice (i))	Offside Rear Suspension arm pin or bush worn but not resulting in exce	essive movement (5.3.4 (a)

MOT #19	2023-10-20 10:04	
MOT test number	802577238899	
Result	★ Failed	
Pass with rectification	Rear Exhaust has a major leak of exhaust gases (6.1.2 (a))	
Advice Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))		
Advice Nearside Rear (a) (i))	Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4	

CarCheck.co.uk page 3/15



CF08EKE

MOT #18 2022-09-22 09:26

MOT test number 746985989245

Result ✓ Passed

Advice Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a)

(i))

Advice Offside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

Advice Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4

(a) (i))

Advice Nearside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

Advice Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT #17 2022-09-16 08:26

MOT test number 592175052383

Result X Failed

Advice Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

Advice Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MAJOR Front Service brake imbalanced across an axle (1.2.1 (b) (i))

MAJOR Offside Front Service brake excessively binding (1.2.1 (f))

Advice Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

DANGEROUS Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))

Advice Offside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

MAJOR Nearside Front Brake hose excessively deteriorated (1.1.12 (b) (ii))

MAJOR Windscreen washer provides insufficient washer liquid (3.5 (a))

MAJOR Offside Front Service brake excessively fluctuating (1.2.1 (e))

CarCheck.co.uk page 4/15



CF08EKE

report date: 2024-03-29

MOT #16 2021-09-16 12:03

MOT test number 508950613362

Result ✓ Passed

Advice Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement Radius arm. (5.3.4 (a) (i))

Advice Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement Radius arm. (5.3.4 (a) (i))

MOT #15 2021-09-10 14:47

MOT test number 742109762552

Result X Failed

MAJOR Exhaust emissions exceed default limit of 1.5m-1 (8.2.2.2 (b))

Advice Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement Radius arm. (5.3.4 (a) (i))

DANGEROUS Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Advice Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement Radius arm. (5.3.4 (a) (i))

MOT #14 2020-08-05 13:06

MOT test number 600004819503

Result
✓ Passed

Advice Front Tyre worn close to legal limit/worn on edge 225/50/17 (5.2.3 (e))

MOT #13 2019-08-07 15:59

MOT test number 549879663724

Result ✓ Passed

Advice Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

CarCheck.co.uk page 5/15



MOT #12 2019-08-07 11:15

MOT test number 378709294544

Result X Failed

MAJOR Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MAJOR Exhaust emissions exceed default limit of 1.5m-1 (8.2.2.2 (b))

Advice Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MAJOR Central Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #11 2018-07-24 11:33

MOT test number 177412136415

Result \(\sqrt{Passed} \)

MOT #10 2018-07-18 14:34

MOT test number 992858484292

Result ★ Failed

MAJOR Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (i))

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened inner surface (1.1.14 (a) (ii))

DANGEROUS Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MAJOR Offside Rear Service brake excessively binding (1.2.1 (f))

MOT #9 2017-07-25 12:29

MOT test number 624275393159

Result
✓ Passed

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Exhaust heatshield loose

Advice Nearside rear tyre wearing unevenly on inside edge

CarCheck.co.uk page 6/15



MOT #8 2016-07-27 13:09

MOT test number 297747232050

Result ✓ Passed

Advice Uneven tread nearside rear

MOT #7

MOT test number

173538121739

Result

Advice Uneven tread nearside rear

Fail Nearside Rear Stop lamp not working (1.2.1b)

 MOT #6
 2015-08-03 16:24

 MOT test number
 646815715250

 Result
 ✓ Passed

MOT #5

MOT test number

195985715260

Result

Fail Offside Front Electrical wiring insecure (1.9.2a)

Fail Nearside Front Tyre has ply or cords exposed (4.1.D.1b)

MOT #4

MOT test number

456951424174

Result

Advice Offside Rear Brake pad(s) wearing thin (3.5.1g)

Advice Nearside Rear Brake pad(s) wearing thin (3.5.1g)

CarCheck.co.uk page 7/15



MOT test number
628200024136

Result

Fail Exhaust has a major leak of exhaust gases (7.1.2)

Advice Offside Rear Brake pad(s) wearing thin (3.5.1g)

Fail Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Advice Nearside Rear Brake pad(s) wearing thin (3.5.1g)

MOT #2

MOT test number

946137422204

Result

MOT #1

2011-08-12 12:25

MOT test number

387594021458

Result

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 8/15



Tax & MOT check



Tax status	Valid until 1 April
Days left	336
MOT expiry date	19 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 9/15



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 10/15



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 11/15



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report is	
THE PARTY OF THE P	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	AIZ SIE
Plate since	
	More info >

CarCheck.co.uk page 12/15



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info >

CarCheck.co.uk page 13/15



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2008-08-15
Last registration	2023-10-20
Complete history	See info



Registration #1	2008-08-15	29 mi
Registration #2	2011-08-12	36.440 mi
Registration #3	2012-08-14	45.229 mi
Registration #4	2014-04-30	62.038 mi
Registration #5	2014-05-01	62.038 mi
Registration #6	2015-08-03	72.192 mi
Registration #7	2015-08-03	72.192 mi
Registration #8	2016-07-27	80.078 mi
Registration #9	2016-07-27	80.078 mi
Registration #10	2017-07-25	87.556 mi
Registration #11	2018-07-18	91.773 mi
Registration #12		11.777 es
Registration #13		11.177 mi
Registration #14		11.177 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.777 es
Registration #21		11.777 es
Registration #22		0.00 44

More info >

CarCheck.co.uk page 14/15



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	2154 mm
Height	1736 mm
Length	4820 mm
Wheel base	2850 mm
Kerb weight	1975 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 15/

Number of axles2Engine number8D79516