



report date: 2024-03-29

General information

Make	KIA
Model	SORENTO CRDI KX-2
Colour	Silver
Year of manufacture	2010
Top speed	118 mph
0 - 60 mph	9.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	194 BHP
Max. torque	421 Nm at 1.800 rpm
Engine capacity	2.199 cc
Cylinders	4
Fuel type	Diesel
Consumption city	32.1 mpg
Consumption extra urban	51.4 mpg
Consumption combined	42.2 mpg
CO2 emission	177 g/km
CO2 label	I






Internet history

Entry 1

Date	2021-08-08
Pictures	49
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-09-07
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	20
Total items failed	10

MOT #16 2023-09-08 07:55

MOT test number 443187745991

Result ✓ Passed

Next expiry date 2024-09-07

- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement front most wishbone bush (5.3.4 (a) (i))
- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

MOT #15 2023-09-06 13:55

MOT test number 743785542186

Result ✗ Failed

- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement front most wishbone bush (5.3.4 (a) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Fail** Nearside Front Lower Suspension arm pin or bush excessively worn Front most wishbone bush (5.3.4 (a) (i))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Offside Side repeater not working (4.4.1 (a) (ii))
- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Fail** Offside Headlamp aim too high (4.1.2 (a))

**MOT #14** 2022-09-05 15:53**MOT test number** 255256011793**Result** ✓ Passed**Advice** Rear seats all down at time of test**MOT #13** 2022-09-05 09:26**MOT test number** 668473695891**Result** ✗ Failed**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Fail** Nearside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))**Advice** Rear seats all down at time of test**Advice** Front Brake pad(s) wearing thin both (1.1.13 (a) (ii))**MOT #12** 2021-08-31 13:38**MOT test number** 703982639526**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #11** 2021-03-08 11:49**MOT test number** 639962008966**Result** ✓ Passed

**MOT #10** 2021-03-05 14:52**MOT test number** 396194746469**Result** ✗ Failed

- Fail** Offside Parking brake inoperative on one side (1.4.1 (a))
- Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))

MOT #9 2020-10-15 11:00**MOT test number** 640267954960**Result** ✓ Passed

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Lower Suspension component ball joint has slight play (5.3.4 (a) (i))

MOT #8 2019-09-23 10:09**MOT test number** 973193896476**Result** ✓ Passed

- Advice** Rear diff bush split

MOT #7 2018-09-26 09:48**MOT test number** 834423754370**Result** ✓ Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #6 2017-10-17 11:20**MOT test number** 753135285380**Result** ✓ Passed

**MOT #5** 2016-10-19 13:40**MOT test number** 623019895759**Result** ✓ Passed**MOT #4** 2016-10-17 10:46**MOT test number** 442872072189**Result** ✗ Failed**Fail** Offside Front Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)**Fail** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #3** 2015-10-20 09:52**MOT test number** 882486762537**Result** ✓ Passed**Advice** Front wipers starting to smear**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #2** 2014-10-21 12:25**MOT test number** 326534794438**Result** ✓ Passed**MOT #1** 2013-10-21 12:38**MOT test number** 876414493242**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
7 September 2024

Tax status	Valid until 1 September
Days left	124
MOT expiry date	7 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-09-29
Last registration	2023-09-08
Complete history	See info



Registration #1	2010-09-29	21 mi
Registration #2	2013-10-21	36.707 mi
Registration #3	2014-10-21	40.947 mi
Registration #4	2015-10-20	52.754 mi
Registration #5	2016-10-17	64.835 mi
Registration #6	2016-10-19	64.838 mi
Registration #7	2017-10-17	74.285 mi
Registration #8	2018-09-26	81.689 mi
Registration #9	2019-09-23	91.316 mi
Registration #10	2020-09-23	91.317 mi
Registration #11	2020-09-23	91.317 mi
Registration #12	2020-09-23	91.317 mi
Registration #13	2020-09-23	91.317 mi
Registration #14	2020-09-23	91.317 mi
Registration #15	2020-09-23	91.317 mi
Registration #16	2020-09-23	91.317 mi
Registration #17	2020-09-23	91.317 mi
Registration #18	2020-09-23	91.317 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	84%
Pedestrian	44%
Safety systems	71%
Overall rating	76%
Video	see crash video



Dimensions & weight

Width	1885 mm
Height	1755 mm
Length	4685 mm
Wheel base	2700 mm
Kerb weight	1844 kg
Max. allowed weight	2510 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Engine number

D4HBAU237026