




report date: 2024-03-28

General information

Make	VOLVO
Model	V60 D3 R-DESIGN LUX NAV
Colour	Grey
Year of manufacture	2017
Top speed	130 mph
0 - 60 mph	8.5 seconds
Gearbox	6 speed automatic

Engine & fuel consumption


Power	148 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.969 cc
Cylinders	4
Fuel type	Diesel
Consumption city	60.1 mpg
Consumption extra urban	70.6 mpg
Consumption combined	67.3 mpg
CO2 emission	114 g/km
CO2 label	C



Internet history

Entry 1

Date	2021-11-06
Pictures	5
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-09-26
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	17
Total items failed	1

MOT #5	2023-09-21 15:19
MOT test number	911645478609
Result	✓ Passed
Next expiry date	2024-09-26
Advice	Offside Rear tyre inner edge wearing,advise
Advice	Front Brake disc worn, but not excessively both discs pitted,advise (1.1.14 (a) (i))
Advice	Lower vehicle has under trays obscuring some inspections,advise

MOT #4	2023-09-21 15:19
MOT test number	341321306362
Result	✗ Failed
Advice	Front Brake disc worn, but not excessively both discs pitted,advise (1.1.14 (a) (i))
Advice	Offside Rear tyre inner edge wearing,advise
Pass with rectification	Nearside Front Headlamp aim too high (4.1.2 (a))
Advice	Lower vehicle has under trays obscuring some inspections,advise

**MOT #3** 2022-09-22 15:03**MOT test number** 396662436346**Result** ✓ Passed

- Advice** Nearside Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Brake disc worn, but not excessively has lip (1.1.14 (a) (i))
- Advice** Nearside Rear Brake disc worn, but not excessively has lip (1.1.14 (a) (i))
- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge worn (5.2.3 (e))
- Advice** Offside Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Brake disc worn, but not excessively has lip (1.1.14 (a) (i))
- Advice** Offside Rear Brake disc worn, but not excessively has lip (1.1.14 (a) (i))
- Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge worn (5.2.3 (e))

MOT #2 2021-09-09 11:40**MOT test number** 656264699548**Result** ✓ Passed

- Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #1 2020-09-17 10:01**MOT test number** 701771621143**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))



Tax & MOT check

✓
Taxed

Tax due:
1 June 2024

✓
MOT

Expires:
26 September 2024

Tax status	Valid until 1 June
Days left	33
MOT expiry date	26 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
First licence fee (12 months)	£ 210,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 255,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	KN67WWK
Plate since	2019-09-28
Current registration	KN67WWK
Plate since	2019-09-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2017-09-27
Last registration	2023-09-21
Complete history	See info



Registration #1	2017-09-27	16 mi
Registration #2	2020-09-17	40.629 mi
Registration #3	2021-09-09	48.308 mi
Registration #4	2022-09-20	55.277 mi
Registration #5	2023-09-21	62.246 mi
Registration #6	2024-03-28	69.215 mi
Registration #7	2024-03-28	76.184 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	82%
Pedestrian	64%
Safety systems	100%
Overall rating	86%
Video	see crash video



Dimensions & weight

Width	2097 mm
Height	1484 mm
Length	4635 mm
Wheel base	2776 mm
Kerb weight	1663 kg
Max. allowed weight	2200 kg

Additional information

Fuel tank capacity	67 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	2263408