



YYIIMXL

report date: 2024-03-28

General information

Make	MINI
Model	COOPER S
Colour	White
Year of manufacture	2011
Top speed	133 mph
0 - 60 mph	7.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	190 BHP
Max. torque	240 Nm at 1.600 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption combined	44.8 mpg
CO2 emission	143 g/km
CO2 label	F





Internet history

Entry 2

Date	2021-09-10
Pictures	0
Listing price	View report

source: yesauto.com

Entry 1

Date	2021-09-07
Pictures	1
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-01-02
MOT pass rate	63 %
MOT passed	10
Failed MOT tests	6
Total advice items	46
Total items failed	3

MOT #16	2024-01-03 13:20
MOT test number	559872400877
Result	✓ Passed
Next expiry date	2025-01-02
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened both n/s & o/s (1.1.14 (a) (ii))
Advice	Front Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened both n/s & o/s (1.1.14 (a) (ii))
Advice	Offside Front Coil spring corroded (5.3.1 (b) (i))

MOT #15	2024-01-03 12:28
MOT test number	443528096999
Result	✗ Failed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened both n/s & o/s (1.1.14 (a) (ii))
Advice	Front Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened both n/s & o/s (1.1.14 (a) (ii))
MAJOR	Offside Front Position lamp not working (4.2.1 (a) (ii))
Advice	Offside Front Coil spring corroded (5.3.1 (b) (i))

**MOT #14** 2022-12-14 15:49**MOT test number** 638428468973**Result** ✓ Passed**Advice** Front Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both n/s & o/s (1.1.14 (a) (ii))**MOT #13** 2022-12-13 13:21**MOT test number** 674710047057**Result** ✗ Failed**Advice** Front Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both n/s & o/s (1.1.14 (a) (ii))**MAJOR** Rear Reversing lamp inoperative (4.6.1 (a))**MOT #12** 2021-12-03 13:27**MOT test number** 512329540531**Result** ✓ Passed**MOT #11** 2021-11-09 16:03**MOT test number** 447568037862**Result** ✗ Failed**MAJOR** Oil leaking excessively from engine (8.4.1 (a) (i))**MAJOR** Offside Rear Shock absorbers has an excessively worn bush top housing (5.3.2 (c))**MAJOR** Nearside Front Position lamp not working (4.2.1 (a) (ii))**MAJOR** Nearside Rear Shock absorbers has an excessively worn bush top housing (5.3.2 (c))

**MOT #10**

2020-11-23 14:51

MOT test number

180479525931

Result

✓ Passed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Seat belt buckle slightly damaged (7.1.2 (d))

MOT #9

2020-11-23 09:50

MOT test number

833508597091

Result

✗ Failed

- DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
 - Advice** Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
 - Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
 - Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
 - Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
 - Advice** Offside Rear Seat belt buckle slightly damaged (7.1.2 (d))
 - Advice** Oil leak, but not excessive (8.4.1 (a) (i))

MOT #8

2019-05-29 11:50

MOT test number

873006857309

Result

✓ Passed

- Advice** Oil leak, but not excessive slight weap (8.4.1 (a) (i))
- Advice** Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Minor** Windscreen damaged but not adversely affecting driver's view chip (3.2 (a) (i))
- Advice** Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #7** 2018-04-05 10:50**MOT test number** 814234942001**Result** ✓ Passed**Advice** Offside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)**MOT #6** 2018-04-05 10:50**MOT test number** 772946900880**Result** ✗ Failed**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)**Advice** Offside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**MOT #5** 2017-04-10 10:07**MOT test number** 188957230823**Result** ✓ Passed**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Rear tyres worn on inner edges**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear Nail in tyre

**MOT #4** 2017-04-10 10:07**MOT test number** 385031823999**Result** ✗ Failed**Pass with rectification** Front Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Rear tyres worn on inner edges**Advice** Nearside Rear Nail in tyre**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #3** 2016-04-05 15:45**MOT test number** 334167253989**Result** ✓ Passed**MOT #2** 2015-04-07 09:28**MOT test number** 636757295062**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**MOT #1** 2014-04-15 19:42**MOT test number** 256645904124**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
2 January 2025

Tax status	Valid until 1 December
Days left	216
MOT expiry date	2 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	YY11MXL
Plate since	2019-03-28
Current registration	YY11MXL
Plate since	2019-03-28

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2011-06-24
Last registration	2024-01-03
Complete history	See info



Registration #1	2011-06-24	7 mi
Registration #2	2014-04-15	22.061 mi
Registration #3	2015-04-07	39.822 mi
Registration #4	2016-04-05	55.020 mi
Registration #5	2017-04-10	65.827 mi
Registration #6	2017-04-10	65.827 mi
Registration #7	2018-04-05	76.116 mi
Registration #8	2018-04-05	76.116 mi
Registration #9	2019-05-29	84.437 mi
Registration #10	2020-11-23	102.477 mi
Registration #11	2020-11-23	102.477 mi
Registration #12	2020-11-23	102.477 mi
Registration #13	2020-11-23	102.477 mi
Registration #14	2020-11-23	102.477 mi
Registration #15	2020-11-23	102.477 mi
Registration #16	2020-11-23	102.477 mi
Registration #17	2020-11-23	102.477 mi
Registration #18	2020-11-23	102.477 mi
Registration #19	2020-11-23	102.477 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1789 mm
Height	1577 mm
Length	4097 mm
Kerb weight	1310 kg
Max. allowed weight	1780 kg

Additional information

Fuel tank capacity	47 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Engine number	A431I943