






report date: 2024-03-28

General information

| Make | RENAULT |
|---------------------|-------------------|
| Model | ZOE DYNAMIQUE NAV |
| Colour | Purple |
| Year of manufacture | 2018 |
| Top speed | 84 mph |
| 0 - 60 mph | 11.9 seconds |
| Gearbox | 1 speed automatic |

Engine & fuel consumption

| Power | 108 BHP |
|----------------------|---------------------|
| Max. torque | 225 Nm at 3.395 rpm |
| Fuel type | Electricity |
| Consumption combined | 235.2 mpg |



CarCheck.co.uk page 1/11



LN68XTC

report date: 2024-03-28

Internet history

Entry 3

Date 2021-09-21

Pictures 13

Listing price <u>View report</u>









source: yesauto.com

Entry 2

Date 2021-09-19

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date2021-09-18Pictures0Listing priceView report

source: heycar.co.uk

CarCheck.co.uk page 2/11



MOT history

| MOT expiry date | 2024-09-27 |
|--------------------|------------|
| MOT pass rate | 75 % |
| MOT passed | 3 |
| Failed MOT tests | 1 |
| Total advice items | 8 |
| Total items failed | 1 |

| MOT #4 | | 2023-09-22 11:15 |
|-----------|--|------------------|
| MOT test | number | 588823628895 |
| Result | | ✓ Passed |
| Next expi | ry date | 2024-09-27 |
| Advice | Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Advice | Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Advice | Nearside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i)) | |

| MOT #3 | | 2022-09-23 11:04 |
|----------|---|------------------|
| MOT test | number | 329525214447 |
| Result | | ✓ Passed |
| Advice | Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i)) | |
| Advice | Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Advice | Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |

| MOT #2 | 2021-09-28 14:32 |
|-----------------|------------------|
| MOT test number | 732445677368 |
| Result | ✓ Passed |

CarCheck.co.uk page 3/11



MOT #1 2021-09-28 13:14

MOT test number 100019926299

Result X Failed

Advice Offside Front tyre bald on shoulders

Fail Nearside Front Outer Tyre has a cut in excess of the requirements deep enough to reach the ply or cords tread deep cut (5.2.3 (d) (i))

Advice Nearside Rear Nail in tyre

CarCheck.co.uk page 4/11



LN68XTC

report date: 2024-03-28

27 September 2024

Tax & MOT check

MOT expiry date



Full MOT history See MOT history

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

| Owner history | |
|---|-------------|
| For how long did the current and previous owner(s) have this RENAULT? How many owner have? Check it in the premium report and see all owner registrations. Download the full is | |
| ********** | |
| *************************************** | |
| ************ | |
| ********* | |
| *************************************** | |
| THE STREET STREET | |
| | More info > |
| Plate changes | |
| See in this check if this RENAULT had different number plates. | |
| Number of plates | , |
| Current registration | NK SIE |
| Plate since | |
| Current registration | OK SIE |
| Plate since | |
| | More info > |
| | |

CarCheck.co.uk page 8/11



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| | |

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 8 |
| First mileage registration | 2018-10-31 |
| Last registration | 2023-09-22 |
| Complete history | See info |



| Registration #1 | 2018-10-31 | 27 mi |
|-----------------|------------|-----------|
| Registration #2 | | 71.777 66 |
| Registration #3 | | 11.777 es |
| Registration #4 | | 11.777 es |
| Registration #5 | | 11.777 es |
| Registration #6 | | 71.777 es |
| Registration #7 | | 11.777 es |
| Registration #8 | | 11.777 es |

More info >

CarCheck.co.uk page 10/11



Car features

| S0225 | Air conditionin |
|-------|-----------------|
| S0295 | |
| S0482 | |
| 50501 | |
| 50566 | |
| 50567 | |
| 50569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 89% |
| Children | 80% |
| Pedestrian | 66% |
| Safety systems | 85% |
| Overall rating | 82% |
| Video | see crash video |



Dimensions & weight

| Width | 1945 mm |
|---------------------|---------|
| Height | 1562 mm |
| Length | 4084 mm |
| Wheel base | 2588 mm |
| Kerb weight | 1500 kg |
| Max. allowed weight | 1954 kg |

Additional information

| Fuel delivery | Not Applicable | |
|-----------------------------------|----------------|------------|
| Number of doors | 5 | |
| Number of seats | 5 | |
| Number of axles Carcheck.co.uk | 2 | page 11/11 |