




report date: 2024-03-29

General information

Make	VOLVO
Model	S80 SE LUX (170BHP)
Colour	Grey
Year of manufacture	2006
Top speed	137 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	168 BHP
Max. torque	225 Nm at 4.500 rpm
Engine capacity	2.435 cc
Cylinders	5
Fuel type	Petrol
Consumption city	22.8 mpg
Consumption extra urban	40.4 mpg
Consumption combined	31.4 mpg
CO2 emission	214 g/km
CO2 label	K





Internet history

Entry 1	
Date	2021-06-21
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-06-21
MOT pass rate	68 %
MOT passed	15
Failed MOT tests	7
Total advice items	11
Total items failed	17

MOT #22	2023-06-22 09:01
MOT test number	478590761111
Result	✓ Passed
Next expiry date	2024-06-21

MOT #21	2023-06-17 08:13
MOT test number	435264174004
Result	✗ Failed
<div><div>Advice</div> Offside Front Direction indicator slightly discoloured (4.4.3 (a))</div> <div><div>Fail</div> Offside Headlamp levelling device inoperative (4.1.5 (a))</div> <div><div>Fail</div> Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))</div> <div><div>Advice</div> Nearside Front Direction indicator slightly discoloured (4.4.3 (a))</div> <div><div>Fail</div> Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))</div>	

MOT #20	2022-06-13 08:00
MOT test number	130884913634
Result	✓ Passed
<div><div>Advice</div> Nearside Rear Tyre slightly damaged/cracking or perishing cracking and also starting to become out of shape on the inner edge (5.2.3 (d) (ii))</div>	

**MOT #19** 2021-06-21 10:38**MOT test number** 293974469700**Result** ✓ Passed**MOT #18** 2021-06-21 09:22**MOT test number** 869625563844**Result** ✗ Failed**Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MOT #17** 2020-01-23 11:20**MOT test number** 384087766984**Result** ✓ Passed**MOT #16** 2019-02-04 11:21**MOT test number** 170684570367**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge and has slight damage to outer side wall (5.2.3 (e))**Advice** Offside Rear Valve stem slightly damaged (5.2.3 (j))**MOT #15** 2018-01-23 12:15**MOT test number** 421576845567**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #14** 2017-02-08 09:45**MOT test number** 694895354160**Result** ✓ Passed



MOT #13	2016-01-07 13:58
MOT test number	510983061946
Result	✓ Passed
Advice	Centre Exhaust has a minor leak of exhaust gases (7.1.2)

MOT #12	2016-01-07 13:02
MOT test number	717111925668
Result	✗ Failed
Fail	Nearside Rear Tyre not fitted in accordance with side wall instructions (4.1.D.1f)
Pass with rectification	Offside Rear Outer Rear position lamp(s) not working (1.1.A.3b)
Advice	Centre Exhaust has a minor leak of exhaust gases (7.1.2)
Pass with rectification	Nearside Rear Outer Rear position lamp(s) not working (1.1.A.3b)

MOT #11	2015-01-27 14:39
MOT test number	537407625067
Result	✓ Passed

MOT #10	2015-01-27 12:14
MOT test number	139757325493
Result	✗ Failed
Pass with rectification	Nearside Headlamp not working on dipped beam (1.7.5a)
Fail	Offside Front Tyre has ply or cords exposed (4.1.D.1b)
Fail	Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
Notice	Osir tyre has worn unevenly and is worn low at inner edge.

MOT #9	2014-02-06 16:32
MOT test number	665307434075
Result	✓ Passed

**MOT #8** 2013-02-06 11:59**MOT test number** 616417133008**Result** ✓ Passed**MOT #7** 2012-02-20 13:49**MOT test number** 406751652079**Result** ✓ Passed**Notice** Osr tyre is worn low on very inner edge.**MOT #6** 2012-02-20 10:55**MOT test number** 778081952074**Result** ✗ Failed**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**Pass with rectification** Nearside Front Headlamp not working on dipped beam (1.7.5a)**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**Notice** Osr tyre is worn low on very inner edge.**MOT #5** 2011-02-15 12:51**MOT test number** 819706841044**Result** ✓ Passed**MOT #4** 2011-02-15 12:51**MOT test number** 389616341038**Result** ✗ Failed**Pass with rectification** Offside Rear Registration plate lamp not working (1.1.C.1d)**MOT #3** 2010-03-04 15:50**MOT test number** 312413560016**Result** ✓ Passed



MOT #2	2009-03-03 15:53
MOT test number	773892769004
Result	✓ Passed

MOT #1	2009-03-03 14:24
MOT test number	134382969010
Result	✗ Failed
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Fail	Fuel system component insecure (7.2.1)
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
21 June 2024

Tax status	Valid until 1 August
Days left	94
MOT expiry date	21 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-




Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.


Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2006-03-07
Last registration	2023-06-22
Complete history	See info



Registration #1	2006-03-07	15 mi
Registration #2	2009-03-03	26.690 mi
Registration #3	2009-03-03	26.690 mi
Registration #4	2010-03-04	36.428 mi
Registration #5	2011-02-15	45.606 mi
Registration #6	2012-02-20	56.031 mi
Registration #7	2012-02-20	56.031 mi
Registration #8	2013-02-06	65.076 mi
Registration #9	2014-02-06	73.931 mi
Registration #10	2015-01-27	81.975 mi
Registration #11	2015-01-27	81.975 mi
Registration #12	2016-01-07	88.061 mi
Registration #13	2016-01-07	88.061 mi
Registration #14	2016-01-07	88.061 mi
Registration #15	2016-01-07	88.061 mi
Registration #16	2016-01-07	88.061 mi
Registration #17	2016-01-07	88.061 mi
Registration #18	2016-01-07	88.061 mi
Registration #19	2016-01-07	88.061 mi
Registration #20	2016-01-07	88.061 mi
Registration #21	2016-01-07	88.061 mi
Registration #22	2016-01-07	88.061 mi
Registration #23	2016-01-07	88.061 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1833 mm
Height	1454 mm
Length	4850 mm
Wheel base	2835 mm
Kerb weight	1476 kg
Max. allowed weight	2020 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	3774595