





report date: 2024-03-28

General information

Make	HONDA
Model	ACCORD I-VTEC ES GT
Colour	Silver
Year of manufacture	2014
Top speed	134 mph
0 - 60 mph	9.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	154 BHP
Max. torque	192 Nm at 4.100 rpm
Engine capacity	1.997 сс
Cylinders	4
Fuel type	Petrol
Consumption city	30.1 mpg
Consumption extra urban	47.9 mpg
Consumption combined	39.2 mpg
CO2 emission	159 g/km
CO2 label	G



CarCheck.co.uk page 1/12



SR14NLA

report date: 2024-03-28

Internet history

Entry 1

Date 2022-01-14

Pictures 7

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2025-04-11
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	12
Total items failed	3

MOT #12	2024-03-27 11:07
MOT test number	757425091837
Result	✓ Passed
Next expiry date	2025-04-11
Advice Offside Rear Service brake binding but not excessively (1.2.1 (f))	

MOT #11	2023-04-04 11:45
MOT test number	678061104827
Result	✓ Passed
MOT #10	2022-04-12 07:56

MOT test num	ber 50	08647300591
Result		✓ Passed
Advice Nea	arside Rear Tyre slightly damaged/cracking or perishing cracks (5.2.3 (d) (ii))	

	Advice	Nearside Rear Tyre slightly damaged/cracking or perishing cracks (5.2.3 (d) (ii))
	Advice	Offside Rear Tyre slightly damaged/cracking or perishing cracks (5.2.3 (d) (ii))
-		

MOT #9	2021-09-23 14:02
MOT test number	858704763132
Result	✓ Passed
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

CarCheck.co.uk page 3/12



SR14NLA

report date: 2024-03-28

× Failed

Passed

MOT #8 2021-03-19 16:46

MOT test number 833507522544

Result \rightarrow Passed

Advice

Result

Offside Front Outer Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #7 2021-03-19 11:43

MOT test number 327915063356

Result

Fail Nearside Windscreen washer provides insufficient washer liquid (3.5 (a))

Advice Offside Front Outer Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #6 2020-03-10 13:29

MOT test number 817303024790

Result ✓ Passed

MOT #5 2019-03-14 14:47

MOT test number 679535590366

Result \(\sqrt{Passed} \)

Advice Offside Rear Tyre worn close to legal limit/worn on edge worn on inside edge (5.2.3 (e))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge worn inside edge (5.2.3 (e))

MOT #4 2018-03-15 11:36

MOT test number 149841920194

Advice Vehicles internal headlight adjuster altered to recheck lights

CarCheck.co.uk page 4/12



Advice

SR14NLA report date: 2024-03-28

MOT #3 2018-03-15 11:36

MOT test number 278766720966

Result X Failed

Pass with rectification Headlamp aim too high both (1.8)

Vehicles internal headlight adjuster altered to recheck lights

MOT #2 2017-03-17 14:17

MOT test number 803454855310

Advice Front washer jets poor

MOT #1 2017-03-17 12:18

MOT test number 577414493411

Result X Failed

Fail Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

Advice Front washer jets poor

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 March
Days left	306
MOT expiry date	11 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

e union mestery	
For how long did the current and previous owner(s) have this HONDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full respectively.	

	More info >
Plate changes	
See in this check if this HONDA had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HONDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2014-03-18
Last registration	2024-03-27
Complete history	See info



Registration #1	2014-03-18	18 mi
Registration #2	2017-03-17	25.126 mi
Registration #3	2017-03-17	25.126 mi
Registration #4	2018-03-15	29.816 mi
Registration #5	2018-03-15	29.816 mi
Registration #6	2019-03-14	34.712 mi
Registration #7	2020-03-10	38.040 mi
Registration #8		71.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		71.777 es
Registration #13		11.777 es

mn.n.n

More info >

77.777 au

CarCheck.co.uk page 11/12



Safety ratings

NCAP rating	****
Adult	86%
Children	79%
Pedestrian	54%
Safety systems	86%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1840 mm
Height	1440 mm
Length	4726 mm
Wheel base	2705 mm
Kerb weight	1501 kg
Max. allowed weight	1935 kg

Additional information

Fuel tank capacity	65 I
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	4101871

CarCheck.co.uk page 12/12