



RENAULT



report date: 2024-03-29

General information

Make	RENAULT
Model	MEGANE DYNAMIQUE TOMTOM DCI
Colour	Black
Year of manufacture	2012
Top speed	118 mph
0 - 60 mph	12.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	78.5 mpg
Consumption combined	67.3 mpg
CO2 emission	109 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-02-04
Pictures	10
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2024-08-17
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	53
Total items failed	3

MOT #11	2023-08-18 10:37
MOT test number	925193347856
Result	✓ Passed
Next expiry date	2024-08-17
Advice	Nearside Rear rear light lense damaged but not affecting light output

**MOT #10**

2022-08-17 13:59

MOT test number

513653837230

Result

✓ Passed

- Advice** Front brake discs are corroded / scored / worn / pitted (inner face)
- Advice** Exhaust emissions are too clean to get a reading
- Advice** Very slight play in the steering rack / front track rod ends
- Minor** Offside Front Windscreen wiper blade defective (3.4 (b) (i))
- Advice** Rear Suspension arms pins / bushes are worn but not resulting in excessive movement
- Advice** Service light is ON
- Advice** Oil leak in the engine bay area but not excessive
- Advice** DRIVERS SIDE FRONT TYRE IS VERY VERY CLOSE TO THE LEGAL LIMIT 2.0MM
- Advice** Rear shock absorbers & coil springs are corroded
- Advice** Rear brake discs are corroded / scored / worn / pitted (inner face)
- Minor** Nearside Front Windscreen wiper blade defective (3.4 (b) (i))
- Advice** Front Suspension arms pins / bushes are worn but not resulting in excessive movement
- Advice** Hand brake just met minimum mot requirements, needs adjustment / repair
- Advice** Engine covers, under trays & sill covers are fitted thus not allowing full inspection
- Advice** Nearside Front Road wheel bead is slightly distorted
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear shock absorbers & coil springs are corroded

**MOT #9**

2022-08-17 13:59

MOT test number

756412617973

Result**✗ Failed**

- Minor** Offside Front Windscreen wiper blade defective (3.4 (b) (i))
- Advice** Rear shock absorbers & coil springs are corroded
- Advice** Front brake discs are corroded / scored / worn / pitted (inner face)
- Advice** Exhaust emissions are too clean to get a reading
- Advice** Very slight play in the steering rack / front track rod ends
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Suspension arms pins / bushes are worn but not resulting in excessive movement
- Pass with rectification** Front Registration plate insecure (0.1 (a))
- Advice** Service light is ON
- Minor** Nearside Front Windscreen wiper blade defective (3.4 (b) (i))
- Advice** Oil leak in the engine bay area but not excessive
- Advice** DRIVERS SIDE FRONT TYRE IS VERY VERY CLOSE TO THE LEGAL LIMIT 2.0MM
- Advice** Rear shock absorbers & coil springs are corroded
- Advice** Rear brake discs are corroded / scored / worn / pitted (inner face)
- Advice** Front Suspension arms pins / bushes are worn but not resulting in excessive movement
- Advice** Hand brake just met minimum mot requirements, needs adjustment / repair
- Advice** Engine covers, under trays & sill covers are fitted thus not allowing full inspection
- Pass with rectification** Offside Front Headlamp aim too high (4.1.2 (a))
- Advice** Nearside Front Road wheel bead is slightly distorted



MOT #8	2021-08-18 10:35
MOT test number	390406608909
Result	✓ Passed
Advice	Brake disc worn, but not excessively front and rear (1.1.14 (a) (i))

MOT #7	2020-08-06 13:18
MOT test number	274482305207
Result	✓ Passed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))
Advice	Nearside Front Outer Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #6	2019-08-06 07:48
MOT test number	466841089545
Result	✓ Passed
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Front Lower Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #5	2019-08-06 07:48
MOT test number	551815279184
Result	✗ Failed
Pass with rectification	Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Front Lower Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #4** 2018-07-17 13:52**MOT test number** 529132859293**Result** ✓ Passed**Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Nearside Front tyre worn on outer edge**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Offside Front tyre worn on outer edge**MOT #3** 2017-05-05 13:57**MOT test number** 887473276350**Result** ✓ Passed**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**MOT #2** 2016-04-23 10:04**MOT test number** 355762152846**Result** ✓ Passed**Advice** Offside Rear nail in tyre**Advice** Offside Rear brake slightly dragging**MOT #1** 2015-05-12 12:13**MOT test number** 947252835126**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
17 August 2024

Tax status	Valid until 1 March
Days left	305
MOT expiry date	17 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	HN62VXV
Plate since	2019-03-29
Current registration	HN62VXV
Plate since	2019-03-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2012-12-12
Last registration	2023-08-18
Complete history	See info



Registration #1	2012-12-12	21 mi
Registration #2	2015-05-12	33.923 mi
Registration #3	2016-04-23	40.133 mi
Registration #4	2017-05-05	45.278 mi
Registration #5	2018-07-17	50.679 mi
Registration #6	2019-08-06	56.102 mi
Registration #7	2019-08-06	56.102 mi
Registration #8	2019-08-06	56.102 mi
Registration #9	2019-08-06	56.102 mi
Registration #10	2019-08-06	56.102 mi
Registration #11	2019-08-06	56.102 mi
Registration #12	2019-08-06	56.102 mi
Registration #13	2019-08-06	56.102 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1808 mm
Height	1471 mm
Length	4295 mm
Wheel base	2703 mm
Kerb weight	1215 kg
Max. allowed weight	1813 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D096392