





report date: 2024-03-29

General information

Make	VOLVO
Model	XC90 D5 SE LUX AWD
Colour	Grey
Year of manufacture	2011
Top speed	127 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	200 BHP
Max. torque	420 Nm at 2.000 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	25.7 mpg
Consumption extra urban	41.5 mpg
Consumption combined	34.0 mpg
CO2 emission	219 g/km
CO2 label	K



CarCheck.co.uk page 1/12



Internet history

_		4		7
ᆮ	n	Т	rν	1

LIICI Y I	
Date	2021-06-09
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/12



OE11CSX

report date: 2024-03-29

B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-05-25
MOT pass rate	92 %
MOT passed	11
Failed MOT tests	1
Total advice items	8
Total items failed	2

MOT #12	2023-05-25 15:21
MOT test number	955057480331
Result	✓ Passed
Next expiry date	2024-05-25

MOT #11	2022-05-26 11:23
MOT test number	495775152058
Result	✓ Passed

MOT #10		2022-05-26 11:23
MOT test number		360325422784
Result		X Failed
Pass with rectification	Nearside Front Headlamp aim too high (4.1.2 (a))	
Pass with rectification	Offside Front Headlamp aim too high (4.1.2 (a))	

MOT #9	2021-07-01 08:42
MOT test number	701294579318
Result	✓ Passed
MOT #8	2020-06-05 15:59
MOT test number	765245040818
Result	. ✓ Passed

CarCheck.co.uk page 3/12



OE11CSX

report date: 2024-03-29

MOT #7 2019-04-26 13:00

MOT test number 118902138111

Result ✓ Passed

MOT #6 2018-04-13 10:53

MOT test number 791772809370

Result
✓ Passed

Advice Engine covers and undertrays fitted obscuring some testable components

Advice Rear Brake pad(s) wearing thin (3.5.1g)

MOT #5 2017-04-03 14:46

MOT test number 975514264519

Result \rightarrow Passed

Advice Offside Front Tyre worn close to the legal limit 2.6mm (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit 1.8mm advise immediate replacement (4.1.E.1)

Advice Engine covers and undertrays fitted

MOT #4 2016-04-29 13:58

MOT test number 103244743561

Result

Passed

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Engine covers and undertrays fitted

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #3 2015-05-01 13:31

MOT test number 407361725157

Result

Passed

CarCheck.co.uk page 4/12



MOT #2	2014-06-20 15:29
MOT test number	209431474127
Result	✓ Passed
MOT #1	2014-06-18 15:25
MOT #1 MOT test number	2014-06-18 15:25 919569764121

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 July
Days left	62
MOT expiry date	25 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



OE11CSX

report date: 2024-03-29

Owner history	
For how long did the current and previous owner(s) have this VOLVO? How many owners have? Check it in the premium report and see all owner registrations. Download the full r	

THE STATE OF THE S	
Plate changes	More info >
See in this check if this VOLVO had different number plates.	
Number of plates	
Current registration	OK SIE
Plate since	
Current registration	UK ZIN
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >


CarCheck.co.uk page 10/12



Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2011-06-24
Last registration	2023-05-25
Complete history	See info



Registration #1	2011-06-24	26 mi
Registration #2	2014-06-18	44.260 mi
Registration #3	2014-06-20	44.411 mi
Registration #4	2015-05-01	55.875 mi
Registration #5	2016-04-29	69.546 mi
Registration #6	2017-04-03	83.264 mi
Registration #7	2018-04-13	95.600 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		
Registration #10		m.m-
Registration #11		11,777 ea
-		11.777 ea 11.777 ea
Registration #11		11.777 es 11.777 es 11.777 es

mn.n.n

More info >

77.777 86

CarCheck.co.uk page 11/12



Car features

50225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1898 mm
Height	1784 mm
Length	4807 mm
Wheel base	2857 mm
Kerb weight	2158 kg
Max. allowed weight	2750 kg

Additional information

Fuel tank capacity	68 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 12/12

Number of axles 2
Engine number 1044305