





report date: 2024-03-29

#### General information

Make	BMW
Model	X6 XDRIVE40D M SPORT
Colour	Grey
Year of manufacture	2011
Top speed	147 mph
Gearbox	8 speed automatic

# Engine & fuel consumption

Power	302 BHP
Max. torque	600 Nm at 1.500 rpm
Engine capacity	2.993 сс
Cylinders	6
Fuel type	Diesel
Consumption city	32.1 mpg
Consumption extra urban	41.5 mpg
Consumption combined	37.7 mpg
CO2 emission	198 g/km
CO2 label	



CarCheck.co.uk page 1/13



report date: 2024-03-29


#### Internet history

#### Entry 3

Date 2022-02-04

Pictures 50

Listing price <u>View report</u>









source: cargurus.co.uk

#### Entry 2

Date 2021-12-29

Pictures 19

Listing price <u>View report</u>









source: autotrader.co.uk

#### Entry 1

Date 2021-06-23

Pictures 1

Listing price <u>View report</u>



source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

B 4	$\sim$ $-$		
10.71	$^{\prime}$	hic	torv.
101	C I	1115	IUI V
	•		tory

MOT expiry date	2024-02-20
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	27
Total items failed	1

MOT #14	2023-01-30 16:12
MOT test number	278815573709
Result	✓ Passed
Next expiry date	2024-02-20

MOT #13		2023-01-30 10:54
MOT test	number	721117525867
Result		<b>X</b> Failed
MAJOR	Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))	

MOT #12	2022-02-21 11:38
MOT test number	497911270309
Result	<b>✓</b> Passed
MOT #11	2021-09-14 17:18
MOT test number	823504806291
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/13



report date: 2024-03-29

**MOT #10** 2021-09-03 08:20 351026899966 **MOT** test number Result × Failed **Advice** Nearside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i)) **MAJOR** Front Windscreen washer provides insufficient washer liquid (3.5 (a)) **Advice** Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i)) Advice Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i)) **Advice** Offside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i)) Advice Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i)) Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i)) **Advice** 

MOT #9	2020-08-30 14:46
MOT test number	696066146545
Result	✓ Passed
MOT #8	2019-08-09 08:43

MOT test number 216124943617

Result 

Passed

MOT #7 2019-08-08 08:22

MOT test number 420134969901

**Result** ★ Failed

**MAJOR** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MAJOR Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT #6

MOT test number

269857431111

Result

Advice Rear brake discs corroded

Advice Offside Front cv boot split and leaking

MOT #5

MOT test number

Passed

Advice Offside Rear Nail in tyre non repairable

Advice Rear Inner Brake pad(s) wearing thin (3.5.1g)

Advice Front Inner Brake pad(s) wearing thin (3.5.1g)

MOT #4

MOT test number

Result

Advice

Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice

Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #3

MOT test number

830826904787


Result

Advice Front Inner Brake pad(s) wearing thin (3.5.1g)

CarCheck.co.uk page 5/13



report date: 2024-03-29



MOT #1	2014-08-18 14:53
MOT test number	476050534286
Result	<b>×</b> Failed
Notice Engine covers fitted obscuring some components in the engine bay	
Fail Nearside Rear coil spring broken (2.4.C.1a)	
Advice Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)	
Notice Under-trays fitted obscuring some underside components	
Advice Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)	
Advice Nearside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)	

CarCheck.co.uk page 6/13



report date: 2024-03-29

#### Tax & MOT check





Expired: 20 February 2024

Tax status	Valid until 1 August
Days left	94
MOT expiry date	20 February 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-

CarCheck.co.uk page 7/13




report date: 2024-03-29

#### Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



faste since

SW61LXH

report date: 2024-03-29

More info >

# Owner history For how long did the current and previous owner(s) have this BMW? How many owners did this BMW have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this BMW had different number plates. obser of plates

CarCheck.co.uk page 10/13



report date: 2024-03-29

#### Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >


CarCheck.co.uk page 11/13



report date: 2024-03-29

## Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2011-09-09
Last registration	2023-01-30
Complete history	See info



Registration #1	2011-09-09	26 mi
Registration #2	2014-08-18	18.069 mi
Registration #3	2014-08-19	18.071 mi
Registration #4	2015-08-19	21.431 mi
Registration #5	2016-08-10	24.428 mi
Registration #6	2017-08-21	30.207 mi
Registration #7	2018-08-14	38.282 mi
Registration #8	2019-08-08	48.565 mi
Registration #9	2019-08-09	48.565 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		D.777 es
Registration #17		11.777 es
Registration #18		77.777 au

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-29

## Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
50567	
50569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1933 mm
Height	1776 mm
Length	4857 mm
Wheel base	2933 mm
Kerb weight	2110 kg
Max. allowed weight	2790 kg

# Additional information

Fuel tank capacity	85 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 13/13

Number of axles 2

Engine number 31387671