



report date: 2024-03-28

General information

Make	FIAT
Model	GRAND PUNTO DYNAMIC
Colour	Black
Year of manufacture	2009
Top speed	103 mph
0 - 60 mph	13.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	77 BHP
Max. torque	115 Nm at 3.000 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	41.5 mpg
Consumption extra urban	56.5 mpg
Consumption combined	49.6 mpg
CO2 emission	134 g/km
CO2 label	E





Internet history

Entry 1

Date	2022-01-10
Pictures	1
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2023-01-23
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	34
Total items failed	5

MOT #17 2023-09-20 08:19

MOT test number 653261787764

Result ✗ Failed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MAJOR Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))

MAJOR Exhaust has a major leak of exhaust gases flexi (6.1.2 (a))

MOT #16 2022-01-24 10:44

MOT test number 272810900045

Result ✓ Passed

MOT #15 2022-01-21 13:30

MOT test number 460569268303

Result ✗ Failed

MAJOR Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

DANGEROUS Offside Rear Tyre tread depth below requirements of 1.6mm Flat spot (5.2.3 (e))

DANGEROUS Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MOT #14**

2021-05-10 14:05

MOT test number

636716916195

Result

✓ Passed

Minor

Nearside Rear Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))

Advice

Nearside Front Oil leak, but not excessive gear box (8.4.1 (a) (i))

MOT #13

2021-05-06 14:14

MOT test number

854225993146

Result

✗ Failed

MAJOR

Nearside Front Position lamp not working (4.2.1 (a) (ii))

MAJOR

Central Rear Stop lamp(s) not working (4.3.1 (a) (ii))

DANGEROUS

Front Tyre tread depth below requirements of 1.6mm both inside edge (5.2.3 (e))

MAJOR

Front Exhaust has a major leak of exhaust gases (6.1.2 (a))

Advice

Nearside Rear revers lamp not working

MAJOR

Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

Advice

Nearside Front Outer Tyre slightly damaged cut (5.2.3 (d) (ii))

MAJOR

Front Anti-roll bar linkage ball joint excessively worn both side (5.3.4 (a) (i))

MOT #12

2020-03-04 14:16

MOT test number

932663766554

Result

✓ Passed

Advice

Offside Rear Coil spring corroded (5.3.1 (b) (i))

Advice

Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Advice

Nearside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #11**

2020-03-02 15:12

MOT test number

189827133950

Result

✗ Failed

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt**MAJOR** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**Minor** Nearside Rear All position lamps with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**MOT #10**

2019-04-09 15:25

MOT test number

581144565982

Result

✓ Passed

Minor Offside Front Upper Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Child Seat fitted not allowing full inspection of adult belt**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #9**

2018-04-09 10:00

MOT test number

479936238438

Result

✓ Passed

Advice Child Seat fitted not allowing full inspection of adult belt**Advice** Oil leak gearbox**MOT #8**

2017-04-14 11:28

MOT test number

881585647877

Result

✓ Passed

Advice Nearside Front Anti-roll bar has slight play in a ball joint drop link (2.4.G.2)

**MOT #7** 2016-04-04 09:44**MOT test number** 891032638655**Result** ✓ Passed**MOT #6** 2016-04-01 15:57**MOT test number** 630495976212**Result** ✗ Failed

- Fail** Nearside Front Direction indicator incorrect colour (1.4.A.2f)
- Fail** Offside Front Front position lamp(s) not working (1.1.A.3b)
- Fail** Offside Front Anti-roll bar linkage worn and seriously weakened (2.4.G.1)
- Fail** Offside Front Direction indicator incorrect colour (1.4.A.2f)
- Fail** Nearside Front Anti-roll bar linkage worn and seriously weakened (2.4.G.1)

MOT #5 2015-12-09 11:35**MOT test number** 156036025749**Result** ✓ Passed**MOT #4** 2014-12-18 11:02**MOT test number** 499482754336**Result** ✓ Passed**MOT #3** 2013-11-20 10:50**MOT test number** 447774623439**Result** ✓ Passed

- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #2	2012-12-13 11:43
MOT test number	468718042406
Result	✓ Passed

MOT #1	2012-01-14 10:25
MOT test number	625204612066
Result	✓ Passed



Damage history


Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-02-05
Last registration	2023-09-20
Complete history	See info



Registration #1	2009-02-05	17 mi
Registration #2	2012-01-14	10.660 mi
Registration #3	2012-12-13	16.134 mi
Registration #4	2013-11-20	21.912 mi
Registration #5	2014-12-18	28.561 mi
Registration #6	2015-12-09	33.142 mi
Registration #7	2016-04-01	33.249 mi
Registration #8	2016-04-04	33.249 mi
Registration #9	2017-04-14	36.854 mi
Registration #10	2019-05-20	35.377 mi
Registration #11	2019-05-20	35.377 mi
Registration #12	2019-05-20	35.377 mi
Registration #13	2019-05-20	35.377 mi
Registration #14	2019-05-20	35.377 mi
Registration #15	2019-05-20	35.377 mi
Registration #16	2019-05-20	35.377 mi
Registration #17	2019-05-20	35.377 mi
Registration #18	2019-05-20	35.377 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4030 mm
Wheel base	2510 mm
Kerb weight	1025 kg
Max. allowed weight	1585 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5

Number of axles	2
Engine number	4924076