



TOYOTA



report date: 2024-03-29

General information

Make	TOYOTA
Model	CELICA VVTI BLUE
Colour	Black
Year of manufacture	2005
Top speed	127 mph
0 - 60 mph	8.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	172 Nm at 4.200 rpm
Engine capacity	1.794 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.4 mpg
Consumption extra urban	45.6 mpg
Consumption combined	36.7 mpg
CO2 emission	185 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-06-14
Pictures	24
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-01-25
MOT pass rate	71 %
MOT passed	15
Failed MOT tests	6
Total advice items	48
Total items failed	8

MOT #21	2023-01-25 15:08
MOT test number	939992243446
Result	✓ Passed
Next expiry date	2024-01-25

MOT #20	2023-01-25 11:23
MOT test number	471199684175
Result	✗ Failed
MAJOR	Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
MAJOR	Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
MAJOR	Exhaust carbon monoxide content at idle exceeds default limits (8.2.1.2 (b))
MAJOR	Nearside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
DANGEROUS	Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
MAJOR	Exhaust carbon monoxide content at idle exceeds manufacturer's specified limits (8.2.1.2 (b))
MAJOR	Parking brake efficiency below requirements (1.4.2 (a) (i))

MOT #19	2022-01-26 17:15
MOT test number	222855922951
Result	✓ Passed

**MOT #18** 2020-12-17 17:02**MOT test number** 853699034481**Result** ✓ Passed**Advice** Slight blow on exhaust**MOT #17** 2019-06-18 08:51**MOT test number** 617687998146**Result** ✓ Passed**MOT #16** 2018-06-02 10:53**MOT test number** 396351405969**Result** ✓ Passed**MOT #15** 2018-05-25 11:56**MOT test number** 956350385910**Result** ✗ Failed**Advice** Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MAJOR** Brake lever has insufficient reserve travel (1.1.2 (a))**Advice** Offside Rear Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MAJOR** Emissions not tested lambda too high (8.2.1.2 (d))**Advice** Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Fuel Pipe/s corroded filler pipe**MAJOR** Rear Exhaust has a major leak of exhaust gases back box (6.1.2 (a))

**MOT #14** 2017-05-20 13:16**MOT test number** 680740894325**Result** ✓ Passed**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #13** 2016-05-25 14:10**MOT test number** 103449736625**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Slight play in drag link**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #12** 2015-05-02 11:50**MOT test number** 768222425129**Result** ✓ Passed**Notice** Both rear tyres starting to go out of shape**Advice** Offside Rear position lamp(s) damaged, but still visible from a reasonable distance (1.1.A.3d)**MOT #11** 2015-04-25 11:31**MOT test number** 816335015163**Result** ✗ Failed**Advice** Offside Rear position lamp(s) damaged, but still visible from a reasonable distance (1.1.A.3d)**Fail** Offside Registration plate lamp not working (1.1.C.1d)**Notice** Both rear tyres starting to go out of shape**Fail** Nearside Registration plate lamp not working (1.1.C.1d)

**MOT #10** 2014-05-13 14:43**MOT test number** 739533134101**Result** ✓ Passed**Notice** Cut To O/s Front Tyre Wall (not to cord)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #9** 2014-05-13 12:15**MOT test number** 765103434142**Result** ✗ Failed**Notice** Cut To O/s Front Tyre Wall (not to cord)**Fail** Offside Headlamp excessively deteriorated so that the light output is severely reduced (1.7.5a)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #8** 2013-05-07 16:10**MOT test number** 536127923196**Result** ✓ Passed**MOT #7** 2013-05-07 09:29**MOT test number** 228957523476**Result** ✗ Failed**Notice** Travel on parking brake lever**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Offside Front Headlamp aim too high and too far to the right. (1.8)**Notice** Off side rear parking brake effort low (at time of mot)**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**Fail** Parking brake: efficiency below requirements (3.7.B.7)



MOT #6	2012-04-28 10:23
MOT test number	756549812120
Result	✓ Passed
Advice	Parking brake lever has little reserve travel (3.1.6b)

MOT #5	2011-05-07 13:36
MOT test number	887737021180
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Front Brake pad(s) wearing thin (3.5.1g)
Advice	Nearside Rear Brake pad(s) wearing thin (3.5.1g)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Front Brake pad(s) wearing thin (3.5.1g)
Advice	Offside Rear Brake pad(s) wearing thin (3.5.1g)
Notice	Rear tyres worn uneven

**MOT #4** 2011-05-07 13:36**MOT test number** 309677221137**Result** ✗ Failed**Pass with rectification** Offside Front Headlamp not working on dipped beam (1.7.5a)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Rear tyres worn uneven**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**MOT #3** 2010-05-08 11:34**MOT test number** 900258720186**Result** ✓ Passed**MOT #2** 2009-05-06 10:02**MOT test number** 244196029115**Result** ✓ Passed**Advice** Rear brake disc slightly pitted (3.5.1h)**MOT #1** 2008-05-03 13:32**MOT test number** 201384528401**Result** ✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 June 2024

✗
MOT

Expired:
25 January 2024

Tax status	Valid until 1 June
Days left	32
MOT expiry date	25 January 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	YE05CWZ
Plate since	2019-03-29
Current registration	YE05CWZ
Plate since	2019-03-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2005-05-09
Last registration	2023-01-25
Complete history	See info



Registration #1	2005-05-09	9 mi
Registration #2	2008-05-03	32.624 mi
Registration #3	2009-05-06	42.509 mi
Registration #4	2010-05-08	49.714 mi
Registration #5	2011-05-07	57.172 mi
Registration #6	2012-04-28	63.636 mi
Registration #7	2013-05-07	70.196 mi
Registration #8	2013-05-07	70.198 mi
Registration #9	2014-05-13	77.888 mi
Registration #10	2014-05-13	77.888 mi
Registration #11	2015-04-25	84.375 mi
Registration #12	2015-05-20	91.875 mi
Registration #13	2015-05-20	91.875 mi
Registration #14	2015-05-20	91.875 mi
Registration #15	2015-05-20	91.875 mi
Registration #16	2015-05-20	91.875 mi
Registration #17	2015-05-20	91.875 mi
Registration #18	2015-05-20	91.875 mi
Registration #19	2015-05-20	91.875 mi
Registration #20	2015-05-20	91.875 mi
Registration #21	2015-05-20	91.875 mi
Registration #22	2015-05-20	91.875 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1735 mm
Height	1315 mm
Length	4350 mm
Wheel base	2600 mm
Kerb weight	1145 kg
Max. allowed weight	1565 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	1ZZ2317949