





report date: 2024-03-29

General information

Make	FORD
Model	S-MAX GHIA TDCI
Colour	Black
Year of manufacture	2009
Top speed	120 mph
0 - 60 mph	10.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	143 BHP	
Max. torque	340 Nm at 2.000 rpm	
Engine capacity	1.997 сс	
Cylinders	4	
Fuel type	Diesel	
Consumption city	34.5 mpg	
Consumption extra urban	51.4 mpg	
Consumption combined	43.5 mpg	
CO2 emission	159 g/km	
CO2 label	G	



CarCheck.co.uk page 1/13




Internet history

Entry 1

Date 2021-08-13


Pictures 12

Listing price View report









source: cargurus.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2024-08-29
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	21
Total items failed	6

MOT #13	2023-08-30 11:58	
MOT test number	871857694058	
Result	✓ Passed	
Next expiry date	2024-08-29	
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened discs worn and lightly scored (1.1.14 (a) (ii))		
Minor Battery insecure but not likely to fall from carrier (4.13 (a) (i))		
Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))		

MOT #12	2023-08-16 14:46
MOT test number	960929237935
Result	X Failed
Fail Central Exhaust has a major leak of exhaust gases (6.1.2 (a))	
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice Suspension arm corroded but not seriously weakened both rear (5.3.3 (b) (i))	
Fail Exhaust emissions exceed manufacturer's specified limit 1.51 (8.2.2.2 (a))	
Fail (a) (ii)) Electrical wiring insecure and connectors likely to become disconnected live terming the connected live terming t	inal for battery (4.11
Advice Suspension arm corroded but not seriously weakened both front (5.3.3 (b) (i))	
Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))	

CarCheck.co.uk page 3/13



MOT test number

SL59JCJ report date: 2024-03-29

702003993412

MOT test number

Result

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

 MOT #10
 2021-08-17 16:01

 MOT test number
 986087303594

 Result
 ✓ Passed

MOT #9 2018-10-04 08:52

MOT test number 188385270406

Result ✓ Passed

MOT #8

MOT test number

299632646997

Result

Fail Front Windscreen washer not working (3.5 (a))

MOT #7 2017-10-25 12:17

Result ✓ Passed

MOT #6 2016-10-31 10:29

MOT test number 168043073750

Advice Engine cover and engine undertray fitted

Advice Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

CarCheck.co.uk page 4/13



MOT #5 2016-10-28 14:39

MOT test number 559729678312

Result X Failed

Fail Rear Brake lining(s) less than 1.5 mm thick (3.5.1g)

Advice Engine cover and engine undertray fitted

Advice Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Fail Rear Direction indicators incorrect colour (1.4.A.2f)

MOT #4 2015-10-23 11:56

MOT test number 923266808435

Result \rightarrow Passed

Advice Nearside Rear rear pads getting low

Advice Offside Rear pads getting low

MOT #3 2014-10-24 13:55

MOT test number 929087794203

Result
✓ Passed

Advice Nearside Rear Direction indicators slightly discoloured (1.4.A.2f)

Notice Engine covers fitted obscuring some components in the engine bay

Advice Offside Rear Direction indicators slightly discoloured (1.4.A.2f)

Notice Under-trays fitted obscuring some underside components

MOT #2 2013-10-25 12:56

MOT test number 587968293216

Result \rightarrow Passed

CarCheck.co.uk page 5/13



MOT #1 2012-10-26 13:48

MOT test number 618700802369

CarCheck.co.uk page 6/13



Tax & MOT check



Tax status	Valid until 1 August
Days left	93
MOT expiry date	29 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 7/13



SL59JCJ

report date: 2024-03-29

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

o milet mestery	
For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report	

THE STATE OF THE S	
THE STREET STREE	
	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	
Current registration	NK SIN
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 10/13



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2009-10-30
Last registration	2023-08-30
Complete history	See info



Registration #1	2009-10-30	25 mi
Registration #2	2012-10-26	13.841 mi
Registration #3	2013-10-25	18.170 mi
Registration #4	2014-10-24	32.169 mi
Registration #5	2015-10-23	28.129 mi
Registration #6	2016-10-28	32.965 mi
Registration #7	2016-10-31	32.967 mi
Registration #8	2017-10-25	36.443 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		D.777 es

More info >

CarCheck.co.uk page 12/13



Car features

50225	Air conditionin
50295	
60482	
60501	
0566	
60567	
60569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1884 mm
Height	1736 mm
Length	4820 mm
Wheel base	2850 mm
Kerb weight	1933 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 13/13

Number of axles 2

Engine number 9K79192