



report date: 2024-03-29

General information

Make	VOLVO
Model	XC60 D3 SE
Colour	Silver
Year of manufacture	2010
Top speed	130 mph
0 - 60 mph	9.2 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	161 BHP
Max. torque	400 Nm at 1.400 rpm
Engine capacity	1.984 cc
Cylinders	5
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	47.9 mpg
CO2 emission	154 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-02-06
Pictures	1
Listing price	View report



source: autoonline.co.uk



MOT history

MOT expiry date	2025-03-06
MOT pass rate	67 %
MOT passed	12
Failed MOT tests	6
Total advice items	23
Total items failed	10

MOT #18	2024-03-06 16:07
MOT test number	831930385251
Result	✓ Passed
Next expiry date	2025-03-06
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #17	2024-03-06 16:07
MOT test number	601688870765
Result	✗ Failed
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt
Pass with rectification	Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

MOT #16	2023-03-07 15:52
MOT test number	881246780657
Result	✓ Passed

**MOT #15** 2023-03-06 17:25**MOT test number** 946635535259**Result** ✗ Failed**Fail** Central Exhaust system insecure (6.1.2 (a))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**MOT #14** 2022-02-08 10:50**MOT test number** 627603438083**Result** ✓ Passed**Advice** Driver's view Items removed from driver's view prior to test (3.1 (a) (ii))**Advice** Vehicles internal headlight adjuster altered to recheck lights**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Offside Rear tyre worn inner edge and perishing**MOT #13** 2021-02-23 11:29**MOT test number** 892125845149**Result** ✓ Passed**MOT #12** 2020-12-08 16:44**MOT test number** 177133848091**Result** ✓ Passed

**MOT #11** 2020-11-04 12:42**MOT test number** 719616322348**Result** ✗ Failed**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Nearside Rear Rear fog lamp with a multiple light source up to 1/2 not functioning (4.5.1 (a) (i))**Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))**Advice** Offside Rear Suspension rod pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Nearside Rear Suspension rod pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #10** 2019-11-20 15:19**MOT test number** 376415062367**Result** ✓ Passed**MOT #9** 2019-11-20 10:18**MOT test number** 930910366609**Result** ✗ Failed**Fail** Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Pass with rectification** Offside Front Headlamp aim too low (4.1.2 (a))**Advice** Front Tyre worn close to legal limit/worn on edge Both. (5.2.3 (e))**MOT #8** 2018-11-14 14:07**MOT test number** 824706323555**Result** ✓ Passed**Advice** Front Inner Brake disc worn, but not excessively both front (1.1.14 (a) (i))

**MOT #7** 2017-12-06 11:21**MOT test number** 236446969135**Result** ✓ Passed**Advice** Offside Front tyre very worn on inner edge**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2017-12-05 10:41**MOT test number** 159379973731**Result** ✗ Failed**Fail** Offside Headlamp aim too high (1.8)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Headlamp aim too high (1.8)**Fail** Nearside Rear coil spring broken (2.4.C.1a)**Advice** Offside Front tyre very worn on inner edge**MOT #5** 2016-12-07 16:15**MOT test number** 938889629217**Result** ✓ Passed**MOT #4** 2016-12-07 16:15**MOT test number** 441986159287**Result** ✗ Failed**Pass with rectification** Nearside Rear Registration plate lamp not working (1.1.C.1d)



MOT #3	2015-11-11 11:46
MOT test number	908872007250
Result	✓ Passed
Advice	Rear Brake pad(s) wearing thin (3.5.1g)
Advice	Rear brake discs poor

MOT #2	2014-11-05 14:08
MOT test number	439479104458
Result	✓ Passed

MOT #1	2013-09-18 09:53
MOT test number	128431563254
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
6 March 2025

Tax status	Valid until 1 March
Days left	305
MOT expiry date	6 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2010-10-15
Last registration	2024-03-06
Complete history	See info



Registration #1	2010-10-15	27 mi
Registration #2	2013-09-18	34.992 mi
Registration #3	2014-11-05	46.589 mi
Registration #4	2015-11-11	51.940 mi
Registration #5	2016-12-07	60.703 mi
Registration #6	2016-12-07	60.703 mi
Registration #7	2017-12-05	68.362 mi
Registration #8	2017-12-06	68.372 mi
Registration #9	2018-11-14	75.068 mi
Registration #10	2019-11-20	82.355 mi
Registration #11	2019-11-20	82.355 mi
Registration #12	2019-11-20	82.355 mi
Registration #13	2019-11-20	82.355 mi
Registration #14	2019-11-20	82.355 mi
Registration #15	2019-11-20	82.355 mi
Registration #16	2019-11-20	82.355 mi
Registration #17	2019-11-20	82.355 mi
Registration #18	2019-11-20	82.355 mi
Registration #19	2019-11-20	82.355 mi
Registration #20	2019-11-20	82.355 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1861 mm
Height	1493 mm
Length	4851 mm
Wheel base	2835 mm
Kerb weight	1684 kg
Max. allowed weight	2200 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	882769