



PEUGEOT



report date: 2024-03-29

General information

Make	PEUGEOT
Model	206 VERVE E4
Colour	Red
Year of manufacture	2006
Top speed	106 mph
0 - 60 mph	14.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	74 BHP
Max. torque	120 Nm at 3.400 rpm
Engine capacity	1.360 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	44.1 mpg
CO2 emission	152 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-07-12
Pictures	20
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-06-29
MOT pass rate	75 %
MOT passed	15
Failed MOT tests	5
Total advice items	29
Total items failed	10

MOT #20	2023-06-30 12:03
MOT test number	570265951598
Result	✓ Passed
Next expiry date	2024-06-29
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Minor	Nearside Front Windscreen wiper blade defective (3.4 (b) (i))
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
Advice	Front Brake pad(s) wearing thin BOTH (1.1.13 (a) (ii))
Advice	Nearside Front Play in steering rack inner joint(s)
Advice	Nearside Front Headlamp has a product on the lens but not seriously reducing light output CONDENSATION (4.1.4 (b))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened BOTH (1.1.14 (a) (ii))
Advice	Front Anti-roll bar linkage ball joint has slight play BOTH (5.3.4 (a) (i))

**MOT #19**

2023-06-30 09:03

**MOT test number**

289318124806

**Result****✗ Failed**

- Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened BOTH (1.1.14 (a) (ii))
- Fail** Exhaust has a major leak of exhaust gases (6.1.2 (a))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))
- Minor** Nearside Front Windscreen wiper blade defective (3.4 (b) (i))
- Advice** Nearside Front Play in steering rack inner joint(s)
- Advice** Front Anti-roll bar linkage ball joint has slight play BOTH (5.3.4 (a) (i))
- Fail** Exhaust carbon monoxide content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))
- Advice** Front Brake pad(s) wearing thin BOTH (1.1.13 (a) (ii))
- Advice** Nearside Front Headlamp has a product on the lens but not seriously reducing light output  
CONDENSATION (4.1.4 (b))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

**MOT #18**

2022-06-25 11:14

**MOT test number**

819251466363

**Result****✓ Passed****MOT #17**

2021-06-29 09:41

**MOT test number**

482176418535

**Result****✓ Passed**

**MOT #16** 2021-05-29 11:53**MOT test number** 192273933281**Result** ✗ Failed**Fail** Exhaust carbon monoxide content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))**Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**MOT #15** 2020-08-24 10:29**MOT test number** 639674302703**Result** ✓ Passed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #14** 2019-08-27 10:46**MOT test number** 263039291821**Result** ✓ Passed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #13** 2018-08-30 13:53**MOT test number** 243741387382**Result** ✓ Passed**MOT #12** 2018-08-30 13:53**MOT test number** 971641128607**Result** ✗ Failed**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**MOT #11** 2017-09-12 10:52**MOT test number** 707746990557**Result** ✓ Passed**Advice** Rear tyres have slightly deteriorated**MOT #10** 2016-10-18 11:28**MOT test number** 801061621287**Result** ✓ Passed**MOT #9** 2016-10-18 11:28**MOT test number** 186596665088**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too high (1.8)**MOT #8** 2015-10-29 11:39**MOT test number** 599020162367**Result** ✓ Passed**Advice** Exhaust rear silencer outer skin corroded**MOT #7** 2014-10-30 12:21**MOT test number** 488553504484**Result** ✓ Passed**Notice** Exhaust back box outer skin corroded**Notice** Both rear tyres starting to crack on sidewalls

**MOT #6** 2014-10-29 11:01**MOT test number** 328032304357**Result** ✗ Failed

- Notice** Play in steering rack inner joint(s)
- Fail** Nearside Steering rack gaiter insecure (2.2.D.2d)
- Notice** Both rear tyres starting to crack on sidewalls
- Notice** Exhaust back box outer skin corroded

**MOT #5** 2013-10-30 13:43**MOT test number** 519113203324**Result** ✓ Passed

- Advice** Nearside Track rod end ball joint has slight play (2.2.B.1f)

**MOT #4** 2012-11-01 13:01**MOT test number** 468456102426**Result** ✓ Passed**MOT #3** 2011-10-25 09:08**MOT test number** 175858991223**Result** ✓ Passed**MOT #2** 2010-10-26 11:19**MOT test number** 691739090208**Result** ✓ Passed**MOT #1** 2009-10-26 09:06**MOT test number** 842529899293**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
  
Tax due:  
1 June 2024

✓  
**MOT**  
  
Expires:  
29 June 2024

Tax status	Valid until 1 June
Days left	32
MOT expiry date	29 June 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-





Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2006-11-08
Last registration	2023-06-30
Complete history	<a href="#">See info</a>



Registration #1	2006-11-08	17 mi
Registration #2	2009-10-26	13.685 mi
Registration #3	2010-10-26	17.920 mi
Registration #4	2011-10-25	22.737 mi
Registration #5	2012-11-01	27.195 mi
Registration #6	2013-10-30	52.350 mi
Registration #7	2014-10-29	37.278 mi
Registration #8	2014-10-30	37.281 mi
Registration #9	2015-10-29	41.872 mi
Registration #10	2016-10-18	43.805 mi
Registration #11	2016-10-18	43.805 mi
Registration #12	2016-10-18	43.805 mi
Registration #13	2016-10-18	43.805 mi
Registration #14	2016-10-18	43.805 mi
Registration #15	2016-10-18	43.805 mi
Registration #16	2016-10-18	43.805 mi
Registration #17	2016-10-18	43.805 mi
Registration #18	2016-10-18	43.805 mi
Registration #19	2016-10-18	43.805 mi
Registration #20	2016-10-18	43.805 mi
Registration #21	2016-10-18	43.805 mi
Registration #22	2016-10-18	43.805 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Dimensions & weight

Width	1652 mm
Height	1433 mm
Length	3822 mm
Wheel base	2445 mm
Kerb weight	1025 kg
Max. allowed weight	1450 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	FST65298536