





report date: 2024-03-28

General information

Make	HYUNDAI
Model	SANTA FE CRDI PREMIUM SE
Colour	Silver
Year of manufacture	2014
Top speed	118 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	194 BHP
Max. torque	422 Nm at 2.500 rpm
Engine capacity	2.199 сс
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	54.3 mpg
Consumption combined	46.3 mpg
CO2 emission	159 g/km
CO2 label	G



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 2

Date 2021-08-01

Pictures 5

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date 2021-07-31
Pictures 5

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2025-01-28
MOT pass rate	89 %
MOT passed	8
Failed MOT tests	1
Total advice items	13
Total items failed	2

MOT #9	2024-01-25 15:02
MOT test number	266340699391
Result	✓ Passed
Next expiry date	2025-01-28

MOT #8	2024-01-25 09:17
MOT test number	501209291458
Result	★ Failed
Fail Offside Rear Tyre has ply or cord	ds exposed (5.2.3 (d) (ii))
Fail Nearside Rear Tyre has ply or co	rds exposed (5.2.3 (d) (ii))

MOT #7	2023-01-24 08:23
MOT test number	936869194838
Result	✓ Passed

MOT #6	2022-01-22 09:45
MOT test number	370079125994
Result	✓ Passed

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #5 2021-01-16 09:34 **MOT test number** 774216737815 Result ✓ Passed **Advice** Offside rear tyre bald inner edge close to cords Brake fluid close to minimum mark (1.1.10 (d) (ii)) Advice Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Advice Nearside rear tyre wearing inner edge Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) **Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #4		2020-01-28 11:01
MOT test	number	142620859618
Result		✓ Passed
Advice	Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Front tyres wearing inner edges.	
Advice	Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Rear Child Seat fitted not allowing full inspection of adult belt 3 seats fitted.	

MOT #3	2019-01-14 10:46
MOT test number	351358492358
Result	✓ Passed
MOT #2	2018-01-29 16:19
MOT test number	304614406963
Result	✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #1		2017-04-06 10:55
MOT test	number	145463518171
Result		✓ Passed
Advice	Offside Front Brake pad(s) wearing thin (3.5.1g)	
Advice	Nearside Front Brake pad(s) wearing thin (3.5.1g)	

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 October
Days left	155
MOT expiry date	28 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

Owner history	
For how long did the current and previous owner(s) have this HYUNDAI? How many owner have? Check it in the premium report and see all owner registrations. Download the full	

	More info >
Plate changes	
See in this check if this HYUNDAI had different number plates.	
Number of plates	
Current registration	SIF. GIS
Plate since	990.0.0
Current registration	NE SIE
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Courts at info	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-04-15
Last registration	2024-01-25
Complete history	See info



Registration #1	2014-04-15	20 mi
Registration #2	2017-04-06	26.971 mi
Registration #3	2018-01-29	29.769 mi
Registration #4	2019-01-14	45.930 mi
Registration #5	2020-01-28	63.790 mi
Registration #6	2021-01-16	74.900 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		10.777 es

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditionin
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	96%
Children	89%
Pedestrian	71%
Safety systems	86%
Overall rating	89%
Video	see crash video



Dimensions & weight

Width	1880 mm
Height	1690 mm
Length	4690 mm
Wheel base	2700 mm
Kerb weight	1963 kg
Max. allowed weight	2600 kg

Additional information

Fuel tank capacity	64 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 12/1

Number of axles 2

Engine number D4HBDU923293