





### General information

Make	FIAT
Model	500L MULTIJET POP STAR DUALOGIC
Colour	Grey
Year of manufacture	2016
Top speed	102 mph
0 - 60 mph	15.1 seconds
Gearbox	5 speed automatic

## Engine & fuel consumption

Power	85 BHP
Max. torque	200 Nm at 1.500 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	62.8 mpg
Consumption extra urban	76.4 mpg
Consumption combined	70.6 mpg
CO2 emission	105 g/km
CO2 label	В







## Internet history

Entry 3

Date

Pictures

2023-12-12

8



#### source: g3remarketing.co.uk

Entry	2
Entry	2

Date	2021-07-08
Pictures	0
Listing price	View report

#### source: cargurus.co.uk

Entry 1	
Date	2021-07-07
Pictures	0
Listing price	View report

source: autotrader.co.uk



## MOT history

MOT expiry date	2025-02-23
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	18
Total items failed	5

MOT #8	2024-02-21 10:59
MOT test number	661952475326
Result	✓ Passed
Next expiry date	2025-02-23
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Minor (b) (i)) Offside Rear Registration plate lamp missing in the case of multiple lamps or	light sources (4.7.1

MOT #7	2023-02-23 12:16
MOT test	<b>number</b> 252462743366
Result	✓ Passec
Advice	Nearside Front Tyre slightly damaged/cracking or perishing tyre wearing on edges (5.2.3 (d) (ii))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
<b>Minor</b> (b) (i))	Offside Rear Registration plate lamp missing in the case of multiple lamps or light sources (4.7.1
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))





MOT #6		2022-02-24 14:33
MOT test	number	496850675046
Result		✓ Passed
Advice Minor (b) (i))	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Offside Rear Registration plate lamp missing in the case of multiple lamps or	r light sources (4.7.1

MOT #5	2022-02-23 13:12
MOT test number	323625553990
Result	🗙 Failed
Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b)	(ii))
Minor (b) (i)) Offside Rear Registration plate lamp missing in the case of multiple lamps or light	sources (4.7.1
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice Front Brake disc worn, but not excessively both sides (1.1.14 (a) (i))	
Advice Nearside Rear Nail in tyre	
Fail Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii	))
Fail Offside Front Outer Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
<b>Fail</b> Offside Front Tyre has ply or cords exposed cut to tyre tread (5.2.3 (d) (ii))	

MOT #4	2021-02-20 12:02
MOT test number	964821978729
Result	✓ Passed
AdviceNearside Rear Child Seat fitted not allowing full inspection of adult beltAdviceRear Tyre slightly damaged/cracking or perishing both side (5.2.3 (d) (ii))	

MOT #3	2020-02-13 09:46
MOT test number	477775187029
Result	✓ Passed





MOT #2	2019-02-19 16:54
MOT test number	594479944609
Result	✓ Passed
MOT #1	2019-02-19 14:35
MOT test number	371562235819
Result	× Failed
Advice Nearside front tyre worn and damaged on outer side wall	
FailNearside Stop lamp(s) not working (4.3.1 (a) (ii))	



Tax & MOT check

✓ Taxed Tax due: 1 December 2024	✓ MOT Expires: 23 February 2025
Tax status	Valid until 1 December
Days left	216
MOT expiry date	23 February 2025
Full MOT history	See MOT history
Tax calculation	

Vehicle class	49
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-





#### Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FEIDO
Category	4. ARMPE
Туре	
Damage 2	AMPL
	F Stores
Date	1.E
Category	ante
Туре	

#### Extra FIAT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4





## Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

xxxxxxxx	
************	
********	
*******	
************	
********	
	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Carrent registration	
Plate since	
	More info >





#### Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	



FG16WUW report date: 2024-03-28

## Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2016-03-23
Last registration	2024-02-21
Complete history	See info



Registration #1	2016-03-23	28 mi
Registration #2	2019-02-19	20.520 mi
Registration #3	2019-02-19	20.540 mi
Registration #4	2020-02-13	25.439 mi
Registration #5	2021-02-20	34.167 mi
Registration #6		11.777 est
Registration #7		11.777 mi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.117 esi



# FG16WUW report date: 2024-03-28

## Car features

S0225	Air conditionin
S0295	
S0482	
S0501	
\$0566	
\$0567	
S0569	

## Safety ratings

NCAP rating	****
Adult	94%
Children	78%
Pedestrian	65%
Safety systems	71%
Overall rating	83%
Video	see crash video



Dimensions & weight	
Width	2018 mm
Height	1667 mm
Length	4147 mm
Wheel base	2612 mm
Kerb weight	1320 kg
Max. allowed weight	1850 kg
Additional information	
Fuel tank capacity	50 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/12

Number of axles	2
Engine number	5771426