





report date: 2024-03-29

General information

| Make | SUZUKI |
|---------------------|----------------|
| Model | ALTO SZ |
| Colour | White |
| Year of manufacture | 2013 |
| Top speed | 96 mph |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 68 BHP |
|-------------------------|--------------------|
| Max. torque | 90 Nm at 3.400 rpm |
| Engine capacity | 996 cc |
| Cylinders | 3 |
| Fuel type | Petrol |
| Consumption city | 54.3 mpg |
| Consumption extra urban | 74.3 mpg |
| Consumption combined | 65.7 mpg |
| CO2 emission | 99 g/km |
| CO2 label | A |



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

Entry 1

Date 2021-02-04


Pictures 8

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/11



PE63EUC report date: 2024-03-29

MOT history

| MOT expiry date | 2025-02-16 |
|--------------------|------------|
| MOT pass rate | 82 % |
| MOT passed | 9 |
| Failed MOT tests | 2 |
| Total advice items | 3 |
| Total items failed | 3 |

| MOT #11 | 2024-02-16 10:59 |
|---|------------------|
| MOT test number | 999483615176 |
| Result | ✓ Passed |
| Next expiry date | 2025-02-16 |
| Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |

| MOT #10 | 2023-02-17 10:23 |
|--|------------------|
| MOT test number | 127269023790 |
| Result | ✓ Passed |
| Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |

| MOT #9 | 2022-02-08 12:49 |
|-----------------|------------------|
| MOT test number | 549245961168 |
| Result | ✓ Passed |

| MOT #8 | | 2022-02-08 12:49 |
|-------------------------|--|------------------|
| MOT test number | | 922784582139 |
| Result | | X Failed |
| Pass with rectification | Nearside Stop lamp(s) not working (4.3.1 (a) (ii)) | |

CarCheck.co.uk page 3/11



MOT #1

Result

Advice

MOT test number

Front Brake pad(s) wearing thin (3.5.1g)

PE63EUC

report date: 2024-03-29

2016-09-03 09:18

770866556217

✓ Passed

| MOT #7 | 2021-02-13 12:26 |
|-----------------------------------|--|
| MOT test number | 846129601317 |
| Result | ✓ Passed |
| | |
| MOT #6 | 2020-09-09 08:50 |
| MOT test number | 103389548757 |
| Result | ✓ Passed |
| | |
| MOT #5 | 2020-09-09 08:50 |
| MOT test number | 982938535484 |
| Result | ★ Failed |
| Pass with rectification (b) (ii)) | Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 |
| Pass with rectification (b) (ii)) | Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 |
| MOT #4 | 2019-08-31 10:25 |
| MOT test number | 802412043602 |
| Result | ✓ Passed |
| MOT #3 | 2018-09-08 09:16 |
| MOT test number | 663077957259 |
| Result | ✓ Passed |
| MOT #2 | 2017-09-09 09:06 |
| MOT test number | 895646102962 |
| Result | ✓ Passed |

CarCheck.co.uk page 4/11



report date: 2024-03-29

Tax & MOT check



| Tax status | Valid until 1 March |
|------------------|---------------------|
| Days left | 307 |
| MOT expiry date | 16 February 2025 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|---|----------------|
| Band | A |
| Single payment (12 months) | £ 0,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | Not applicable |

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|--|
| Date | |
| Category | |
| Туре | |
| Damage 2 | |
| Date | |
| Category | |
| Туре | |



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



PE63EUC report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



factor scincol

PE63EUC

report date: 2024-03-29

More info >

Owner history For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this SUZUKI had different number plates.

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this SUZUKI is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 13 |
| First mileage registration | 2013-09-13 |
| Last registration | 2024-02-16 |
| Complete history | See info |



| Registration #1 | 2013-09-13 | 8 mi |
|------------------|------------|-----------|
| Registration #2 | 2016-09-03 | 16.223 mi |
| Registration #3 | 2017-09-09 | 20.621 mi |
| Registration #4 | 2018-09-08 | 24.663 mi |
| Registration #5 | 2019-08-31 | 28.832 mi |
| Registration #6 | 2020-09-09 | 32.024 mi |
| Registration #7 | 2020-09-09 | 32.024 mi |
| Registration #8 | | 11.777 es |
| Registration #9 | | 11.777 mi |
| Registration #10 | | 11.777 es |
| Registration #11 | | 11.777 mi |
| Registration #12 | | 0.00 44 |
| Registration #13 | | 10.777 es |

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 55% |
| Children | 46% |
| Pedestrian | 35% |
| Safety systems | 29% |
| Overall rating | 47% |
| Video | see crash video |



Dimensions & weight

| Width | 1600 mm |
|---------------------|---------|
| Height | 1470 mm |
| Length | 3500 mm |
| Wheel base | 2360 mm |
| Kerb weight | 930 kg |
| Max. allowed weight | 1250 kg |

Additional information

| Fuel tank capacity | 35 I |
|--------------------|-----------------------|
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats | 4 |
| Number of axles | 2 |
| Engine number | K10BN 1660046 |

CarCheck.co.uk page 11/11