



HYUNDAI




report date: 2024-03-29

General information

Make	HYUNDAI
Model	MATRIX ATLANTIC
Colour	Blue
Year of manufacture	2008
Top speed	103 mph
0 - 60 mph	14.2 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	102 BHP
Max. torque	141 Nm at 4.500 rpm
Engine capacity	1.599 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.5 mpg
Consumption extra urban	42.8 mpg
Consumption combined	34.0 mpg
CO2 emission	198 g/km
CO2 label	J





Internet history

Entry 1

Date	2021-09-21
Pictures	33
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2024-10-24
MOT pass rate	78 %
MOT passed	14
Failed MOT tests	4
Total advice items	10
Total items failed	8

MOT #18	2023-10-25 10:35
MOT test number	148358505571
Result	✓ Passed
Next expiry date	2024-10-24
Minor	Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #17	2022-12-05 16:25
MOT test number	145970522704
Result	✓ Passed
Advice	Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Nearside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Offside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))

**MOT #16**

2022-12-05 13:22

**MOT test number**

708320330176

**Result****✗ Failed****Fail** Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Minor** Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Offside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))**Fail** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))**MOT #15**

2021-11-04 17:37

**MOT test number**

838230047274

**Result****✓ Passed****MOT #14**

2021-11-04 14:44

**MOT test number**

723592396657

**Result****✗ Failed****Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Offside Front Outer Prop shaft joint constant velocity boot no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #13**

2021-03-02 10:23

**MOT test number**

407952612967

**Result****✓ Passed**



<b>MOT #12</b>	2020-01-20 11:22
----------------	------------------

<b>MOT test number</b>	815247986143
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #11</b>	2019-01-16 10:05
----------------	------------------

<b>MOT test number</b>	646040185934
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #10</b>	2018-01-11 10:54
----------------	------------------

<b>MOT test number</b>	719472883290
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #9</b>	2017-01-11 11:23
---------------	------------------

<b>MOT test number</b>	246985166818
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #8</b>	2016-01-13 11:49
---------------	------------------

<b>MOT test number</b>	685796165353
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #7</b>	2015-01-12 12:52
---------------	------------------

<b>MOT test number</b>	946242115059
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #6</b>	2015-01-12 11:49
---------------	------------------

<b>MOT test number</b>	896032415048
------------------------	--------------

<b>Result</b>	✗ Failed
---------------	----------

<b>Fail</b>	Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
-------------	---

**MOT #5** 2014-01-16 14:53**MOT test number** 457046914024**Result** ✓ Passed**MOT #4** 2014-01-16 12:06**MOT test number** 289456714073**Result** ✗ Failed**Fail** Offside Front Front constant velocity joint is insecure (2.5.C.1b)**Fail** Nearside Front Front constant velocity joint is insecure (2.5.C.1b)**MOT #3** 2013-01-17 12:03**MOT test number** 628437213013**Result** ✓ Passed**MOT #2** 2012-01-23 14:43**MOT test number** 998583922043**Result** ✓ Passed**MOT #1** 2011-09-23 11:48**MOT test number** 358226961235**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 November 2024

✓  
**MOT**  
**Expires:**  
24 October 2024

<b>Tax status</b>	Valid until 1 November
<b>Days left</b>	185
<b>MOT expiry date</b>	24 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	J
<b>Single payment (12 months)</b>	£ 365,00,-
<b>Single six month payment</b>	£ 200,75,-
<b>Total payable by 12 monthly instalments</b>	£ 383,25,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	 
Plate since	2024-03-29
Current registration	 
Plate since	2024-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.


Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2008-10-27
Last registration	2023-10-25
Complete history	<a href="#">See info</a>



Registration #1	2008-10-27	28 mi
Registration #2	2011-09-23	15.011 mi
Registration #3	2012-01-23	16.917 mi
Registration #4	2013-01-17	19.006 mi
Registration #5	2014-01-16	21.240 mi
Registration #6	2014-01-16	21.240 mi
Registration #7	2015-01-12	23.173 mi
Registration #8	2015-01-12	23.173 mi
Registration #9	2016-01-13	24.494 mi
Registration #10	2017-01-11	25.425 mi
Registration #11	2018-01-11	26.356 mi
Registration #12	2018-01-11	26.356 mi
Registration #13	2018-01-11	26.356 mi
Registration #14	2018-01-11	26.356 mi
Registration #15	2018-01-11	26.356 mi
Registration #16	2018-01-11	26.356 mi
Registration #17	2018-01-11	26.356 mi
Registration #18	2018-01-11	26.356 mi
Registration #19	2018-01-11	26.356 mi
Registration #20	2018-01-11	26.356 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1740 mm
Height	1685 mm
Length	4050 mm
Wheel base	2600 mm
Kerb weight	1344 kg
Max. allowed weight	1820 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	G4ED7T009756