





report date: 2024-03-29

General information

Make	RENAULT
Model	MEGANE DYNAMIQUE TOMTOM VVT
Colour	Black
Year of manufacture	2013
Top speed	118 mph
0 - 60 mph	10.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	151 Nm at 4.250 rpm
Engine capacity	1.598 сс
Cylinders	4
Fuel type	Petrol
Consumption city	30.1 mpg
Consumption extra urban	51.4 mpg
Consumption combined	40.9 mpg
CO2 emission	159 g/km
CO2 label	G



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history

Entry 1


Date 2021-02-04

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/12



SA63CGX report date: 2024-03-29

MOT history

MOT expiry date	2025-03-12
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	14
Total items failed	9

MOT #10	2024-03-13 08:45
MOT test number	569620791179
Result	✓ Passed
Next expiry date	2025-03-12

MOT #9	2023-01-27 08:52
MOT test number	188793705899
Result	√ Passed

MOT #8		2021-11-26 13:03
MOT test	number	360037732902
Result		✓ Passed
Advice	Service brake binding but not excessively Both rear (1.2.1 (f))	
Minor	Nearside Windscreen wiper blade defective (3.4 (b) (i))	
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))	

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT #7 2021-11-26 13:03 **MOT** test number 371727288940 Result × Failed **Pass with rectification** Offside Headlamp aim too low (4.1.2 (a)) **Advice** Service brake binding but not excessively Both rear (1.2.1 (f)) Pass with rectification Nearside Headlamp aim too low (4.1.2 (a)) Advice Nearside Front Shock absorbers has light misting of oil (5.3.2 (b)) Minor Nearside Windscreen wiper blade defective (3.4 (b) (i)) Pass with rectification Nearside Front Headlamp are incorrectly positioned (4.1.4 (a))

MOT #6

MOT test number

436128541336

Result

√ Passed

MOT #5 2019-11-19 13:41 **MOT** test number 273049194577 Result ✓ Passed **Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b)) Advice Nearside Rear Service brake binding but not excessively (1.2.1 (f)) **Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) **Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))

MOT #4

MOT test number

518959982352

Result

✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #3 2017-11-30 17:00

MOT test number 744815031948

Result ✓ Passed

Advice

Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #2 2017-11-29 11:13

MOT test number 224962763739

Result X Failed

Fail Front position lamp(s) not working both sides (1.1.A.3b)

Fail Nearside Outer Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

Fail Nearside Front Suspension arm has excessive play in a ball joint (2.4.G.2)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Fail Nearside Headlamp aim too high (1.8)

Fail Offside Outer Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

Fail Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)

MOT #1 2016-08-26 10:27

MOT test number 153915530978

CarCheck.co.uk page 5/12



SA63CGX report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 September
Days left	124
MOT expiry date	12 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



SA63CGX report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

Owner history

Owner history	
For how long did the current and previous owner(s) have this RENAULT? How many owner have? Check it in the premium report and see all owner registrations. Download the full is	
presents .	

2000000	

	More info >
Plate changes	
See in this check if this RENAULT had different number plates.	
Number of plates	
Current registration	NK SIK
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2013-09-24
Last registration	2024-03-13
Complete history	See info



Registration #1	2013-09-24	12 mi
Registration #2	2016-08-26	15.499 mi
Registration #3	2017-11-29	22.508 mi
Registration #4	2017-11-30	22.524 mi
Registration #5	2018-11-21	28.867 mi
Registration #6	2019-11-19	35.197 mi
Registration #7		9.77 es
Registration #8		71.777 es
Registration #9		9.777 es
Registration #10		71.777 es
Registration #11		9.77 es
Registration #12		11.777 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
S0482	
50501	
50566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1804 mm
Height	1423 mm
Length	4299 mm
Wheel base	2641 mm
Kerb weight	1205 kg
Max. allowed weight	1746 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	5 page 12/12

Number of axles 2

Engine number D128084