



report date: 2024-03-29

General information

Make	VOLVO
Model	C30 D S
Colour	Silver
Year of manufacture	2007
Top speed	118 mph
0 - 60 mph	11.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	108 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	45.6 mpg
Consumption extra urban	67.3 mpg
Consumption combined	57.6 mpg
CO2 emission	129 g/km
CO2 label	D





Internet history

Entry 1

Date	2021-06-05
Pictures	10
Listing price	View report



source: yesauto.com



MOT history

MOT expiry date	2024-10-08
MOT pass rate	88 %
MOT passed	14
Failed MOT tests	2
Total advice items	31
Total items failed	2

MOT #16 2023-09-11 09:31

MOT test number 365507371524

Result ✓ Passed

Next expiry date 2024-10-08

Advice Rear Direction indicator slightly discoloured Nearside and offside rear (4.4.3 (a))

Minor Offside Front Upper Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #15 2022-09-30 09:24

MOT test number 966744890863

Result ✓ Passed

Advice Brake hose has slight corrosion to ferrule All have slight corrosion (1.1.12 (f) (i))

Advice General slight under body corrosion around suspension components and subframes

Advice Front Brake disc worn, pitted or scored, but not seriously weakened Both nearside and offside front brake discs are slightly corroded on inner faces (1.1.14 (a) (ii))

Advice Front Brake pads approx 75% worn

MOT #14 2021-10-08 08:13

MOT test number 910384953204

Result ✓ Passed

**MOT #13** 2021-10-08 08:13**MOT test number** 401642339105**Result** ✗ Failed**Pass with rectification** Offside Front Obligatory mirror missing (3.3 (a))**MOT #12** 2020-09-29 12:49**MOT test number** 289926478074**Result** ✓ Passed**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Protective undertrays fitted**MOT #11** 2019-10-09 13:11**MOT test number** 266924850200**Result** ✓ Passed**Advice** Protective undertrays fitted.**MOT #10** 2019-10-04 14:11**MOT test number** 592937281860**Result** ✗ Failed**Advice** Protective undertrays fitted.**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #9** 2018-10-02 11:19**MOT test number** 334226010311**Result** ✓ Passed**Advice** Rear Tyre worn close to legal limit/worn on edge both (5.2.3 (e))**Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement both (5.3.4 (a) (i))**Advice** Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))

**MOT #8** 2017-10-05 13:13**MOT test number** 364734505986**Result** ✓ Passed**Advice** Under tray and top engine and outer sills covers fitted obscuring some components**Advice** Offside Front Brake pipe slightly corroded coated with grease (3.6.B.2c)**MOT #7** 2016-10-04 08:40**MOT test number** 673319444719**Result** ✓ Passed**Advice** Covers on underside obscuring some components**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement rear (2.4.G.2)**Advice** Covers in engine bay obscuring some components**Advice** Offside Front brake pipe coated in grease**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement rear (2.4.G.2)**Advice** Covers over outer cills**MOT #6** 2015-09-25 14:02**MOT test number** 532040689748**Result** ✓ Passed**Advice** Under tray and top engine and outer sills covers fitted obscuring some components**MOT #5** 2014-09-24 10:52**MOT test number** 749327364201**Result** ✓ Passed**Notice** Cover over outer sills**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components

**MOT #4** 2013-10-04 11:39**MOT test number** 909907073255**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components**Notice** Cover over outer sills**MOT #3** 2012-09-28 10:19**MOT test number** 889462272279**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components**Notice** Cover over outer sills**MOT #2** 2011-10-04 11:40**MOT test number** 248317371202**Result** ✓ Passed**MOT #1** 2010-09-20 09:43**MOT test number** 840193260298**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
8 October 2024

Tax status	Valid until 1 August
Days left	94
MOT expiry date	8 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2007-09-29
Last registration	2023-09-11
Complete history	See info



Registration #1	2007-09-29	7 mi
Registration #2	2010-09-20	21.627 mi
Registration #3	2011-10-04	23.380 mi
Registration #4	2012-09-28	24.783 mi
Registration #5	2013-10-04	26.433 mi
Registration #6	2014-09-24	28.116 mi
Registration #7	2015-09-25	30.168 mi
Registration #8	2016-10-04	30.744 mi
Registration #9	2017-10-05	31.237 mi
Registration #10	2018-09-29	31.237 mi
Registration #11	2019-09-29	31.237 mi
Registration #12	2020-09-29	31.237 mi
Registration #13	2021-09-29	31.237 mi
Registration #14	2022-09-29	31.237 mi
Registration #15	2023-09-29	31.237 mi
Registration #16	2024-03-29	31.237 mi
Registration #17	2024-03-29	31.237 mi
Registration #18	2024-03-29	31.237 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4266 mm
Wheel base	2640 mm
Kerb weight	1368 kg
Max. allowed weight	1780 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	4

Engine number	146674
---------------	--------