




report date: 2024-03-29

General information

Make	VOLVO
Model	XC60 T5 INSCRIPTION PRO AWD
Colour	Grey
Year of manufacture	2018
Top speed	137 mph
0 - 60 mph	6.4 seconds
Gearbox	8 speed automatic

Engine & fuel consumption

Power	251 BHP
Max. torque	350 Nm at 1.500 rpm
Engine capacity	1.969 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	45.6 mpg
Consumption combined	38.7 mpg
CO2 emission	169 g/km
CO2 label	H





Internet history

Entry 3

Date	2021-08-11
Pictures	7
Listing price	<a href="#">View report</a>



source: heycar.co.uk

Entry 2

Date	2021-08-11
Pictures	1
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

Entry 1

Date	2021-08-10
Pictures	1
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2024-07-05
MOT pass rate	75 %
MOT passed	3
Failed MOT tests	1
Total advice items	15
Total items failed	0

MOT #4 2023-07-04 13:51

MOT test number 419218467329

Result ✔ Passed

Next expiry date 2024-07-05

- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Under tray fitted
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))



<b>MOT #3</b>	2023-07-04 09:16
<b>MOT test number</b>	832697919413
<b>Result</b>	✗ Failed
<b>DANGEROUS</b>	Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
<b>Advice</b>	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>MAJOR</b>	Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))
<b>Advice</b>	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Advice</b>	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
<b>DANGEROUS</b>	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
<b>Advice</b>	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>MAJOR</b>	Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
<b>Advice</b>	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
<b>Advice</b>	Under tray fitted

<b>MOT #2</b>	2022-06-18 10:20
<b>MOT test number</b>	970170039169
<b>Result</b>	✓ Passed
<b>Advice</b>	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

<b>MOT #1</b>	2021-06-23 11:35
<b>MOT test number</b>	645161661576
<b>Result</b>	✓ Passed



Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 August 2024

✓  
**MOT**

**Expires:**  
5 July 2024

**Tax status** Valid until 1 August

**Days left** 94

**MOT expiry date** 5 July 2024

**Full MOT history** [See MOT history](#)

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	I
<b>First licence fee (12 months)</b>	£ 645,00,-
<b>Standard rate (12 months)</b>	£ 180,00,-
<b>Standard rate (6 months)</b>	£ 99,00,-
<b>Premium rate (12 months)</b>	£ 570,00,-
<b>Premium rate (6 months)</b>	£ 313,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



**Vehicle valuation**

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

<b>Trade retail value</b>	£ 19,999
<b>Auction value</b>	£ 19,999
<b>Average private trade value</b>	£ 19,999

**More info** >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	<b>YY18XBF</b>
Plate since	2018-03-29
Current registration	<b>YY18XBF</b>
Plate since	2018-03-29

More info >



**Finance check**

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled. If not, and you buy this VOLVO then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this VOLVO is financed.

<b>Finance company</b>	REDACTED
<b>Date of agreement</b>	REDACTED
<b>Agreement type</b>	REDACTED
<b>Agreement term</b>	REDACTED
<b>Agreement number</b>	REDACTED
<b>Contact info</b>	REDACTED

**More info** >



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2018-07-06
Last registration	2023-07-04
Complete history	<a href="#">See info</a>



Registration #1	2018-07-06	7 mi
Registration #2	2021-06-23	18.582 mi
Registration #3	2019-06-23	18.582 mi
Registration #4	2019-06-23	18.582 mi
Registration #5	2019-06-23	18.582 mi
Registration #6	2019-06-23	18.582 mi
Registration #7	2019-06-23	18.582 mi
Registration #8	2019-06-23	18.582 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	98%
Children	87%
Pedestrian	76%
Safety systems	95%
Overall rating	90%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1999 mm
Height	1658 mm
Length	4688 mm
Wheel base	2865 mm
Kerb weight	1773 kg
Max. allowed weight	2430 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	2504136