



PEUGEOT




report date: 2024-03-29

General information

Make	PEUGEOT
Model	307 S
Colour	Silver
Year of manufacture	2007
Top speed	118 mph
0 - 60 mph	10.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	107 BHP
Max. torque	147 Nm at 4.000 rpm
Engine capacity	1.587 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.7 mpg
Consumption extra urban	48.7 mpg
Consumption combined	39.2 mpg
CO2 emission	174 g/km
CO2 label	H







Internet history

Entry 1

Date	2022-01-08
Pictures	19
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2024-10-12
MOT pass rate	79 %
MOT passed	15
Failed MOT tests	4
Total advice items	16
Total items failed	7

MOT #19	2023-09-25 14:49
MOT test number	374570999791
Result	✓ Passed
Next expiry date	2024-10-12
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #18	2022-10-13 15:18
MOT test number	548137404680
Result	✓ Passed
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #17** 2022-09-29 11:35**MOT test number** 279320361429**Result** ✗ Failed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both. (1.1.14 (a) (ii))**Fail** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both. (1.1.14 (a) (ii))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #16** 2021-09-16 11:22**MOT test number** 761806491039**Result** ✓ Passed**MOT #15** 2020-09-18 15:33**MOT test number** 411327250410**Result** ✓ Passed**MOT #14** 2020-09-18 15:33**MOT test number** 228879006169**Result** ✗ Failed**Pass with rectification** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**MOT #13** 2019-09-10 08:45**MOT test number** 990721948993**Result** ✓ Passed**Advice** Nearside Front Tyre slightly damaged/cracking or perishing sidewall slight cracking (5.2.3 (d) (ii))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing sidewall slightly cracking (5.2.3 (d) (ii))

**MOT #12** 2019-09-10 08:45**MOT test number** 325336770361**Result** ✗ Failed**Advice** Nearside Front Tyre slightly damaged/cracking or perishing sidewall slight cracking (5.2.3 (d) (ii))**Pass with rectification** Offside Rear Outer Position lamp not working (4.2.1 (a) (ii))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing sidewall slightly cracking (5.2.3 (d) (ii))**MOT #11** 2018-09-06 10:12**MOT test number** 271816970313**Result** ✓ Passed**MOT #10** 2017-08-21 12:20**MOT test number** 696451561586**Result** ✓ Passed**MOT #9** 2016-09-12 11:25**MOT test number** 967701226079**Result** ✓ Passed**MOT #8** 2015-09-15 14:06**MOT test number** 636445567705**Result** ✓ Passed**MOT #7** 2014-08-28 16:28**MOT test number** 885690744216**Result** ✓ Passed

**MOT #6** 2013-12-05 14:53**MOT test number** 126209133328**Result** ✓ Passed**Notice** Rear discs slightly corroded on the outer edges**Notice** Offside rear tyre 2.5mm**MOT #5** 2012-12-17 11:52**MOT test number** 227462152342**Result** ✓ Passed**Notice** Nearside rear tyre 2mm**Notice** Offside front tyre 2mm**MOT #4** 2011-11-26 09:23**MOT test number** 696600731349**Result** ✓ Passed**MOT #3** 2010-12-15 15:23**MOT test number** 764329640302**Result** ✗ Failed**Pass with rectification** Nearside Upper Rear position lamp(s) not working (1.1.A.3b)**Pass with rectification** Offside Headlamp aim too low (1.8)**Pass with rectification** Offside Upper Rear position lamp(s) not working (1.1.A.3b)**MOT #2** 2010-12-15 15:23**MOT test number** 714209740330**Result** ✓ Passed



MOT #1	2010-09-04 12:05
MOT test number	411647640298
Result	✓ Passed



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2007-09-18
Last registration	2023-09-25
Complete history	<a href="#">See info</a>



Registration #1	2007-09-18	11 mi
Registration #2	2010-09-04	24.770 mi
Registration #3	2010-12-15	26.393 mi
Registration #4	2011-11-26	33.843 mi
Registration #5	2012-12-17	42.015 mi
Registration #6	2013-12-05	49.561 mi
Registration #7	2014-08-28	53.933 mi
Registration #8	2015-09-15	56.554 mi
Registration #9	2016-09-12	59.292 mi
Registration #10	2017-08-21	61.455 mi
Registration #11	2018-08-21	61.455 mi
Registration #12	2019-08-21	61.455 mi
Registration #13	2020-08-21	61.455 mi
Registration #14	2021-08-21	61.455 mi
Registration #15	2022-08-21	61.455 mi
Registration #16	2023-08-21	61.455 mi
Registration #17	2024-08-21	61.455 mi
Registration #18	2025-08-21	61.455 mi
Registration #19	2026-08-21	61.455 mi
Registration #20	2027-08-21	61.455 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1746 mm
Height	1512 mm
Length	4202 mm
Wheel base	2608 mm
Kerb weight	1275 kg
Max. allowed weight	1700 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	FX6N3093351