



RENAULT

MT55NWF

report date: 2024-03-29

General information

Make	RENAULT
Model	MEGANE OASIS 16V EU4
Colour	Black
Year of manufacture	-
Top speed	114 mph
0 - 60 mph	12.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	127 Nm at 3.750 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	30.7 mpg
Consumption extra urban	54.3 mpg
Consumption combined	42.8 mpg






Internet history

Entry 1

Date	2021-01-21
Pictures	12
Listing price	View report



source: yesauto.com

**MOT history****MOT #20** 2018-11-05 14:19**MOT test number** 733125581375**Result** ✓ Passed**Next expiry date** 2019-11-16

- Advice** Rear Brake disc worn, but not excessively both sides (1.1.14 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))
- Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Nearside front tyre cracking between treads
- Advice** Nearside Rear Position lamp slightly affected by the operation of another lamp bad earth (4.2.3 (c))

MOT #19 2018-11-05 10:29**MOT test number** 368523628302**Result** ✗ Failed

- Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Advice** Nearside front tyre cracking between treads
- Advice** Rear Brake disc worn, but not excessively both sides (1.1.14 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))
- Advice** Nearside Rear Position lamp slightly affected by the operation of another lamp bad earth (4.2.3 (c))
- Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))

MOT #18 2017-11-06 13:18**MOT test number** 965402398792**Result** ✓ Passed

- Advice** Offside front tyre wearing inner edge

**MOT #17** 2017-11-06 10:05**MOT test number** 222789563761**Result** ✗ Failed**Fail** Nearside Front Suspension arm has excessive play in a ball joint (2.4.G.2)**Advice** Offside front tyre wearing inner edge**MOT #16** 2016-11-17 14:06**MOT test number** 522895711707**Result** ✓ Passed**MOT #15** 2015-11-11 17:36**MOT test number** 725207377800**Result** ✓ Passed**MOT #14** 2015-11-11 09:17**MOT test number** 909856555422**Result** ✗ Failed**Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Nearside Front Front position lamp(s) not working (1.1.A.3b)**Fail** Nearside Front Track rod end ball joint has excessive play (2.2.B.1f)**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #13** 2014-11-04 12:40**MOT test number** 268888604321**Result** ✓ Passed

**MOT #12**

2014-11-03 15:33

MOT test number

955737904306

Result**✗ Failed****Fail** Nearside Front Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)**Fail** Front brake disc in such a condition that it is seriously weakened (3.5.1i)**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Offside Front Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)**Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #11**

2013-12-06 18:12

MOT test number

335690443353

Result**✓ Passed****MOT #10**

2013-12-06 10:54

MOT test number

519760843351

Result**✗ Failed****Pass with rectification** Nearside Rear Front position lamp(s) not working (1.1.A.3b)**Fail** Offside Front Front constant velocity joint is excessively worn (2.5.C.1b)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #9**

2012-04-19 17:50

MOT test number

308610612108

Result**✓ Passed****Advice** Offside Front Track rod end ball joint has slight play (2.2.B.1f)**Advice** Nearside Front Track rod end ball joint has slight play (2.2.B.1f)

**MOT #8** 2012-04-19 17:50**MOT test number** 476240612189**Result** ✗ Failed**Pass with rectification** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Nearside Front Track rod end ball joint has slight play (2.2.B.1f)**Pass with rectification** Nearside Front Front position lamp(s) not working (1.1.A.3b)**Pass with rectification** Rear Exhaust system not adequately supported (7.1.1)**Advice** Offside Front Track rod end ball joint has slight play (2.2.B.1f)**MOT #7** 2011-08-22 17:34**MOT test number** 505584531244**Result** ✓ Passed**MOT #6** 2011-08-22 13:48**MOT test number** 255944131233**Result** ✗ Failed**Fail** Nearside Front Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Front Track rod end ball joint has slight play (2.2.B.1f)**MOT #5** 2010-08-23 17:19**MOT test number** 440635430236**Result** ✓ Passed**Notice** Front brake discs lipped**Advice** Front Brake pad(s) wearing thin (3.5.1g)

**MOT #4**

2010-08-23 13:07

MOT test number

333045030465

Result**✗ Failed**

- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Offside rear brake binding (3.7.B.1)
- Fail** Offside Front constant velocity joint gaiter insecurely mounted to its housing (2.5.C.1a)
- Fail** Nearside rear brake binding (3.7.B.1)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Notice** Front brake discs lipped

MOT #3

2009-08-13 09:13

MOT test number

713205829225

Result**✗ Failed**

- Advice** Nearside Front Track rod end ball joint has slight play (2.2.B.1f)
- Advice** Offside Front Track rod end ball joint has slight play (2.2.B.1f)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Pass with rectification** Offside Front Headlamp not working on dipped beam (1.7.5a)

MOT #2

2009-08-13 09:13

MOT test number

322065629274

Result**✓ Passed**

- Advice** Offside Front Track rod end ball joint has slight play (2.2.B.1f)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Front Track rod end ball joint has slight play (2.2.B.1f)



MOT #1	2008-08-21 12:02
MOT test number	904844538205
Result	✓ Passed



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2024-03-29
Current registration	*****
Plate since	2024-03-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.


Finance company	RENAULT	FINANCE
Date of agreement	2024-03-29	2024-03-29
Agreement type	RENAULT	FINANCE
Agreement term	RENAULT	FINANCE
Agreement number	RENAULT	FINANCE
Contact info	RENAULT	FINANCE

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2005-10-25
Last registration	2018-11-05
Complete history	See info



Registration #1	2005-10-25	26 mi
Registration #2	2008-08-21	18.994 mi
Registration #3	2009-08-13	27.483 mi
Registration #4	2010-08-23	37.270 mi
Registration #5	2010-08-23	37.272 mi
Registration #6	2011-08-22	51.747 mi
Registration #7	2011-08-22	51.747 mi
Registration #8	2012-04-19	59.309 mi
Registration #9	2013-12-06	70.021 mi
Registration #10	2013-12-06	70.028 mi
Registration #11	2014-06-20	70.028 mi
Registration #12	2014-06-20	70.028 mi
Registration #13	2014-06-20	70.028 mi
Registration #14	2014-06-20	70.028 mi
Registration #15	2014-06-20	70.028 mi
Registration #16	2014-06-20	70.028 mi
Registration #17	2014-06-20	70.028 mi
Registration #18	2014-06-20	70.028 mi
Registration #19	2014-06-20	70.028 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2026 mm
Height	1457 mm
Length	4209 mm
Wheel base	2625 mm
Kerb weight	1165 kg
Max. allowed weight	1715 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Engine number	D001663
---------------	---------