





General information

| Make | ΤΟΥΟΤΑ |
|---------------------|----------------|
| Model | RAV-4 D-4D XT3 |
| Colour | Black |
| Year of manufacture | 2005 |
| Top speed | 106 mph |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 114 BHP |
|-------------------------|---------------------|
| Max. torque | 250 Nm at 1.800 rpm |
| Engine capacity | 1.995 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 31.7 mpg |
| Consumption extra urban | 46.3 mpg |
| Consumption combined | 39.8 mpg |
| CO2 emission | 190 g/km |
| CO2 label | J |





Internet history

| Entry 2 | |
|---------------|-------------|
| Date | 2021-09-18 |
| Pictures | 19 |
| Listing price | View report |



source: autotrader.co.uk

| Entry 1 | |
|---------------|-------------|
| Date | 2021-08-25 |
| Pictures | 19 |
| Listing price | View report |
| | |



source: autotrader.co.uk









MOT history

| MOT expiry date | 2024-08-15 |
|--------------------|------------|
| MOT pass rate | 68 % |
| MOT passed | 15 |
| Failed MOT tests | 7 |
| Total advice items | 17 |
| Total items failed | 16 |

| MOT #22 | 2023-08-16 11:06 |
|------------------|------------------|
| MOT test number | 216846593174 |
| Result | ✓ Passed |
| Next expiry date | 2024-08-15 |

| MOT #21 | | 2021-05-26 14:48 |
|----------|--|------------------|
| MOT test | number | 573147622135 |
| Result | | 🗸 Passed |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Central Exhaust has a minor leak of exhaust gases (6.1.2 (a)) | |

| MOT #20 | 2021-05-25 12:52 |
|---|------------------|
| MOT test number | 558946141977 |
| Result | 🗙 Failed |
| Advice Central Exhaust has a minor leak of exhaust gases (6.1.2 (a)) | |
| Fail Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i)) | |
| Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Fail Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g)) | |
| Fail Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i)) | |





| MOT #19 | 2020-05-28 11:16 |
|-----------------|------------------|
| MOT test number | 618154292857 |
| Result | ✓ Passed |
| | |
| MOT #18 | 2020-05-28 11:16 |
| MOT test number | 226743542485 |
| Result | 🗙 Failed |
| | |

Pass with rectificationOffside Stop lamp(s) not working (4.3.1 (a) (ii))

| MOT #17 | 2019-05-31 16: | 14 |
|----------|--|----|
| MOT test | number 2694585405 | 66 |
| Result | ✓ Pass | ed |
| Advice | Power steering component has slight seepage from a component (2.1.5 (a)) | |
| Advice | Brake pipe corroded, covered in grease or other material both front to rear at rear (1.1.11 (c)) | |

| MOT #16 | 2019-05-31 09:45 |
|---|-------------------|
| MOT test number | 554984635885 |
| Result | 🗙 Failed |
| Fail Nearside Front Headlamp aim too high (4.1.2 (a)) | |
| Advice Power steering component has slight seepage from a component (2.1.5 (a)) | |
| Fail Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a)) | |
| Fail Offside Front Headlamp aim too high (4.1.2 (a)) | |
| Advice Brake pipe corroded, covered in grease or other material both front to rear at | rear (1.1.11 (c)) |
| Fail Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (| z)) |





| MOT #15 | 2018-06-01 13:43 |
|---|------------------|
| MOT test number | 394574346872 |
| Result | ✓ Passed |
| Advice Offside Front Coil spring corroded (5.3.1 (b) (i)) | |
| MOT #14 | 2018-05-31 10:08 |
| MOT test number | 558381181233 |
| Result | 🗙 Failed |
| Advice Offside Rear Coil spring corroded (5.3.1 (b) (i)) | |
| Fail Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i)) | |
| Advice Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i)) | |
| Advice Offside Front Coil spring corroded (5.3.1 (b) (i)) | |

| MOT #13 | 2017-05-31 10:00 |
|-----------------|------------------|
| MOT test number | 952321578132 |
| Result | ✓ Passed |
| | |
| MOT #12 | 2016-06-03 07:55 |
| MOT test number | 134367838317 |
| Result | ✓ Passed |
| | |
| MOT #11 | 2016-06-03 07:55 |
| MOT test number | 582226833135 |
| Result | 🗙 Failed |

Result

Nearside Rear Registration plate lamp not working (1.1.C.1d) **Pass with rectification**



| MOT #10 | | 2015-06-10 16:57 |
|----------|---|------------------|
| MOT test | number | 518611865153 |
| Result | | ✓ Passed |
| Advice | Front Brake pad(s) wearing thin (3.5.1g) | |
| Notice | Front wipers slight smearing not affecting drivers view | |
| | | |

| МОТ #9 | 2014-04-11 12:06 |
|-----------------|------------------|
| MOT test number | 905741404109 |
| Result | ✓ Passed |

| MOT #8 | 8 | 2014-04-10 11:26 |
|------------------------|--|------------------|
| MOT te | est number | 646150504124 |
| Result | | 🗙 Failed |
| Fail | Offside Windscreen wiper does not clear the windscreen effectively (8.2.2) | |
| Fail | Offside Registration plate lamp not working (1.1.C.1d) | |
| Fail | Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2) | |
| Fail | Nearside Registration plate lamp not working (1.1.C.1d) | |
| Fail ingress | Nearside Front constant velocity joint gaiter damaged to the extent that it no longe of dirt etc (2.5.C.1a) | er prevents the |

| MOT #7 | | 2013-04-18 10:34 |
|----------|--|------------------|
| MOT test | number | 675078903100 |
| Result | | ✓ Passed |
| Advice | Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) | |
| Advice | Front Brake pad(s) wearing thin (3.5.1g) | |

GP05HZF

report date: 2024-03-29





| MOT #6 | 2012-04-11 16:21 |
|---------------------------------|--|
| MOT test number | 249102302191 |
| Result | ✓ Passed |
| Notice Child seat fitted | not allowing full inspection of adult belt |
| MOT #5 | 2011-04-19 09:55 |
| MOT test number | 255989601100 |
| Result | ✓ Passed |
| | |
| MOT #4 | 2010-04-19 16:31 |
| MOT test number | 251539700484 |
| Result | ✓ Passed |
| | |
| MOT #3 | 2010-04-19 16:31 |
| MOT test number | 331499900176 |
| Result | × Failed |
| Pass with rectification | Windscreen wiper does not clear the windscreen effectively (8.2.2) |
| MOT #2 | 2009-07-29 16:42 |
| MOT test number | 193350919273 |
| Result | ✓ Passed |
| | |
| MOT #1 | 2008-06-26 14:04 |
| MOT test number | 521168878178 |

Result

🗸 Passed



Tax & MOT check

| X Untaxed Tax expired: 10 April 2024 | ✓ MOT Expires: 15 August 2024 |
|---|--|
| Tax status | Expired at 10 April 2024 |
| Days left | 18 days too late |
| MOT expiry date | 15 August 2024 |
| Full MOT history | See MOT history |
| Tax calculation | |

| Vehicle class | 49 |
|---|------------|
| Band | J |
| Single payment (12 months) | £ 365,00,- |
| Single six month payment | £ 200,75,- |
| Total payable by 12 monthly instalments | £ 383,25,- |





Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|------|
| Date | |
| Category | Lamp |
| Туре | K K |
| Damage 2 | AMPL |
| | |
| Date | NE |
| Category | AMP |
| Туре | |

Extra TOYOTA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4.00.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 10.200 |

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| ******* | |
|--|-------------|
| *********** | |
| ******* | |
| ******* | |
| ************* | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this TOYOTA had different number plat | es. |
| Number of plates | , |
| Current registration | |
| Plate since | |
| Correct registration | |
| Plate since | |
| | More info > |





Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |


More info \rightarrow





Mileage check

| In miles |
|------------|
| 24 |
| 2005-06-28 |
| 2023-08-16 |
| See info |
| |



| Registration #1 | 2005-06-28 | 25 mi |
|--|------------|--|
| Registration #2 | 2008-06-26 | 13.943 mi |
| Registration #3 | 2009-07-29 | 50.089 mi |
| Registration #4 | 2010-04-19 | 59.467 mi |
| Registration #5 | 2011-04-19 | 67.876 mi |
| Registration #6 | 2012-04-11 | 75.888 mi |
| Registration #7 | 2013-04-18 | 83.369 mi |
| Registration #8 | 2014-04-10 | 91.625 mi |
| Registration #9 | 2014-04-11 | 91.625 mi |
| Registration #10 | 2015-06-10 | 100.064 mi |
| Registration #11 | 2016-06-03 | 104.128 mi |
| Registration #12 | 2016-06-03 | 104.128 mi |
| Registration #13 | | 11.777 est |
| | | |
| Registration #14 | | 11.777 est |
| Registration #14 Registration #15 | | 11.777 es |
| - | | 11.777 est 11.777 est 11.777 est |
| Registration #15 | | 11,227 es 11,227 es 11,227 es 11,227 es |
| Registration #15 Registration #16 | | 11.777 46 11.777 46 11.777 46 11.777 46 11.777 46 |
| Registration #15 Registration #16 Registration #17 | | 11,227 46 11,227 46 11,227 46 11,227 46 11,227 46 11,227 46 |
| Registration #15 Registration #16 Registration #17 Registration #18 | | 11.777 est 11.777 est 11.777 est 11.777 est 11.777 est 11.777 est |
| Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 | | 11,227 46 11,227 46 11,227 46 11,227 46 11,227 46 11,227 46 11,227 46 |
| Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 | | 11.227 46 11.227 46 11.227 46 11.227 46 11.227 46 11.227 46 11.227 46 11.227 46 |
| Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21 | | 11,227 46 11,227 46 11,227 46 11,227 46 11,227 46 11,227 46 11,227 46 11,227 46 |
| Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21 Registration #22 | | 0.227 46 0.227 46 0.227 46 0.227 46 0.227 46 0.227 46 0.227 46 0.227 46 0.227 46 0.227 46 |







Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Safety ratings

NCAP rating

Video

**** see crash video



| Dimensions & weight | |
|-----------------------------------|------------------|
| Width | 1785 mm |
| Height | 1710 mm |
| Length | 4260 mm |
| Wheel base | 2490 mm |
| Kerb weight | 1490 kg |
| Max. allowed weight | 1930 kg |
| Additional information | |
| Fuel tank capacity | 57 |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 5 page 14/14 |

| Number of axles | 2 |
|-----------------|------------|
| Engine number | 1CD0491619 |